

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/EG122006604/ACY3Q2**Date:** 14/06/2023REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

**Claimant Vehicle No :** SJA8583H **Insured Vehicle No :** GBG9382C

Date of Loss: 07/07/2022 Nature of Claim: TP Claim No: CDMCG22001352

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJA8583H**

Make & Model: ADIVA AD1 200, 190cc 3W Engine No: 2GRJ097014

Reg. Date: 15/07/2009 (Man. Year: 2009) Chassis No: JTJBK11A202412681

Colour: Grey Odometer: 511523 km

Engine Capacity: 3456 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/60 R18 Rear Tyre Size: 235/60 R18

Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	11,723.13	6,471.72	5,251.41	44.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,460.00	1,060.00	1,400.00	56.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>14,183.13</b>	<b>7,531.72</b>	<b>6,651.41</b>	<b>46.90</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>6,000.00</b>		
<b>Nett Amount (S\$)</b>	<b>14,183.13</b>	<b>6,000.00</b>	<b>8,183.13</b>	<b>57.70</b>

INSPECTION

Date of Assignment: 12/07/2022

Date Inspected: 18/07/2022 Inspected At: Unimotor Company - Kaki Bukit (HQ)  
1 KAKI BUKIT AVE 6, #01-94 (AUTOBAY @ KAKI BUKIT)  
Singapore 417883

Estimated Period of Repair: 5.0 days

**Adjuster:** ADRIAN LING**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 14 Jun 2023)	
Parts:	N/A	ADIVA AD1 200 190cc 3W (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJA8583H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT R/H HEADLAMP ASSY	Cracked	2,990.60 FL	*2,465.00 FL
2	1		*FRONT R/H HEADLAMP LOWER BRACKET	Cracked	143.10 FL	*143.10 FL
3	1		*FRONT WIPER WASH TANK	Deformed	251.90 FL	*251.90 FL
4	1		*FRONT RADIATOR GRILLE ASSY	Cracked	994.60 FL	*994.60 FL
5	1		*FRONT RADIATOR GRILLE EMBLEM	Necessary	90.20 FL	*90.20 FL
6	1		*FRONT SUPPORT PANEL	Repair	1,920.20 FL	*- FL
7	1		*FRONT SUPPORT TOP COVER GARNISH	Not Necessary	488.60 FL	*- FL
8	1		*R/H FRONT FENDER ASSY	Distorted	1,655.20 FL	*1,124.00 FL
9	1		*R/H FRONT FENDER INNER SHIELD	Deformed	517.00 FL	*426.00 FL
10	8		*R/H FRONT FENDER INNER SHIELD CLIPS	Necessary	56.00 FL	*30.00 FL
11	1		*FRONT BUMPER FACE	Distorted	1,065.70 FL	*895.00 FL
12	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	861.60 FL	*- FL
13	1		*FRONT BUMPER REINFORCEMENT BRACKET	Not Necessary	210.50 FL	*- FL
14	1		*FRONT R/H BUMPER SIDE RETAINER HOLDER	Damaged	146.50 FL	*146.50 FL
15	1		*FRONT BUMPER BLACK SPONGE	Cracked	271.70 FL	*168.00 FL
16	1		*R/H FRONT BUMPER FOG LAMP	Cracked	329.10 FL	*329.10 FL
17	1		*R/H FRONT BUMPER FOG LAMP COVER	Cracked	77.40 FL	*77.40 FL
18	1		*R/H FRONT BUMPER SPARY NOZZBLE	Not Necessary	801.70 FL	*- FL
19	1		*R/H FRONT BUMPER SPARY NOZZBLE COVER	Not Necessary	69.70 FL	*- FL
20	10		*FRONT BUMPER CLIPS	Necessary	84.40 FL	*50.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	13,025.70	7,190.80
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,302.57	719.08
Total Parts (\$\$)	11,723.13	6,471.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISM/REWIRE FRONT DAMAGED PORTION AND REFOCUS HEADLAMP	New	100.00	30.00
2	TO PANEL BEAT DAMAGED PORTION AND RENEW PARTS	New	1,000.00	500.00
3	TO PUTTY AND RESPRAY DAMAGED PORTION	New	1,000.00	400.00
4	TO SPRAY UNDERCOATING IN REPAIR	New	120.00	30.00
5	TO RESET ECU AFTER REPAIR	New	120.00	100.00
6	TO COMPLETE WHEEL ALIGNMENT	New	120.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>2,460.00</b>	<b>1,060.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >