

## Vehicle Damage Assessment Report for [SJA8583H]

Estimate Created: 13/06/2023 14:41 by Insurlogic 4 (Insurlogic\_Pte\_Ltd)

Owned: 13/06/2023 15:33 by Insurlogic 4 (Insurlogic\_Pte\_Ltd)

### General Information

|                   |                              |                  |
|-------------------|------------------------------|------------------|
| Insurance Company | ERGO                         | Claim Number     |
| Claim Type        | TP                           |                  |
| Workshop          | LKK_Auto_Consultants_Pte_Ltd | Reference Number |

### Vehicle Information

|                      |          |                    |    |
|----------------------|----------|--------------------|----|
| Brand                | Lexus    | Model              | RX |
| Engine Type          |          |                    |    |
| License Plate Number | SJA8583H | VIN (or Chassis #) |    |

### Vehicle Condition

|                 |                 |         |
|-----------------|-----------------|---------|
| Damaged Diagram | Odometer        | 0.00 Km |
|                 | Tyres Condition |         |
|                 | Front Left      | mm      |
|                 | Front Right     | mm      |
|                 | Rear Left       | mm      |
|                 | Rear Right      | mm      |

### Comments

|                                                                                                                          |                                 |
|--------------------------------------------------------------------------------------------------------------------------|---------------------------------|
| - FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK:<br>CONCLUDED THE COST OF REPAIR AT \$6,000.00 WITH 5 WORKING<br>DAYS | Insurlogic 4 (13/06/2023 14:51) |
|--------------------------------------------------------------------------------------------------------------------------|---------------------------------|

**Parts**

| Description                        | Number/Type | Qty | Cost    | Markup/Disc.% | Sum      |
|------------------------------------|-------------|-----|---------|---------------|----------|
| RH Headlamp                        |             | 1   | 2465.00 | -10.00 %      | 2,218.50 |
| RH headlamp lower bracket          |             | 1   | 143.10  | -10.00 %      | 128.79   |
| Front wiper washer tank            |             | 1   | 251.90  | -10.00 %      | 226.71   |
| Radiator grille                    |             | 1   | 994.60  | -10.00 %      | 895.14   |
| Radiator grille emblem             |             | 1   | 90.20   | -10.00 %      | 81.18    |
| RH front fender                    |             | 1   | 1124.00 | -10.00 %      | 1,011.60 |
| RH front fender inner shield       |             | 1   | 426.00  | -10.00 %      | 383.40   |
| RH front fender inner shield clips |             | 1   | 30.00   | -10.00 %      | 27.00    |
| Front bumper                       |             | 1   | 895.00  | -10.00 %      | 805.50   |
| Front bumper side holder RH        |             | 1   | 146.50  | -10.00 %      | 131.85   |
| Front bumper black sponge          |             | 1   | 168.00  | -10.00 %      | 151.20   |
| RH front bumper fog lamp           |             | 1   | 329.10  | -10.00 %      | 296.19   |
| RH front bumper fog lamp cover     |             | 1   | 77.40   | -10.00 %      | 69.66    |
| Front bumper clips                 |             | 1   | 50.00   | -10.00 %      | 45.00    |

Parts Subtotal 6,471.72

**Labor****Replace/RnR**

| Description                                                      | Type | Cost   | Markup/Disc % | Price  |
|------------------------------------------------------------------|------|--------|---------------|--------|
| To dismantle / rewire front damage portion and refocus headlamp. | RnR  | 30.00  | 0.00 %        | 30.00  |
| Panel beating                                                    | RnR  | 500.00 | 0.00 %        | 500.00 |
| To spray under coating in repair.                                | RnR  | 30.00  | 0.00 %        | 30.00  |
| To reset ECU after repair.                                       | RnR  | 100.00 | 0.00 %        | 100.00 |

**Repair**

| Description         | Severity | Cost | Markup/Disc % | Price |
|---------------------|----------|------|---------------|-------|
| Front support panel | Medium   | 0.00 | 0.00 %        | 0.00  |

**Paint**

| Description    | Paint Type | Cost   | Markup/Disc % | Price  |
|----------------|------------|--------|---------------|--------|
| Spray painting | Full spray | 400.00 | 0.00 %        | 400.00 |

|            |               |                        |          |
|------------|---------------|------------------------|----------|
| Labor Rate | S\$ 50 / Hour | General Labor Subtotal | 660.00   |
|            |               | Paint Labor Subtotal   | 400.00   |
|            |               | Labor Subtotal         | 1,060.00 |

Summary

|                |            |
|----------------|------------|
| Repair Cost    | 7,531.72   |
| Discount(20 %) | (1,506.34) |
|                | 6,025.38   |
| Excess         | (0.00)     |
| GST(0.00 %)    | 0.00       |
| Grand Subtotal | 6,025.38   |