

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG22006606/APA3Q2**Date:** 18/01/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7220011477
<b>Claimant Vehicle No :</b>	YQ3787H	<b>Insured Vehicle No :</b>	GBD2866K
Date of Loss:	11/07/2022	Nature of Claim:	TP
		Claim No:	0684971997SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>YQ3787H</b>		
Make & Model:	HINO XZU710R, 4.0 D 14FT WIDE CAB 5T (M)	Engine No:	N04CWN14128
Reg. Date:	01/06/2021 (Man. Year: 2021)	Chassis No:	JHHUCV3F20K038546
Colour:	White	Odometer:	17764 km
Engine Capacity:	4009 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/85 R16	Rear Tyre Size:	195/85 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,977.16	2,484.20	3,492.96	58.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,860.00	580.00	1,280.00	68.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>7,837.16</b>	<b>3,064.20</b>	<b>4,772.96</b>	<b>60.90</b>
<b>+ GST 7.00/7.00% (S\$)</b>	548.60	214.49	334.11	60.90
<b>Nett Amount (S\$)</b>	<b>8,385.76</b>	<b>3,278.69</b>	<b>5,107.07</b>	<b>60.90</b>
<b>+ Loss of Use (4.0 x S\$120.00/day) (S\$)</b>		480.00		
<b>+ Doc/Search Fee (S\$)</b>		38.45		
<b>Nett Liability (S\$)</b>		<b>3,797.14</b>		

INSPECTION

Date of Assignment:	13/07/2022	
Date Inspected:	13/07/2022 Inspected At:	Ryder Auto Pte Ltd (HQ) 2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit Singapore 417921
Estimated Period of Repair:	3.0 days	

**Adjuster:** ADRIAN LING**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	2,280.20 FL	*967.00 FL
2	1		*FRONT BUMPER O/S BRACKET	Bent	450.00 FL	*285.00 FL
3	1		*FRONT GRILLE	Not Necessary	1,098.20 FL	*- FL
4	8		*FRONT GRILLE CLIPS	Not Necessary	80.00 FS	*- FS
5	1		*FRONT O/S HEAD LAMP (WITH MOTOR)	Cut	1,780.20 FL	*1,086.00 FL
6	1		*FRONT O/S HEAD LAMP LOWER SEAL	Not Necessary	168.20 FL	*- FL
7	1		*FRONT HINO EMBLEM	Not Necessary	102.21 FL	*- FL
8	1		*FRONT O/S FOG LAMP (LED)	Cracked	800.00 FS	*280.00 FS
9	1		*FRONT O/S FOG LAMP BRACKET	Cracked	100.00 FS	*100.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					6,859.01	2,718.00
- List Item Discount on L Items 15.00/10.00% (\$\$)					881.85	233.80
Total Parts (\$\$)					5,977.16	2,484.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPAIR FRONT PORTION	New	800.00	300.00
2	TO SPRAY PAINTING FRONT PORTION	New	600.00	250.00
3	TO CHECK FOR FAULT CODE AND RESTTING	New	280.00	0.00
4	TO CHECK WIRING	New	100.00	30.00
5	TO RE-SEAL ANTI RUST	New	80.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>1,860.00</b>	<b>580.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >