

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/ASM 22006610/4943

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

GBB4966G

at Workshop m/s

1 mprum

of

Insured:

SLV 5980E

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

\$14k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

C 266W

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GBB4966G

Yr Regn:

07/05/09

Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Dyna

c.c

2982

Colour

S.1m

A/C:

Insured / Std / NI / NA

Sp. Reading

425794

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTFAT354 LOK 200542

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195 R15

R:

155 R12 habilead

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

maxmike

Front

Rear

R/Bal.

6

mm

R/Bal.

6/6

mm

L/Bal.

6

mm

L/Bal.

6/6

mm

D.O.A.

10/07/22

D.O.I.

13/7/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Lf.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

20/8/22

Account 30-04-2024 LTA \$4809

18/7/22 1/5 \$4000 informed shown (Red. \$7421.79, 65%)

Date/Time, File Pass to?

☐

: Preli. Report

1) 20/7/22

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

) S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ 4000)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

IMPERIUM AUTOMOTIVE

25 Kaki Bukit Road 4 #01-47 Synergy@KB, Singapore 417800

HP : 9748 9940 Shawn Tan

Email: shawn7530@hotmail.com

13 Jul 2022

Vehicle No.: GBB 4966 C

Model: TOYOTA DYNA

Not Authorized

her

13/7/22

*2/s #4000/
Hdngs.*

QTY	DESCRIPTION	AMT S\$
	<u>List Items</u>	
1	Front headlamp -LH <i>Cne</i>	\$ 1,080.50
1	Front headlamp lower seal rubber <i>Torn</i>	\$ 48.50
1	Front corner panel - LH <i>11</i>	\$ 276.50 X
1	Front bumper <i>Worped</i>	\$ 682.80
1	Front bumper reinforcement <i>11</i>	\$ 221.30 X
1	Front mudguard -LH <i>Worped</i>	\$ 189.65
1	Front wheel hub <i>11</i>	\$ 280.95 X
1	Front wheel bearing <i>11</i>	\$ 194.95 X
1	Front shock absorber <i>11</i>	\$ 142.80 X
1	Front knuckle arm <i>11</i>	\$ 522.85 X
1	Front lower arm <i>11</i>	\$ 424.60 X
1	Front cabin lock handle <i>11</i>	\$ 148.60 X
1	Front door -LH <i>Bobson</i>	\$ 1,568.60
1	Front door checker <i>11</i>	\$ 131.75 X
2	Front door hinges <i>11</i>	\$ 157.00 X
1	Front door lock <i>11</i>	\$ 375.85 X
1	Front door lettering <i>her</i>	\$ 45.00
1	Front door regulator <i>11</i>	\$ 295.65 X
1	Front door inner trim board <i>Torn</i>	\$ 509.35
1	Front door rubber <i>11</i>	\$ 190.05 X
1	Front door corner rubber <i>11</i>	\$ 105.25 X
1	Wheel arch panel -LH <i>Burf</i>	\$ 569.20
1	Wheel arch panel garnish <i>11</i>	\$ 122.80 X
1	Wheel arch panel inner seal <i>Torn</i>	\$ 105.95
1	Step panel garnish -LH <i>Cut</i>	\$ 325.50
1	Side gate front stopper bracket <i>11</i>	\$ 145.00 X
1	Side gate front stopper rubber <i>11</i>	\$ 48.10 X
		\$ 8,909.05
	Less 25%	\$ 2,227.26
		\$ 6,681.79

Special Nett Items

1	Front tyre	8u	\$	350.00	X
1	Front wheel rim	8u	\$	350.00	X
			\$	700.00	

S/N.	Labour Charges				
1	To check wiring and reset headlamps focusing.		\$	80.00	20
2	To remove and refit front undercarriage.		\$	11 300.00	X
3	To conduct wheel alignment.		\$	180.00	60
4	To remove, refit door fittings and replace damaged parts, transfer all fittings to new door.		\$	180.00	60
5	To apply undercoating.		\$	200.00	40
6	Panel beating.		\$	1,600.00	700
7	To re-spray painting on the affected areas.		\$	1,500.00	650
			\$	4,040.00	

Grand Total : \$ 11,421.79

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1-4666.4
252
3498.80
1530
5029.80
202
4023