

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | | |
|---|---|---|----------------|-------|-----------------------|--|
| | AXA INSURANCE | PTE LTD | | Ref: | CS/ASM22006610/Uqy3e2 | |
| | 8 SHENTON WAY SINGAPORE 0688 | #24-01 AXA TOWER 11 | | Date: | 27/07/2022 | |
| | ATTN: LOW GARN | ET | | Code: | ASM | |
| 1. | Policy Particulars :- THIRD PARTY CLAIM | | | | | |
| | Insured Veh. | SLV 5980E | Veh. Inspected | d | GBB 4966C | |
| | Policy No. | | Coverage (\$) | | 0.00 | |
| | Claim No. | S2M046GI | Excess (\$) | | 0.00 | |
| | Assign From | LOW GARNET | Assign Date | | 13/07/2022 | |
| 2. | 2. Vehicle Particulars & Condition | | | | | |
| | Make & Model | TOYOTA DYNA (M) | c.c | | 2982 | |
| | Engine No. | HIDDEN | Year of Reg. | | 2009 | |
| | Chassis No. | JTFAT35Y50K200542 | Colour | | SILVER | |
| | Odometer | 425194 KM | Steering | | IN ORDER | |
| | Brakes | IN ORDER | Modification | | NIL | |
| | General | GOOD | | | | |
| 3. Conditions of Tyres | | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | 195 R15 | MAXMILER | | 6 mm | |
| | L/H Front Tyre | 195 R15 | MAXMILER | | 6 mm | |
| | R/H Rear Tyre | 155 R12 (D) | HABILEAD | | 6/6 mm | |
| | L/H Rear Tyre | 155 R12 (D) | HABILEAD | | 6/6 mm | |
| 4. | Description of Damages | | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. | | | | | |
| | DAMAGES SEE DETAILS. | | | | | |
| 5. | General Information | | | | | |
| | Accident Date | 10/07/2022 | Inspection Da | te | 13/07/2022 | |
| | Survey held at | IMPERIUM AUTOMOTIVE | • | | | |
| | | 25 KAKI BUKIT ROAD 4 #01-49 SYNERGY @ KB SINGAPORE 417800 | | | | |
| 5a. | Remarks | | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | |
| 5b. | Estimate Days of Repair | | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days | | | | | |
| | | | | | | |