

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22006612/ACY3E2**Date:** 11/10/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00246252101
Claimant Vehicle No :	SKU9962Z	Insured Vehicle No :	SMA8486U
Date of Loss:	08/07/2022	Nature of Claim:	TP
		Claim No:	SNM22D204804/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKU9962Z	Engine No:	A14NET143570451
Make & Model:	CHEVROLET CRUZE, 1.4 1.4T (A)	Chassis No:	KL1JA6989EK626402
Reg. Date:	26/08/2015 (Man. Year: 2015)	Odometer:	208811 km
Colour:	Grey		
Engine Capacity:	1362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,877.30	11,119.70	13,757.60	55.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,710.00	2,630.00	4,080.00	60.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	31,587.30	13,749.70	17,837.60	56.47
Approved Total (Overridden) (\$\$)		11,000.00		
Nett Amount (\$\$)	31,587.30	11,000.00	20,587.30	65.18

INSPECTION

Date of Assignment:	23/07/2022	
Date Inspected:	12/07/2022	Inspected At: HD Perfect Autowork Pte Ltd (HQ) 8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	9.0 days	

Adjuster: ADRIAN LING**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 11 Oct 2022)	
Parts:	N/A	CHEVROLET CRUZE 1.4 1.4T (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKU9962Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Dented	1,531.00 FL	*1,531.00 FL
2	1		*BOOT LID LAMP	N/S Cut	794.00 FL	*397.00 FL
3	1		*BOOT LID OUTER MOULDING	Not Necessary	395.00 FL	*- FL
4	1		*BOOT LID OUTER SWITCH BUTTON	Not Necessary	212.00 FL	*- FL
5	1		*BOOT LID LOGO	Necessary	165.00 FL	*165.00 FL
6	1		*BOOT LID EMBLEM CHEVROLET	Necessary	82.00 FL	*82.00 FL
7	1		*BOOT LID EMBLEM CRUZE	Necessary	80.00 FL	*80.00 FL
8	1		*BOOT LID EMBLEM L	Necessary	55.00 FL	*55.00 FL
9	1		*BOOT LID EMBLEM TURBO	Necessary	91.00 FL	*91.00 FL
10	2		*BOOT LID HINGE	Not Necessary	352.00 FL	*- FL
11	1		*BOOT LID INSULATOR	Not Necessary	225.00 FL	*- FL
12	1		*BOOT LID DETECTOR	Cracked	487.00 FL	*255.00 FL
13	1		*BOOT LID DETECTOR WIREHARNES	Not Necessary	695.00 FL	*- FL
14	1		*BOOT LID LOCK	Damaged	195.00 FL	*195.00 FL
15	1		*BOOT LID CATCH	Not Necessary	42.00 FL	*- FL
16	1		*BOOT LID WEATHERSTRIP	Cut	189.00 FL	*189.00 FL
17	1		*REAR BUMPER	Distorted	1,438.00 FL	*1,438.00 FL
18	1		*REAR BUMPER TOW HOOK COVER	Not Necessary	25.00 FL	*- FL
19	2		*REAR BUMPER SIDE RETAINER	Necessary	232.00 FL	*232.00 FL
20	1		*REAR BUMPER REINFORCEMENT	Distorted	787.00 FL	*787.00 FL
21	1		*REAR BUMPER CENTER BEAM	Cracked	194.00 FL	*194.00 FL
22	2		*TAIL LAMP	Cracked	1,412.00 FL	*1,412.00 FL
23	1		*TAIL LAMP LOWER BRACKET	N/S Cracked	150.00 FL	*75.00 FL
24	1		*TAIL LAMP PANEL LH	Dented	398.00 FL	*398.00 FL
25	4		*TAIL LAMP BOLT COVER	Not Necessary	48.00 FL	*- FL
26	1		*REAR FENDER	N/S Buckled	4,392.00 FL	*1,899.00 FL
27	1		*REAR FENDER INNER TRIM	N/S Torn	996.00 FL	*498.00 FL
28	2		*REAR FENDER INNER COWLING	Not Necessary	234.00 FL	*- FL
29	1		*REAR FENDER AIR VENT LH	Not Necessary	74.00 FL	*- FL
30	1		*REAR WINDSCREEN MOULDING	Necessary	162.00 FL	*162.00 FL
31	1		*REAR END PANEL	Dented	866.00 FL	*866.00 FL
32	1		*REAR END PANEL TOP GARNISH	Deformed	139.00 FL	*139.00 FL
33	1		*REAR FLOOR PANEL	Repair	1,107.00 FL	*- FL
34	1		*REAR FLOOR PANEL TOP BOARD	Deformed	313.00 FL	*313.00 FL
35	1		*REAR SPARE TYRE BOLT	Not Necessary	86.00 FL	*- FL
36	1		*REAR TOOLS TRAY SPONGE	Not Necessary	226.00 FL	*- FL
37	1		*REVERSE SENSOR (4PCS)	Damaged (2Pcs Only)	860.00 FL	*430.00 FL
38	4		*REVERSE SENSOR HOLDER	Necessary	216.00 FL	*100.00 FL
39	1		*REVERSE SENSOR WIREHARNES	Not Necessary	363.00 FL	*- FL
40	1		*REAR CHASSIS MEMBER LH	Not Necessary	754.00 FL	*- FL
41	1		*CENTER EXHAUST PIPE	Not Necessary	1,062.00 FL	*- FL
42	4		*CENTER EXHAUST MOUNTING	Not Necessary	976.00 FL	*- FL
43	1		*SET CENTER EXHAUST GASKET	Not Necessary	269.00 FL	*- FL
44	1		*CENTER EXHAUST INSULATOR	Not Necessary	246.00 FL	*- FL
45	1		*REAR EXHAUST PIPE	Repair	1,545.00 FL	*- FL

Report was unsubmitted during this print-out.

10/11/22, 11:56 AM
Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	1		*SET REAR EXHAUST MOUNTING	Not Necessary	269.00 FL	*- FL
47	1		*REAR EXHAUST INSULATOR	Not Necessary	224.00 FL	*- FL
48	1		*SET REAR EXHAUST GASKET	Necessary	80.00 FL	*50.00 FL
49	1		*REVERSE CAMERA	Not Necessary	564.00 FL	*- FL
50	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
51	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
52	1		*SET TAIL LAMP CLIPS	Necessary	30.00 FS	*30.00 FS
53	1		*TAIL LAMP PANEL SEALANT LH	Necessary	60.00 FS	*20.00 FS
54	1		*BOOT LID SEALANT	Not Necessary	150.00 FS	*- FS
55	1		*SET BOOT LID OUTER GARNISH CLIP	Not Necessary	30.00 FS	*- FS
56	1		*SET BOOT LID INSULATOR CLIPS	Not Necessary	50.00 FS	*- FS
57	1		*REAR FENDER SEALANT LH	Necessary	150.00 FS	*60.00 FS
58	1		*SET REAR FENDER INNER COWLING CLIPS	Not Necessary	50.00 FS	*- FS
59	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
60	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
61	1		*REAR WINDSCREEN INNER SEAL	Necessary	60.00 FS	*40.00 FS
62	1		*REAR END PANEL SEALANT	Necessary	150.00 FS	*60.00 FS
63	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	30.00 FS	*10.00 FS
64	1		*REAR FLOOR PANEL INSULATION SEAL	Not Necessary	220.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	27,507.00	12,323.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,629.70	1,203.30
Total Parts (\$\$)	24,877.30	11,119.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	New	2,600.00	1,200.00
2	TO SPRAY PAINT AFFECTED AREA	New	2,200.00	1,000.00
3	TUFF COAT	New	250.00	60.00
4	WIRING CHECK	New	80.00	30.00
5	REMOVE AND REFIX CUSHION SEAT / UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	New	350.00	60.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
7	TRANSFER BOOTLID MECHANISM	New	80.00	60.00
8	CONDUCT WATER LEAKAGE TEST	New	80.00	0.00
9	REMOVE AND REINSTALL REVERSE CAMERA	New	80.00	50.00
10	REMOVE AND REFIX REAR WINDSCREEN	New	120.00	120.00
11	REMOVE AND REFIX REAR FUEL TANK	New	180.00	0.00
12	REMOVE AND REFIX REAR EXHAUST PIPE	New	180.00	0.00
13	REAR CHASSIS ALIGNMENT	New	250.00	0.00
14	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (\$)			6,710.00	2,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >