

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22006613/ANY3Q2**Date:** 31/10/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNA00226902100

Claimant Vehicle No : SLR6666C **Insured Vehicle No :** SS2255T

Date of Loss: 08/07/2022 Nature of Claim: TP Claim No: SNM22D204803/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLR6666C**

Make & Model: TOYOTA ALPHARD, 2.5 CVT ELEGANCE S/R (A) Engine No: 2ARH640002

Reg. Date: 02/11/2015 (Man. Year: 2015) Chassis No: JTNGF3DH508002905

Colour: Black Odometer: 183197 km

Engine Capacity: 2494 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50 R18 Rear Tyre Size: 235/50 R18

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	30,696.41	10,232.30	20,464.11	66.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,840.00	1,640.00	5,200.00	76.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	37,536.41	11,872.30	25,664.11	68.37
Approved Total (Overridden) (S\$)		9,500.00		
Nett Amount (S\$)	37,536.41	9,500.00	28,036.41	74.69

INSPECTION

Date of Assignment: 13/07/2022

Date Inspected: 12/07/2022 Inspected At: HD Perfect Autowork Pte Ltd (HQ)
8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 31 Oct 2022)

Parts: M1-MPV TOYOTA ALPHARD 2.5 CVT ELEGANCE S/R (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLR6666C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,402.40 FL	*736.00 FL
2	1		*FRONT BUMPER FOG LAMP RH	Cracked	516.10 FL	*335.00 FL
3	1		*FRONT BUMPER FOG LAMP HOUSING RH	Cracked	81.20 FL	*81.20 FL
4	1		*FRONT BUMPER FOG LAMP COVER CHROME RH	Not Necessary	231.20 FL	*- FL
5	1		*FRONT BUMPER TOWING COVER RH	Not Necessary	28.60 FL	*- FL
6	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	148.50 FL	*- FL
7	1		*FRONT BUMPER SIDE RETAINER	O/S Damaged	206.80 FL	*103.40 FL
8	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	466.40 FL	*- FL
9	1		*FRONT BUMPER SPONGE	Cracked	99.30 FL	*99.30 FL
10	1		*FRONT BUMPER BOTTOM COVER	Not Necessary	155.80 FL	*- FL
11	1		*FRONT BUMPER SENSOR	Damaged (1 PCS ONLY)	835.20 FL	*295.00 FL
12	2		*FRONT BUMPER SENSOR HOLDER	Necessary	64.40 FL	*64.40 FL
13	1		*FRONT GRILLE C/W MOULDING	Cracked	2,354.01 FL	*1,748.00 FL
14	1		*FRONT GRILLE LOGO	Not Necessary	1,673.50 FL	*- FL
15	4		*FRONT GRILLE TOP RUBBER	Not Necessary	120.80 FL	*- FL
16	2		*FRONT GRILLE SIDE MOULDING	Not Necessary	503.00 FL	*- FL
17	1		*HEADLAMP(LED)	O/S Cut	7,593.80 FL	*3,796.90 FL
18	1		*FRONT SUPPORT PANEL	Not Necessary	1,561.20 FL	*- FL
19	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	248.50 FL	*- FL
20	1		*WASHER TANK	Deformed	487.60 FL	*169.00 FL
21	1		*FRONT FENDER RH	Buckled	1,312.50 FL	*1,082.00 FL
22	1		*FRONT FENDER COWLING RH	Torn	259.30 FL	*259.30 FL
23	1		*FRONT FENDER INNER GARNISH RH	Not Necessary	123.20 FL	*- FL
24	1		*FRONT FENDER SUPPORT BRACKET RH	Not Necessary	85.20 FL	*- FL
25	1		*FRONT RADAR SENSOR RH	Not Necessary	2,416.70 FL	*- FL
26	1		*FRONT STEERING RACK & PINION	Not Necessary	1,955.30 FL	*- FL
27	1		*FRONT KNUCKLE ARM RH	Damaged	734.80 FL	*734.80 FL
28	1		*FRONT LOWER ARM RH	Bent	815.30 FL	*513.00 FL
29	1		*FRONT STABILIZER BAR LINKAGE RH	Not Necessary	165.20 FL	*- FL
30	1		*FRONT SHOCK ABSORBER RH	Bent	519.10 FL	*519.10 FL
31	1		*FRONT WHEEL HUP C/W BEARING RH	Damaged	670.30 FL	*480.00 FL
32	1		*SET FRONT BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
33	1		*SET FRONT GRILLE CLIP	Necessary	80.00 FS	*30.00 FS
34	1		*FRONT SUPPORT PANEL SEALANT	Not Necessary	120.00 FS	*- FS
35	1		*SET FRONT SUPPORT PANEL TOP GARNISH CLIP	Not Necessary	60.00 FS	*- FS
36	1		*SET FRONT FENDER INNER GARNISH CLIP RH	Not Necessary	80.00 FS	*- FS
37	1		*SET FRONT FENDER COWLING CLIPS	Necessary	80.00 FS	*30.00 FS
38	1		*FRONT DOOR WRAPPING RH	Necessary	1,800.00 FS	*400.00 FS
39	1		*FRONT BUMPER WRAPPING RH	Necessary	1,800.00 FS	*400.00 FS
40	1		*FRONT FENDER WRAPPING RH	Necessary	1,200.00 FS	*400.00 FS
41	1		*FRONT WHEEL TYRE RH	Not Necessary	680.00 FS	*- FS
42	1		*SET FRONT WHEEL SPORT RIM	Cut	2,800.00 FS	*680.00 FS
43	1		*COOLANT	Not Necessary	250.00 FS	*- FS
44	1		*BRAKE OIL	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 37,905.21 12,986.40

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 25.00/25.00% (S\$)					7,208.80	2,754.10
Total Parts (S\$)					30,696.41	10,232.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVING AND REPLACING PARTS	New	1,800.00	600.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,400.00	600.00
3	TUFF COAT	New	250.00	60.00
4	WIRING CHECK	New	250.00	30.00
5	REFOCUS HEADLAMP BEAM	New	80.00	0.00
6	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	New	350.00	0.00
7	REMOVE AND REFIX AND RESET FRONT SENSOR	New	80.00	50.00
8	REMOVE ,REFIX AND RESET FRONT RADAR SENSOR	New	800.00	0.00
9	REMOVE AND REFIX FRONT UNDERCARRIAGE	New	850.00	220.00
10	FOUR WHEEL ALIGNMENT	New	120.00	80.00
11	REMOVE AND REFIX POWER STEERING RACK AND PINION	New	380.00	0.00
12	RESET ABS LIGHT	New	200.00	0.00
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	280.00	0.00
Gross Labour Cost (\$)			6,840.00	1,640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >