

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22006615/DCY3Q2**Date:** 13/10/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNA00010482101

Claimant Vehicle No : SJH9384Y **Insured Vehicle No :** SMK9731C

Date of Loss: 08/07/2022 Nature of Claim: TP Claim No: SNM22D204823/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJH9384Y**

Make & Model: HONDA CIVIC, 1.5 (A) Engine No: R16A13006739

Reg. Date: 28/08/2008 (Man. Year: 2008) Chassis No: JHMFD46208S202310

Colour: Silver Odometer: 148832 km

Engine Capacity: 1595 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16

Front Left Side: Yokohama 5 mm Rear Left Side: Yokohama 5 mm

Front Right Side: Yokohama 5 mm Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,250.80	1,207.08	17,043.72	93.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,120.00	1,180.00	4,940.00	80.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	24,370.80	2,387.08	21,983.72	90.21
Approved Total (Overridden) (\$\$)		1,900.00		
(\$\$)	24,370.80	1,900.00	22,470.80	92.20
+ GST 7.00/7.00% (\$\$)	1,705.96	133.00	1,572.96	92.20
Nett Amount (\$\$)	26,076.76	2,033.00	24,043.76	92.20

INSPECTION

Date of Assignment: 12/07/2022

Date Inspected: 13/07/2022 Inspected At: JWG International Pte Ltd (HQ)
Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK
AutoPoint
Singapore 568047

Estimated Period of Repair: 4.0 days

Adjuster: BRYAN TANI**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Oct 2022)
Parts:	143	HONDA CIVIC 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJH9384Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Repair	1,450.00 FL	*- FL
2	2		*BOOTLID LAMP LH/RH	Not Necessary	388.00 FL	*- FL
3	2		*BOOTLID HINGE LH/RH	Not Necessary	220.00 FL	*- FL
4	1		*BOOTLID LOGO	Necessary	51.00 FL	*35.00 FL
5	1		*BOOTLID NO PLATE TOP GARNISH	Not Necessary	795.00 FL	*- FL
6	1		*BOOTLID CIVIC EMBLEM	Necessary	90.00 FL	*32.00 FL
7	1		*BOOTLID 1.8 EMBLEM	Necessary	88.00 FL	*36.00 FL
8	1		*BOOTLID I-VTEC EMBLEM	Necessary	61.00 FL	*38.00 FL
9	1		*BOOTLID LOCK	Not Necessary	311.00 FL	*- FL
10	1		*BOOTLID SWITCH	Not Necessary	201.00 FL	*- FL
11	2		*BOOTLID NO PLATE LAMP LH/RH	Not Necessary	184.00 FL	*- FL
12	1		*BOOTLID INNER TRIM	Not Necessary	610.00 FL	*- FL
13	1		*BOOTLID WEATHERSTRIP	Serviceable	329.00 FL	*- FL
14	2		*TAIL LAMP LH/RH	Not Necessary	1,978.00 FL	*- FL
15	2		*TAIL LAMP LOWER BRACKET LH/RH	Not Necessary	240.00 FL	*- FL
16	1		*REAR BUMPER	Distorted / Cracked	890.00 FL	*638.10 FL
17	2		*REAR BUMPER SIDE RETAINER LH/RH	Not Necessary	138.00 FL	*- FL
18	1		*REAR BUMPER EXHAUST GARNISH	Not Necessary	134.00 FL	*- FL
19	1		*REAR BUMPER SENSOR WIRE HARNESS	Not Necessary	992.00 FL	*- FL
20	1		*REAR BUMPER UNDERCOVER	Not Necessary	210.00 FL	*- FL
21	1		*REAR REINFORCEMENT BAR	Not Necessary	810.00 FL	*- FL
22	1		*REAR END PANEL	Dented	992.00 FL	*436.00 FL
23	1		*REAR END PANEL TOP GARNISH	Not Necessary	298.00 FL	*- FL
24	1		*REAR KEYLESS BUZZER	Not Necessary	201.00 FL	*- FL
25	1		*SPARE WHEEL PANEL	Not Necessary	1,680.00 FL	*- FL
26	1		*SPARE WHEEL PANEL TOP BOARD	Not Necessary	429.00 FL	*- FL
27	1		*SPARE WHEEL PANEL TOOL BOX	Not Necessary	329.00 FL	*- FL
28	2		*REAR FENDER LH/RH	Not Necessary	4,280.00 FL	*- FL
29	2		*REAR FENDER INNER TRIM BOARD LH/RH	Not Necessary	2,560.00 FL	*- FL
30	1		*REAR EXHAUST MOUNTING	Not Necessary	99.00 FL	*- FL
31	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	194.00 FL	*- FL
32	1		*REAR WINDSCREEN MOULDING	Not Necessary	294.00 FL	*- FL
33	1		*BOOTLID INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
34	1		*BOOTLID NO PLATE TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
35	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*15.00 FS
36	1		*REAR BUMPER LOWER LID CLIPS	Not Necessary	50.00 FS	*- FS
37	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*20.00 FS
38	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
39	1		*SPARE WHEEL PANEL SEALANT	Not Necessary	80.00 FS	*- FS
40	1		*REAR FENDER INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
41	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
42	1		*REAR WINDSCREEN DAMPING SEAL	Not Necessary	30.00 FS	*- FS
43	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	30.00 FS	*- FS
44	1		*REAR FENDER SEALANT	Not Necessary	80.00 FS	*- FS
45	1		*REAR NO PLATE & GARNISH	Not Necessary	100.00 FS	*- FS
46	1		*REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS

Report was unsubmitted during this print-out.

10/13/22, 2:15 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					22,556.00	1,450.10
- List Item Discount on L Items 20.00/20.00% (S\$)					4,305.20	243.02
Total Parts (S\$)					18,250.80	1,207.08
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILITATE REPAIRS	New	300.00	0.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,000.00	500.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,000.00	600.00
4	TO TUFF COAT DAMAGED AREAS	New	300.00	40.00
5	TO RNR REAR WINDSCREEN TO FACILITATE REPAIRS	New	500.00	0.00
6	TO RNR FUEL TANK FILLER PIPE TO FACILITATE REPAIRS	New	100.00	0.00
7	TO RNR BOOTLID MECHANISM TO FACILITATE REPAIRS	New	150.00	0.00
8	TO RNR EXHAUST & ATTACHMENT PARTS TO FACILITATE REPAIRS	New	150.00	0.00
9	TO RNR REAR BUMPER SENSOR TO FACILITATE REPAIRS	New	120.00	40.00
10	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	New	200.00	0.00
11	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS ,RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
Gross Labour Cost (S\$)			6,120.00	1,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >