

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22006618/KWY3Q2**Date:** 04/01/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00154402101
<b>Claimant Vehicle No :</b>	GBH9493K	<b>Insured Vehicle No :</b>	SJH4750G
Date of Loss:	08/07/2022	Nature of Claim:	TP
		Claim No:	SNM22D204817/C02

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>GBH9493K</b>	Engine No:	1KD2830103
Make & Model:	TOYOTA HIACE, 2.0 (M)	Chassis No:	JTFHT02P900246007
Reg. Date:	31/10/2018 (Man. Year: 2018)	Odometer:	87127 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195 R15X8	Rear Tyre Size:	195 R15X8
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 3 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 3 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,771.00	1,341.00	430.00	24.28
Miscellaneous Items	260.00	260.00	0.00	0.00
Labour	1,820.00	1,490.00	330.00	18.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>3,851.00</b>	<b>3,091.00</b>	<b>760.00</b>	<b>19.74</b>
<b>+ GST 7.00/7.00% (S\$)</b>	269.57	216.37	53.20	19.74
<b>Nett Amount (S\$)</b>	<b>4,120.57</b>	<b>3,307.37</b>	<b>813.20</b>	<b>19.74</b>

**INSPECTION**

Date of Assignment:	14/11/2022	Present Location:	Cheng Hoe Motor Pte Ltd (Yishun)
Date Inspected:	27/10/2022	Inspected At:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	5.0 days		

**Adjuster:** KENNETH KONG**Manager:** XinYu

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 04 Jan 2023)	
<b>Parts:</b>	N/A	TOYOTA HIACE 2.0 (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBH9493K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 pc rear bumper	Bent	160.00 F	*160.00 F
2	1		*6 pcs rear bumper clips @ \$1.50/pc	Necessary	9.00 F	*9.00 F
3	1		*1 pc tailgate	Bent	680.00 F	*680.00 F
4	1		*1 pc tailgate inner lock	Dented	100.00 F	*100.00 F
5	1		*1 pc tailgate inner rubber	Cut	130.00 F	*130.00 F
6	1		*1 pc tailgate logo	Necessary	32.00 F	*32.00 F
7	1		*1 pc tailgate emblem	Necessary	30.00 F	*30.00 F
8	1		*1 pc rear end panel (inner)	Repair	430.00 F	*- F
9	1		*1 pc rear end panel (outer)	Buckled	140.00 F	*140.00 F
10	1		*1 pc rear end panel scuff plate	Dented	60.00 F	*60.00 F

F=Franchise part.

<b>Total Parts (\$\$)</b>	<b>1,771.00</b>	<b>1,341.00</b>
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	<b>1 pc tailgate sticker 70km</b> (Necessary)	10.00	10.00
2	1	<b>1 pc tailgate sticker 8 pax</b> (Necessary)	10.00	10.00
3	1	<b>1 set reverse sensor</b> (Shorted)	200.00	200.00
4	1	<b>1 unit rear tailgate windscreen glass sealant</b> (Necessary)	40.00	40.00
<b>Sub Total (\$\$)</b>			<b>260.00</b>	<b>260.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	Remove & refix rear windscreen glass	New	120.00	120.00
2	Remove & refix rear bumper & attachments,taillamps,tailgate & attachments;to cut,weld & renew rear end panel (inner & outer);knocking & repair rear floorboard & realign the same	New	800.00	600.00
3	Putty & respray rear bumper & attachments,parking sensors,tailgate,rear end panel (inner & outer),rear floorboard & all affected areas	New	800.00	700.00
4	Remove & refix reverse camera, reset & realign the same	New	40.00	40.00
5	Rustproofing	New	60.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,820.00</b>	<b>1,490.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >