

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22006619/UVY3E2

Date: 29/07/2022

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00018442201		
Claimant Vehicle No :	GBK2688X	Insured Vehicle No :	YQ3335D		
Date of Loss:	04/07/2022	Nature of Claim:	TP	Claim No:	SNM22D204684/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBK2688X	Engine No:	HR16164026D
Make & Model:	NISSAN NV200, 1.6 MT PETROL (A)	Chassis No:	JN1YAAM20Z0001014
Reg. Date:	28/03/2020 (Man. Year: 2020)	Odometer:	75005 km
Colour:	Silver		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes	
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/70 R14	Rear Tyre Size:	185/70 R14
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,655.24	3,834.00	4,821.24	55.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,810.00	1,330.00	1,480.00	52.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,465.24	5,164.00	6,301.24	54.96
Approved Total (Overridden) (S\$)		4,100.00		
(S\$)	11,465.24	4,100.00	7,365.24	64.24
+ GST 7.00/7.00% (S\$)	802.57	287.00	515.57	64.24
Nett Amount (S\$)	12,267.81	4,387.00	7,880.81	64.24

INSPECTION

Date of Assignment:	13/07/2022	
Date Inspected:	13/07/2022 Inspected At:	LEE BROTHERS AUTOMOTIVE PTE. LTD. (HQ) 1 Kaki Bukit Ave 6, #02-47 Autobay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 29 Jul 2022)	
Parts:	N/A	NISSAN NV200 1.6 MT PETROL (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBK2688X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Badly Dented	1,978.40 FL	*1,978.40 FL
2	1		*TAILGATE GLASS	Shattered	1,485.00 FL	*1,285.00 FL
3	1		*TAILGATE LOGO	Not Necessary	79.90 FL	*- FL
4	1		*TAILGATE EMBLEM NV200	Necessary	145.20 FL	*145.20 FL
5	1		*TAILGATE EMBLEM VANETTE	Necessary	86.60 FL	*86.60 FL
6	1		*TAILGATE WIPER ARM	Not Necessary	96.90 FL	*- FL
7	1		*TAILGATE WIPER MOTOR	Not Necessary	481.90 FL	*- FL
8	1		*TAILGATE TOP MIRROR	Damaged	381.60 FL	*381.60 FL
9	1		*TAILGATE OUTER GARNISH	Not Necessary	351.50 FL	*- FL
10	1		*TAILGATE INNER TRIM	Not Necessary	286.90 FL	*- FL
11	20		*TAILGATE INNER TRIM CLIPS	Not Necessary	110.00 FL	*- FL
12	1		*TAILGATE W/STRIP	Not Necessary	241.20 FL	*- FL
13	2		*TAILGATE DAMPER	Not Necessary	373.80 FL	*- FL
14	1		*TAILLAMP - LH	Cracked	283.20 FL	*283.20 FL
15	1		*TAILLAMP FILLER PANEL - LH	Repair	423.50 FL	*- FL
16	1		*REAR FENDER - LH	Repair	1,636.10 FL	*- FL
17	1		*REAR FENDER INNER TRIM	Not Necessary	281.90 FL	*- FL
18	20		*REAR FENDER INNER TRIM CLIPS	Not Necessary	110.00 FL	*- FL
19	1		*SET TAILGATE GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
20	1		*SET TAILGATE GLASS FOAMTAPE	Necessary	65.00 FS	*40.00 FS
21	1		*REAR STICKER - 70KM/H	Necessary	10.00 FS	*10.00 FS
22	1		*REAR RECORDER CAMERA	Not Necessary	550.00 FS	*- FS
					Sub Total (\$\$)	9,538.60 4,250.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	883.36 416.00
					Total Parts (\$\$)	8,655.24 3,834.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REPLACE REAR TAILGATE GLASS	New	180.00	120.00
2	TO CHECK REAR ELECTRICAL WIRING	New	50.00	20.00
3	TO REMOVE & REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR	New	120.00	0.00
4	TO TUFF KOTE	New	100.00	40.00
5	TO REMOVE, REFIX REAR RECORDER CAMERA	New	80.00	50.00
6	TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS	New	1,080.00	500.00
7	TO PANEL BEAT, CUT, WELD, REMOVE & REPLACE DAMAGED PARTS	New	1,200.00	600.00
Gross Labour Cost (\$\$)			2,810.00	1,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >