

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22006620/GCY3Q2**Date:** 14/09/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00236752100

Claimant Vehicle No : SLJ1942E **Insured Vehicle No :** SFX9D

Date of Loss: 12/07/2022 Nature of Claim: TP Claim No: SNM22D204826C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLJ1942E**

Make & Model: KIA FORTE K3, 1.6 (A) Engine No: G4FGGH651551

Reg. Date: 30/11/2016 (Man. Year: 2016) Chassis No: KNAFZ411MH5658126

Colour: Grey Odometer: 84846 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/45 R17 Rear Tyre Size: 215/45 R17

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 23,731.82 | 18,687.93 | 5,043.89 | 21.25 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 6,100.00 | 4,510.00 | 1,590.00 | 26.07 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 29,831.82 | 23,197.93 | 6,633.89 | 22.24 |
| Approved Total (Overridden) (S\$) | | 18,500.00 | | |
| (S\$) | 29,831.82 | 18,500.00 | 11,331.82 | 37.99 |
| + GST 7.00/7.00% (S\$) | 2,088.23 | 1,295.00 | 793.23 | 37.99 |
| Nett Amount (S\$) | 31,920.05 | 19,795.00 | 12,125.05 | 37.99 |

INSPECTION

Date of Assignment: 13/07/2022

Date Inspected: 13/07/2022 Inspected At: Modern Automotive Pte Ltd (HQ)
Blk 3023A Ubi Road 1, #01-61 & #01-58
Singapore 408717

Estimated Period of Repair: 16.0 days

Adjuster: ADRIAN LING**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | |
|--|--|
| Part Source: MRM-SG | Version: 1.0 (Last Synchronised: 14 Sep 2022) |
| Parts: 143 | KIA FORTE K3 1.6 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: Repairer's | (Price-denominated Standard List) |
| Print Code: (Unsubmitted, no print-code for SLJ1942E) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---|----------------------|-------------|--------------|
| 1 | 1 | | *FRONT NUMBER PLATE GARNISH | Deformed | 101.60 FL | *101.60 FL |
| 2 | 1 | | *FRONT BUMPER | Deformed | 658.40 FL | *658.40 FL |
| 3 | 2 | | *FRONT BUMPER SIDE HOLDER -LH & RH | Necessary | 76.80 FL | *76.80 FL |
| 4 | 1 | | *FRONT BUMPER LOWER GRILLE | Not Necessary | 169.50 FL | *- FL |
| 5 | 2 | | *FRONT BUMPER FOG LAMP -LH & RH | Not Necessary | 528.20 FL | *- FL |
| 6 | 1 | | *FRONT BUMPER FOG LAMP COVER -LH & RH | N/S Cut | 124.80 FL | *62.40 FL |
| 7 | 1 | | *FRONT BUMPER TOW COVER | Not Necessary | 34.10 FL | *- FL |
| 8 | 1 | | *FRONT BUMPER REINFORCEMENT | Dented | 354.90 FL | *354.90 FL |
| 9 | 1 | | *FRONT BUMPER SPONGE | Cracked | 141.80 FL | *141.80 FL |
| 10 | 1 | | *FRONT BUMPER LOGO | Necessary | 65.90 FL | *65.90 FL |
| 11 | 1 | | *FRONT BUMPER LOWER BEAM | Not Necessary | 138.60 FL | *- FL |
| 12 | 4 | | *FRONT BUMPER SENSOR | Damaged (2 PCS ONLY) | 1,020.00 FL | *510.00 FL |
| 13 | 1 | | *FRONT BUMPER SENSOR WIRE HARNESS | Not Necessary | 348.40 FL | *- FL |
| 14 | 4 | | *FRONT BUMPER SENSOR HOLDER | Necessary | 100.40 FL | *100.40 FL |
| 15 | 2 | | *HEAD LAMP -LH & RH | Cracked | 4,215.40 FL | *4,215.40 FL |
| 16 | 1 | | *FRONT SUPPORT PANEL | Cracked | 798.50 FL | *798.50 FL |
| 17 | 1 | | *FRONT SUPPORT PANEL TOP GARNISH | Deformed | 165.90 FL | *165.90 FL |
| 18 | 1 | | *BONNET | Repair | 877.80 FL | *- FL |
| 19 | 1 | | *BONNET LOCK | Not Necessary | 68.90 FL | *- FL |
| 20 | 1 | | *AIR CON CONDENSER | Not Necessary | 820.40 FL | *- FL |
| 21 | 1 | | *AIR CON CONDENSER SIDE GUIDE | O/S Deformed | 70.80 FL | *35.40 FL |
| 22 | 1 | | *FRONT GRILLE | Cracked | 328.00 FL | *328.00 FL |
| 23 | 1 | | *FRONT GRILLE CHROME MOULDING | Cut | 136.00 FL | *136.00 FL |
| 24 | 2 | | *REAR NUMBER PLATE LAMP -LH & RH | Not Necessary | 110.20 FL | *- FL |
| 25 | 1 | | *REAR BUMPER | Distorted | 688.90 FL | *688.90 FL |
| 26 | 2 | | *REAR BUMPER SIDE HOLDER -LH & RH | Damaged | 768.00 FL | *768.00 FL |
| 27 | 1 | | *REAR BUMPER LOWER GARNISH | Distorted | 298.40 FL | *298.40 FL |
| 28 | 2 | | *REAR BUMPER LOWER GARNISH REFLECTOR -LH & RH | Cracked | 171.80 FL | *171.80 FL |
| 29 | 1 | | *REAR BUMPER REINFORCEMENT | Distorted | 385.60 FL | *385.60 FL |
| 30 | 2 | | *REAR BUMPER REINFORCEMENT STAY-LH & RH | Dented | 190.20 FL | *190.20 FL |
| 31 | 5 | | *REAR BUMPER REINFORCEMENT BRACKET | Damaged | 92.50 FL | *92.50 FL |
| 32 | 1 | | *REAR BUMPER REINFORCEMENT ANTENNA SENSOR | Damaged | 185.40 FL | *185.40 FL |
| 33 | 1 | | *REAR BUMPER UNDERCOVER -LH | Deformed | 112.20 FL | *112.20 FL |
| 34 | 4 | | *REVERSE SENSOR | Damaged | 1,001.60 FL | *1,001.60 FL |
| 35 | 1 | | *REVERSE SENSOR WIRE HARNESS | Not Necessary | 349.40 FL | *- FL |
| 36 | 4 | | *REVERSE SENSOR HOLDER | Necessary | 105.60 FL | *105.60 FL |
| 37 | 1 | | *REAR END PANEL | Distorted | 480.50 FL | *480.50 FL |
| 38 | 1 | | *REAR END PANEL TOP GARNISH | Deformed | 153.90 FL | *153.90 FL |
| 39 | 1 | | *BOOTLID | Distorted | 894.50 FL | *894.50 FL |
| 40 | 1 | | *BOOTLID LOCK | Damaged | 165.90 FL | *165.90 FL |
| 41 | 1 | | *BOOTLID WEATHERSTRIPE | Cut | 178.50 FL | *178.50 FL |
| 42 | 2 | | *BOOTLID HINGE | Bent | 156.20 FL | *156.20 FL |
| 43 | 1 | | *BOOTLID TOP SPOILER | Cracked | 585.10 FL | *585.10 FL |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--|---------------|-------------|--------------|
| 44 | 1 | | *BOOTLID INNER TRIMBOARD | Torn | 189.40 FL | *189.40 FL |
| 45 | 2 | | *BOOTLID LAMP -LH & RH | Cracked | 1,392.20 FL | *1,392.20 FL |
| 46 | 1 | | *KIA LOGO | Necessary | 52.40 FL | *52.40 FL |
| 47 | 1 | | *CERATO WORDING | Necessary | 49.50 FL | *49.50 FL |
| 48 | 2 | | *TAIL LAMP -LH & RH | Cracked | 1,584.20 FL | *1,584.20 FL |
| 49 | 2 | | *TAIL LAMP PANEL -LH & RH | Dented | 454.80 FL | *454.80 FL |
| 50 | 2 | | *REAR FENDER INNER TRIMBOARD -LH & RH | Deformed | 516.40 FL | *516.40 FL |
| 51 | 1 | | *SPARE TYRE PANEL | Distorted | 866.90 FL | *866.90 FL |
| 52 | 1 | | *SPARE TYRE PANEL TOP COVER | Torn | 190.50 FL | *190.50 FL |
| 53 | 1 | | *SPARE TYRE NUT SCREW | Damaged | 45.80 FL | *45.80 FL |
| 54 | 1 | | *REAR EXHAUST PIPE | Repair | 757.80 FL | *- FL |
| 55 | 1 | | *REAR EXHAUST PIPE MOUNTING | Not Necessary | 36.90 FL | *- FL |
| 56 | 1 | | *REAR EXHAUST PIPE GASKET | Not Necessary | 34.10 FL | *- FL |
| 57 | 1 | | *REAR EXHAUST PIPE HEAT SHIELD | Crumpled | 89.40 FL | *89.40 FL |
| 58 | 1 | | *FRONT NUMBER PLATE | Bent | 30.00 FS | *30.00 FS |
| 59 | 1 | | *FRONT NUMBER PLATE HOLDER | Deformed | 30.00 FS | *30.00 FS |
| 60 | 1 | | *SET FRONT BUMPER CLIPS | Necessary | 30.00 FS | *30.00 FS |
| 61 | 1 | | *SET FRONT SUPPORT PANEL TOP GARNISH CLIPS | Necessary | 20.00 FS | *20.00 FS |
| 62 | 1 | | *SET AIR CON CONDENSER SIDE GUIDE CLIPS | Necessary | 20.00 FS | *20.00 FS |
| 63 | 1 | | *COOLANT | Necessary | 50.00 FS | *50.00 FS |
| 64 | 1 | | *SET FRONT GRILLE CLIPS | Necessary | 20.00 FS | *20.00 FS |
| 65 | 1 | | *REAR NUMBER PLATE | Dented | 30.00 FS | *30.00 FS |
| 66 | 1 | | *REAR NUMBER PLATE HOLDER | Deformed | 30.00 FS | *30.00 FS |
| 67 | 1 | | *SET REAR BUMPER CLIPS | Necessary | 30.00 FS | *30.00 FS |
| 68 | 1 | | *SET REAR BUMPER UNDERCOVER CLIPS | Necessary | 20.00 FS | *20.00 FS |
| 69 | 1 | | *SET REAR END PANEL TOP GARNISH CLIPS | Necessary | 20.00 FS | *20.00 FS |
| 70 | 1 | | *REAR END PANEL SEALANT | Necessary | 60.00 FS | *60.00 FS |
| 71 | 1 | | *BOOTLID TOP SPOILER SEALANT | Necessary | 50.00 FS | *50.00 FS |
| 72 | 1 | | *SET BOOTLID INNER TRIMBOARD CLIPS | Necessary | 30.00 FS | *30.00 FS |
| 73 | 1 | | *REAR CAMERA | Not Necessary | 500.00 FS | *- FS |
| 74 | 1 | | *SET REAR FENDER INNER TRIMBOARD CLIPS | Necessary | 60.00 FS | *60.00 FS |
| 75 | 1 | | *SPARE TYRE PANEL INSULATION PADS | Necessary | 280.00 FS | *200.00 FS |
| 76 | 1 | | *SPARE TYRE PANEL SEALANT | Necessary | 60.00 FS | *60.00 FS |
| 77 | 1 | | *REAR EXHAUST CHROME PIPE | Dented | 150.00 FS | *80.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|---|------------------|------------------|
| Sub Total (S\$) | 26,199.80 | 20,667.70 |
| - List Item Discount on L Items 10.00/10.00% (S\$) | 2,467.98 | 1,979.77 |
| Total Parts (S\$) | 23,731.82 | 18,687.93 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|---|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | TO KNOCKING OUT FRONT PORTION & RENEW ABOVE PARTS | New | 1,200.00 | 700.00 |
| 2 | TO PUTTY & SPRAY UP PAINT WORKS (FRONT) | New | 800.00 | 600.00 |
| 3 | TO CHECK WIRING (FRONT) | New | 50.00 | 30.00 |
| 4 | TO REMOVE FRONT BUMPER SENSOR | New | 100.00 | 50.00 |
| 5 | TO REMOVE CONDENSER & TOP-UP AIRCON GAS | New | 120.00 | 60.00 |
| 6 | TO REMOVE RADIATOR & TOP-UP COOLANT | New | 120.00 | 60.00 |
| 7 | TO KNOCKING OUT REAR PORTION & RENEW ABOVE PARTS | New | 1,500.00 | 1,300.00 |
| 8 | TO PUTTY & SPRAY UP PAINT WORKS (REAR) | New | 1,300.00 | 1,200.00 |
| 9 | TO CHECK WIRING(REAR) | New | 50.00 | 30.00 |
| 10 | TO SPRAY TUFF COAT | New | 150.00 | 100.00 |
| 11 | TO REMOVE REVERSE SENSOR | New | 100.00 | 50.00 |
| 12 | TO REMOVE REAR CAMERA | New | 100.00 | 50.00 |
| 13 | TO REMOVE UPHOLSTERY | New | 150.00 | 80.00 |
| 14 | TO TRANSFER BOOTLID FITTINGS | New | 150.00 | 60.00 |
| 15 | TO REMOVE REAR EXHAUST PIPE | New | 150.00 | 80.00 |
| 16 | TOWING CHARGES | New | 60.00 | 60.00 |
| Gross Labour Cost (\$\$) | | | 6,100.00 | 4,510.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >