

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897**Our File No:** CS/AIS22006626/ECY3Q2**Date:** 21/12/2022**REFERENCE**

Insured/Claimant:	YEW HENG THAM	Policy No:	SP2000584427	
Date of Loss:	29/06/2022	Nature of Claim:	OD	Claim No: 202222005459

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SMQ713H</b>	Engine No:	31905754B38A15A
Make & Model:	BMW 216D, 1.5 (A)	Chassis No:	WBA6V120305N97921
Reg. Date:	29/10/2019 (Man. Year: 2019)	Odometer:	76938 km
Colour:	Blue		
Engine Capacity:	1499 cc		
Market Value/New Car Price:	S\$130,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	205/55 R17	Rear Tyre Size:	205/55 R17
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Pirelli 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,607.50	3,843.95	2,763.55	41.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,114.00	8,594.00	2,520.00	22.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>17,721.50</b>	<b>12,437.95</b>	<b>5,283.55</b>	<b>29.81</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,240.51</b>	<b>870.66</b>	<b>369.85</b>	<b>29.81</b>
<b>Nett Amount (S\$)</b>	<b>18,962.01</b>	<b>13,308.61</b>	<b>5,653.40</b>	<b>29.81</b>

**INSPECTION**

Date of Assignment:	13/07/2022	
Date Inspected:	22/07/2022 Inspected At:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941
Estimated Period of Repair:	10.0 days	

**Adjuster:** CHEN TSUE YEE**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference**

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 21 Dec 2022)
<b>Parts:</b> 143	BMW 216D 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SMQ713H)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
2	2		*C CLIP FOR PLASTIC NUT	Not Necessary	2.20 FS	*- FS
3	2		*C-CLIP	Not Necessary	3.40 FS	*- FS
4	1		*ALLOY RIM 7.50X17 DOUBLE SPK 549	Cut	977.35 FS	*977.35 FS
5	1		*REAR LH SIDE PANEL	Dented	1,496.05 FS	*1,496.05 FS
6	1		*RR LH DOOR	Repair	1,159.75 FS	*- FS
7	1		*RR BUMPER LH SIDE GUIDE	Not Necessary	163.55 FS	*- FS
8	1		*RR BUMPER LH INNER SIDE GUIDE	Not Necessary	163.55 FS	*- FS
9	1		*LEFT PROTECT	Not Necessary	11.45 FS	*- FS
10	1		*REAR BUMPER PANEL PRIMED (LINES PDC)	Repair	1,050.55 FS	*- FS
11	8		*CLIP COVER FOR COLUMN B	Not Necessary	7.60 FS	*- FS
12	1		*REAR LH SIDE WINDOW FIXED (ALU HOCH)	Necessary	305.60 FS	*305.60 FS
13	1		*REAR DOOR JOINT SEAL	Not Necessary	34.05 FS	*- FS
14	1		*REAR DOOR EDGE PROTECTION	Not Necessary	167.45 FS	*- FS
15	1		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Necessary	131.55 FS	*131.55 FS
16	1		*LH REINFORCEMENT PLATE SILL	Necessary	56.45 FS	*56.45 FS
17	1		*LH REINFORCEMENT PLATE C PILLAR	Necessary	56.30 FS	*56.30 FS
18	1		*LH REINFORCEMENT PLATE D PILLAR	Necessary	64.20 FS	*64.20 FS
19	1		*BULB WHITE (12V 21W)	Necessary	8.15 FS	*8.15 FS
20	20		*BLIND RIVET AVIBVLB	Necessary	11.00 FS	*11.00 FS
21	1		*(DG) BODYWORK ADHESIVE K5A (50ML)	Necessary	121.90 FS	*121.90 FS
22	1		*(DG) CLEANER R1 (100ML)	Necessary	26.15 FS	*26.15 FS
23	1		*(DG) CLEANER R1 (100ML)	Necessary	26.15 FS	*26.15 FS
24	1		*PUNCH RIVET N4 (50 PCS)	Necessary	27.50 FS	*27.50 FS
25	1		*(DG/SL) BODY ADHESIVE K5 (195ML)	Necessary	353.50 FS	*353.50 FS
26	1		*(SL/DG) SEALANT D2 290ML	Necessary	32.10 FS	*32.10 FS

F=Franchise part. S=SpcNett.

<b>Total Parts (S\$)</b>	<b>6,607.50</b>	<b>3,843.95</b>
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE REAR BUMPER ,REAR LEFT DOOR LEFT SIDE SILL	New	5,100.00	4,250.00
2	TO RESPRAY REAR BUMPER ,REAR LEFT DOOR ,REAR LEFT FENDER AND LEFT SIDE SILL	New	3,634.00	2,667.00
3	TO CARRY OUT BODY CAVIRT PRESERVATION (PER PANEL)	New	118.00	0.00
4	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW DOOR INCLUDING CONDUCT CHECK ON NEW DOOR POWER WINDOW SYSTEM FOR PROPER FUNCTION (1 DOOR)	New	531.00	504.00
5	TO CHECK ELECTRICAL SYSTEM	New	177.00	168.00
6	TO REPLACE WHEEL RIM INCLUDING BALANCING	New	94.00	89.00
7	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT IN ACCORDANCE WITH BMW SPECIFICATIONS	New	531.00	504.00
8	TO REMOVE AND INSTALL REAR SIDE WINDOW GLASS TO FACILITATE REPAIR	New	338.00	321.00
9	TO SUPPLY AND INSTALL REAR LEFT WINDOW GLASS SOLAR FILM	New	500.00	0.00
10	TO CONDUCT WATER LEAK TESTS	New	91.00	91.00
<b>Gross Labour Cost (S\$)</b>			<b>11,114.00</b>	<b>8,594.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >