

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22006630/TVY3Q2**Date:** 19/04/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00110382101
Claimant Vehicle No :	SBL328T	Insured Vehicle No :	GBH8161A
Date of Loss:	08/07/2022	Nature of Claim:	TP
		Claim No:	SNM22D204824/C01/CSC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBL328T	Engine No:	28291480430724
Make & Model:	MERCEDES-BENZ GLA200, 1.3 AMG LINE (A)	Chassis No:	W1N2477872J161163
Reg. Date:	21/05/2021 (Man. Year: 2020)	Odometer:	9079 km
Colour:	White		
Engine Capacity:	1332 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R18	Rear Tyre Size:	235/55 R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,608.44	5,971.19	9,637.25	61.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,870.00	1,530.00	4,340.00	73.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,478.44	7,501.19	13,977.25	65.08
Approved Total (Overridden) (S\$)		6,000.00		
(S\$)	21,478.44	6,000.00	15,478.44	72.07
+ GST 8.00/8.00% (S\$)	1,718.28	480.00	1,238.28	72.07
Nett Amount (S\$)	23,196.72	6,480.00	16,716.72	72.07

INSPECTION

Date of Assignment:	11/04/2023	
Date Inspected:	18/07/2022 Inspected At:	Xin Yun Auto Private Limited (HQ) 1 Kaki Bukit Avenue 6, #01-59 Autobay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Apr 2023)
Parts:	M1-SUV	MERCEDES-BENZ GLA200 1.3 AMG LINE (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBL328T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER ASSY	Deformed	2,250.00 F	*1,353.32 FL
2	2		*BUMPER SIDE BRACKET	Not Necessary	280.00 F	*- FL
3	2		*BUMPER SIDE RETAINER	Not Necessary	260.00 F	*- FL
4	1		*BUMPER INTERNAL MOUNTING -CENTER	Deformed	150.00 F	*150.00 FL
5	2		*BUMPER LOWER REFECTOR	Not Necessary	200.00 F	*- FL
6	1		*REINFORCEMENT	Bent	850.00 F	*795.00 FL
7	1		*REINFORCEMENT TOP COVER GARNISH	Cracked	380.00 F	*304.00 FL
8	1		*REAR END TOP COVER	Not Necessary	290.00 F	*- FL
9	1		*EMBLEM	Necessary	145.38 F	*75.00 FL
10	1		*A200 LOGO	Necessary	158.36 F	*108.00 FL
11	1		*TAILGATE ASSY	Bent	2,500.00 F	*2,370.00 FL
12	1		*TAILGATE INTERNAL TRIM	Not Necessary	285.00 F	*- FL
13	1		*TAILGATE LOCK	Not Necessary	225.00 F	*- FL
14	2		*TAILGATE HINGES	Not Necessary	197.20 F	*- FL
15	2		*TAILGATE MOUNTING /STOPPER	Not Necessary	160.00 F	*- FL
16	1		*TAILGATE NUMBER PLATE LIGHT	Not Necessary	100.00 F	*- FL
17	1		*TAILGATE RUBBER GARNISH	Not Necessary	325.00 F	*- FL
18	1		*TAILLIGHT LEFT	Not Necessary	775.75 F	*- FL
19	1		*TAILLIGHT RIGHT	Not Necessary	775.75 F	*- FL
20	1		*LOWER LIP SILVING CHROME	Cracked	375.00 F	*250.00 FL
21	1		*LOWER LIP BASE	Deformed	616.00 F	*506.00 FL
22	2		*LOWER LIP BOTH SIDE JOINT COVER /EXHAUST BASE	Not Necessary	200.00 F	*- FL
23	1		*EXHAUST COVER SILVER COVER	N/S Bent / O/S Not Necessary	380.00 F	*190.00 FL
24	1		*TOW COVER	Not Necessary	80.00 F	*- FL
25	2		*REAR LIGHT SIDE COVER	Not Necessary	180.00 F	*- FL
26	2		*REAR LIGHT BRACKET	Not Necessary	280.00 F	*- FL
27	2		*REAR LIGHT SUPPORT BRACKET	Not Necessary	250.00 F	*- FL
28	1		*AUTO DOOR OPEN SENSOR WITH CABLE	Not Necessary	650.00 F	*- FL
29	1		*TAILGATE MIDDLE TRIM	Not Necessary	380.00 F	*- FL
30	1		*BUMPER DIFFUSER	Not Necessary	200.00 F	*- FL
31	10		*REAR BUMPER CLIPS	Necessary	100.00 FS	*50.00 FS
32	8		*REAR END LOWER PANEL TOP GARNISH CLIPS	Not Necessary	80.00 FS	*- FS
33	1		*REAR END LOWER PANEL SEALANT	Not Necessary	120.00 FS	*- FS
34	8		*REAR TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	80.00 FS	*- FS
35	8		*REAR TAILGATE OUTER GARNISH CLIPS	Not Necessary	80.00 FS	*- FS
36	12		*REAR LOWER LIP CLIPS	Necessary	100.00 FS	*30.00 FS
37	1		*TAILGATE MIDDLE TRIM CLIPS	Not Necessary	120.00 FS	*- FS
38	1		*REAR WINDSCREEN GLASS SEALANT	Not Necessary	120.00 FS	*- FS
39	8		*REAR WINDSCREEN GARNISH CLIPS	Not Necessary	80.00 FS	*- FS
40	1		*REAR WINDSCREEN RUBBER SEAL	Not Necessary	150.00 FS	*- FS
41	2		*REAR BUMPER REVERSE SENSOR	Not Working	600.00 FS	*400.00 FS
42	1		*REAR NO PLATE WITH GARNISH	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 15,608.44 6,581.32

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 0.00/10.00% (S\$)					0.00	610.13
Total Parts (S\$)					15,608.44	5,971.19

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACING ACCIDENT DAMAGES PARTS ,BUMPER ,LOWER LIP ,TAILGATE ,REAR END PANEL ,REINFORCEMENT ETC ,KNOCK JACK AND STRAIGHTEN ACCIDENT DAMAGES AREA	New	2,000.00	600.00
2	TO PUTTY AND SPRAY PAINTING FOR ACCIDENT AFFECTED DAMAGED AREA	New	1,500.00	700.00
3	CHECKING REAR WIRING AND LIGHTING SYSTEM FOR PROPER FUNCTION	New	120.00	50.00
4	CARRY UP BODY CAVITY PRESERVATION FOR AFFECTED AREA	New	200.00	0.00
5	REPLACING REAR UNDERCARRIAGE PARTS ,INCLUDING BLEEDING BRAKE SYSTEM	New	120.00	0.00
6	TO CARRY OUT REAR WHEEL BALANCING	New	100.00	0.00
7	TO CONDUCT WHEEL ALIGNMENT	New	120.00	0.00
8	REMOVING AND INSTALLING REAR BOOTLID COMPARTMENT GARNISH TRIMING ETC ,TO FACILITATE THE NECESSARY REPAIR WORK }	New	150.00	60.00
9	TRANSFERRING TAILGATE /BOOTLID LOCK MECHANISM ,TRIMING ETC }	New	120.00	0.00
10	TO CONDUCT CHASSIS ALIGNMENT	New	150.00	0.00
11	CHECKING CENTRAL LOCK SYSTEM FOR PROPER FUNCTION	New	120.00	0.00
12	REMOVING AND INSTALLING REAR EXHAUST MUFFLER ASSY TO FACILITATE THE NECESSARY REPAIR WORK	New	150.00	0.00
13	REMOVING AND INSTALL REAR CAMERA	New	100.00	0.00
14	PAINT PROTECTION FOR ACCIDENT AFFECTED AREA	New	500.00	0.00
15	WATER TEST AFTER ACCIDENT REPAIR BODY WORK	New	150.00	0.00
16	CARRU OUT DIAGNOSTIC CHECK INCLUDING CLEANING FAULTS CODE ,IF NECESSARY	New	120.00	120.00
17	LABOUR TO REMOVE AND INSTALL REAR CAMERA MODULE WHOLE SET	New	150.00	0.00
Gross Labour Cost (S\$)			5,870.00	1,530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >