



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 6240G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BONNET	DENTED	1,429.10	1,021.32
1	BONNET INNER RUBBER	NOT NECESSARY	66.50	-
1	BONNET LOGO	NECESSARY	90.00	66.20
1	BONNET LOCK	NOT NECESSARY	166.10	-
1	FRONT BUMPER	DEFORMED/TORN	651.10	648.10
1	FRONT BUMPER CENTRE GRILLE	NOT NECESSARY	133.10	-
2	FRONT BUMPER SIDE RETAINERS @\$69.00	NECESSARY	138.00	138.00
1	FRONT BUMPER REINFORCEMENT	DENTED	399.20	322.50
1	FRONT BUMPER SPONGE	TORN	268.00	135.10
1	FRONT GRILLE	CRACKED	485.10	472.80
2	HEADLAMPS @\$1645.10	CRACKED	3,290.20	2,420.20
1	FRONT BRACE PANEL	NOT NECESSARY	151.10	-
1	AIR CON CONDENSER	NOT NECESSARY	1,486.10	-
1	RADIATOR	NOT NECESSARY	1,866.10	-
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	745.10	-
1	FRONT SUPPORT PANEL TOP GARNISH	NOT NECESSARY	285.10	-
	LESS 25% DISCOUNT		-	-1,306.06
			11,649.90	3,918.16
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
1	FRONT BUMPER LICENCE PLATE (SN)	CRACKED	50.00	40.00
1	SET BONNET INSULATOR CLIPS (SN)	NOT NECESSARY	50.00	-
			150.00	90.00
<u>LABOUR</u>				
	TO CHECK WIRING.		50.00	20.00
	TO SPRAY RUST PROOFING.		80.00	30.00
	TO REFILL AIR CON GAS.	NOT NECESSARY	120.00	-
	TO RESET & REPROGRAMME SYSTEM.	NOT NECESSARY	180.00	-
	LABOUR FOR PANEL BEATING & REPLACED PARTS. INCLUSIVE OF THE REPAIR OF FRONT SUPPORT PANEL.		850.00	500.00

Report Ref No. CS/SMO22006632/Uvy3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY & SPRAY PAINTING.		1,080.00	600.00
			2,360.00	1,150.00
GRAND TOTAL			14,159.90	5,158.16
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,100.00

Report Ref No. CS/SMO22006632/Uvy3m4

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.