

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS22006636/EPA3Q2**Date:** 04/11/2022REFERENCE

Handling Insurer: Allianz Insurance Singapore Pte. Ltd. Policy No: SP2001891658
Claimant Vehicle No : SKX7507C **Insured Vehicle No :** SKC7177G
 Date of Loss: 26/06/2022 Nature of Claim: TP Claim No: 202222005394SL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKX7507C**
 Make & Model: NISSAN QASHQAI, 1.2 DIG-T CVT ABS 2WD 5DR (A) Engine No: HRA2208947A
 Reg. Date: 28/12/2015 (Man. Year: 2015) Chassis No: SJNFEAJ11U1533614
 Colour: Brown Odometer: 102735 km
 Engine Capacity: 1197 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/70 R16 Rear Tyre Size: 215/70 R16
 Front Left Side: Dunlop 4 mm Rear Left Side: Dunlop 4 mm
 Front Right Side: Dunlop 4 mm Rear Right Side: Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,401.00	3,578.50	1,822.50	33.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,880.00	1,440.00	440.00	23.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,281.00	5,018.50	2,262.50	31.07
+ GST 7.00/7.00% (S\$)	509.67	351.30	158.37	31.07
Nett Amount (S\$)	7,790.67	5,369.80	2,420.87	31.07
+ Loss of Use (5.0 x S\$50.00/day) (S\$)		250.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,627.25		

INSPECTION

Date of Assignment: 13/07/2022 Present Location: Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)
 Date Inspected: 18/07/2022 Inspected At: Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)
 Estimated Period of Repair: 5.0 days Blk 3 Pioneer Road North, #01-18 Singapore 628457

Adjuster: CHEN TSUE YEE**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 04 Nov 2022)

Parts: M1-SUV NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKX7507C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Not Necessary	35.00 FS	*- FS
2	1		*REAR BUMPER	Dented	420.00 F	*420.00 F
3	2		*REAR BUMPER RETAINER	Broken	50.00 F	*50.00 F
4	1		*REAR BUMPER TOWING COVER	Cut	25.00 F	*25.00 F
5	1		*REAR BUMPER SPONGE	Broken	95.00 F	*95.00 F
6	1		*REAR BUMPER REINFORCEMENT	Bent	320.00 F	*320.00 F
7	2		*REAR BUMPER REINFORCEMENT ARM	Bent	180.00 F	*180.00 F
8	1		*REAR END PANEL	Repair	330.00 F	*- F
9	10		*REAR BUMPER CLIP	Necessary	15.00 F	*15.00 F
10	1		*REAR TAILGATE	Dented	1,750.00 F	*1,750.00 F
11	1		*REAR TAILGATE CENTER GARNISH	Not Necessary	210.00 F	*- F
12	1		*REAR TAILGATE WEATHERSTRIPE	Not Necessary	110.00 F	*- F
13	1		*REAR TAILGATE EMBLEM	Not Necessary	45.00 F	*- F
14	1		*REAR TAILGATE QASHQAI LOGO	Necessary	60.00 F	*60.00 F
15	1		*REAR TAILGATE LAMP RH	Not Necessary	170.00 F	*- F
16	1		*REAR TAILLAMP RH	Not Necessary	210.00 F	*- F
17	1		*REAR WINDSCREEN MOULDING WITH GLASS	Not Necessary	550.00 F	*- F
18	1		*REAR WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
19	1		*REAR PARKING SENSOR	Broken	200.00 FS	*200.00 FS
Supplementary #1						
20	1		*REAR WINDSCREEN MOULDING	Necessary	120.00 F	*120.00 F

F=Franchise part. S=SpcNett.

Sub Total (S\$)	4,935.00	3,275.00
+ Margin on L,N Items 10.00/10.00% (S\$)	466.00	303.50
Total Parts (S\$)	5,401.00	3,578.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK,WELD,REMOVE & FIX ON ABOVE PARTS	New	850.00	660.00
2	TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS	New	800.00	600.00
3	TO CHECK WIRING	New	30.00	30.00
4	TO APPLY ANTI RUST COATING	New	80.00	30.00
5	TO REMOVE & FIX REAR WINDSCREEN	New	120.00	120.00
Gross Labour Cost (\$)			1,880.00	1,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >