

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	MS FIRST CAPITA	L INSURANCE LTD	Ref:	CS3/FCI22006637/Gcy3e2	
	36 ROBINSON RO SINGAPORE 0688	AD #16-01 CITY HOUSE 77	Date	9: 21/07/2022	
			Cod	e: FCI2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	GBK 8730S	Veh. Inspected	SND 2764D	
	Policy No.	D22099240	Coverage (\$)	0.00	
	Claim No.	D22002094MFCV	Excess (\$)	0.00	
	Assign From	AINI	Assign Date	13/07/2022	
2.	. Vehicle Particulars & Condition				
	Make & Model	B.M.W. 528I	c.c	1997	
	Engine No.	HIDDEN	Year of Reg.	2012	
	Chassis No.	WBAXG32030DX82731	Colour	BLUE	
	Odometer	105599 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	255/35Z R20	PIRELLI	6 mm	
	L/H Front Tyre	255/35Z R20	PIRELLI	6 mm	
	R/H Rear Tyre	255/35Z R20	PIRELLI	6 mm	
	L/H Rear Tyre	255/35Z R20	PIRELLI	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.				
5.	General Information				
	Accident Date	07/07/2022	Inspect Date / Time	13/07/2022 (03:30 PM)	
	Survey held at	8 KAKI BUKIT AVENUE 4 #03- 4	1/42 PREMIER @ KAK	I BU	
	Repairer	SAT (SG) PTE LTD			
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D)MARKET VALUE:\$38,000.00				

Report Ref No. CS3/FCI22006637/Gcy3e2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor