

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/GRB22006640/AQY3Q2**Date:** 01/09/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_01

Claimant Vehicle No : SJS645X **Insured Vehicle No :** SMM7769Y

Date of Loss: 09/07/2022 Nature of Claim: TP Claim No: MFL2022D0003633

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJS645X**

Make & Model: TOYOTA ESTIMA, 2.4 (A) Engine No: 2AZC603379

Reg. Date: 28/07/2009 (Man. Year: 2009) Chassis No: ACR500092175

Colour: Silver Odometer: 230938 km

Engine Capacity: 2362 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R19 Rear Tyre Size: 245/40 R19

Front Left Side: Habilead 6 mm Rear Left Side: Habilead 6 mm

Front Right Side: Habilead 6 mm Rear Right Side: Habilead 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,379.40	6,755.80	8,623.60	56.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,350.00	2,990.00	1,360.00	31.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,729.40	9,745.80	9,983.60	50.60
Approved Total (Overridden) (S\$)		7,800.00		
Nett Amount (S\$)	19,729.40	7,800.00	11,929.40	60.47

INSPECTION

Date of Assignment: 13/07/2022

Date Inspected: 13/07/2022 Inspected At:

Estimated Period of Repair: 7.0 days

2020 Spray Painting Pte Ltd (HQ)
53 UBI AVE 1, #05-15 PAYA UBI INDUSTRIAL
PARK
Singapore 408934

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 31 Aug 2022)
Parts:	M1-MPV	TOYOTA ESTIMA 2.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJS645X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Bent	30.00 FS	*30.00 FS
2	1		*REAR NUMBER PLATE HOLDER	Deformed	30.00 FS	*30.00 FS
3	2		*REAR NUMBER PLATE LAMP	Not Necessary	116.80 F	*- FL
4	1		*REAR BUMPER	Distorted	765.40 F	*765.40 FL
5	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
6	2		*REAR BUMPER SIDE HOLDER	Necessary	112.40 F	*112.40 FL
7	2		*REAR BUMPER SIDE SPONGE	Cracked	134.80 F	*134.80 FL
8	1		*REAR BUMPER REFLECTOR	N/S Cracked	133.80 F	*66.90 FL
9	2		*REAR BUMPER TOW COVER	Not Necessary	71.80 F	*- FL
10	1		*REAR END PANEL	Distorted	625.50 F	*625.50 FL
11	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
12	1		*REAR END PANEL TOP GARNISH	Deformed	272.60 F	*272.60 FL
13	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
14	1		*REAR END PANEL LOWER GARNISH	Deformed	198.40 F	*198.40 FL
15	1		*REAR END PANEL LOWER GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
16	2		*TAILLAMP	Cracked	794.20 F	*794.20 FL
17	2		*TAILLAMP PANEL	Repair	556.80 F	*- FL
18	1		*TAILGATE	Distorted	1,380.90 F	*1,380.90 FL
19	1		*TAILGATE LOCK	Damaged	371.50 F	*371.50 FL
20	1		*TAILGATE LOCK COVER	Deformed	55.40 F	*55.40 FL
21	1		*TAILGATE OUTER MOULDING	Cracked	296.80 F	*296.80 FL
22	1		*TAILGATE OUTER MOULDING CLIPS	Necessary	20.00 FS	*20.00 FS
23	1		*TAILGATE WEATHERSTRIPE	Cut	311.70 F	*311.70 FL
24	2		*TAILGATE DAMPER	Not Necessary	570.60 F	*- FL
25	1		*TAILGATE INNER TRIM BOARD	Cracked	455.50 F	*455.50 FL
26	1		*TAILGATE INNER TRIM BOARD CLIPS	Necessary	30.00 FS	*30.00 FS
27	1		*TAILGATE CENTRE REFLECTOR	Not Necessary	299.30 F	*- FL
28	2		*TAILGATE SIDE REFLECTOR	Cracked	675.60 F	*675.60 FL
29	1		*TAILGATE WIPER MOTOR	Not Necessary	591.60 F	*- FL
30	1		*TAILGATE GLASS MOULDING	Necessary	118.50 F	*118.50 FL
31	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
32	1		*REAR LH FENDER	Repair	1,211.70 F	*- FL
33	1		*REAR LH FENDER GLASS SEALANT	Not Necessary	40.00 FS	*- FS
34	2		*REAR FENDER INNER TRIM BOARD	Deformed	1,351.60 F	*1,351.60 FL
35	1		*REAR FENDER INNER TRIM BOARD CLIPS	Necessary	60.00 FS	*60.00 FS
36	1		*REAR FENDER JACK COVER	Cracked	206.70 F	*206.70 FL
37	1		*FLOOR PANEL	Repair	1,125.80 F	*- FL
38	1		*FLOOR PANEL SEALANT	Not Necessary	100.00 FS	*- FS
39	1		*FLOOR PANEL TOP COVER	Not Necessary	687.20 F	*- FL
40	1		*FLOOR PANEL SURROUND TRIM MAT	Not Necessary	556.50 F	*- FL
41	1		*FLOOR PANEL SURROUND TRIM MAT CLIPS	Not Necessary	50.00 FS	*- FS
42	1		*REAR CAMERA	Not Necessary	480.00 FS	*- FS
43	1		*REVERSE SENSOR	Damaged	280.00 FS	*250.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **15,379.40** **8,804.40**
- List Item Discount on L Items 0.00/25.00% (\$\$) 0.00 2,048.60

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	15,379.40
						6,755.80
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,800.00	1,250.00
2	SPRAY PAINTING	New	1,600.00	1,250.00
3	WIRING	New	50.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	50.00
5	TO REMOVE REAR CAMERA	New	100.00	50.00
6	TO REMOVE UPHOLSTERY	New	150.00	80.00
7	TO REMOVE TAILGATE GLASS	New	150.00	120.00
8	TO TRANSFER TAILGATE FITTINGS	New	150.00	80.00
9	TO SPRAY TUFF COAT	New	150.00	80.00
10	TO REMOVE REAR FENDER GLASS	New	100.00	0.00
Gross Labour Cost (\$\$)			4,350.00	2,990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >