

TP Grab
Xiao Chun.

SJS645X 2009 July
Toyota Estimate 2362 cc
ACRS00092175.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Reas	Number Plate	Bent	30(SN) ✓
Reas	Number Plate Holder	Deformed	30(SN) ✓
Reas	Number Plate Lamp x02	NH Ner	58.4 x 2 = 116.80 X
Reas	Bumper	Distorted	765.40 ✓
Reas	Bumper Clips	Ner	50(SN) 30(SN)
Reas	Bumper Side Holder x02	Ner	56.2 x 2 = 112.40 ✓
Reas	Bumper Side Sponge x02	ould	67.4 x 2 = 134.80 ✓
Reas	Bumper Reflector x02	LH ould	66.5 x 2 = 133.80 ^{66.50}
Reas	Bumper Tow Cover x02	NH ner	35.9 x 2 = 71.80 X
Reas	End Panel	Distorted	625.50 ✓
Reas	End Panel Sealant	Ner	60(SN) ✓
Reas	End Panel Top Garnish	Deformed	272.60 ✓
Reas	End Panel Top Garnish Clips	Ner	20(SN) ✓

SJS 645X.

Reer End Panel lower Garnish.	debond	198.40	✓
Reer End Panel lower Garnish Clips	new	20(SN)	✓
Taillamp x 02	cracked.	$397.1 \times 2 = 794.20$	✓
Taillamp Panel x 02.	Repair	$278.4 \times 2 = 556.80$	✓
Tailgate	Distorted	1380.90	✓
Tailgate Lock	Damaged	371.50	✓
Tailgate Lock Cover.	Debond	55.40.	✓
Tailgate Outer Moulding.	Cracked	296.80.	✓
Tailgate Outer Moulding Clips.	new	20(SN)	✓
Tailgate Weatherstripe.	At	311.70	✓
Tailgate Damper x 02	HP new	$285.3 \times 2 = 570.60$	✓
Tailgate Inner Trim Board.	Cracked	455.50.	✓
Tailgate Inner Trim Board clips.	new	30(SN)	✓

S JS 645X.

Tailgate Centre Reflector	Not Nec	299.30	+
Tailgate Side Reflector x 02	Cracked	$337.8 \times 2 = 675.60$	✓
Tailgate Wiper Motor	Not nec	591.60	+
Tailgate Glass Moulding.	} Nec	118.50	✓
Tailgate Glass Sealant.		60(SN)	✓
Rear LH Fender	Repairs	1211.70	+
Rear LH Fender Glass Sealant.	Not Nec	40(SN)	+
Rear Fender Inner Trim Board x 02	Deformed	$675.8 \times 2 = 1351.60$	✓
Rear Fender Inner Trim Board Clips.	Nec	60(SN)	✓
Rear Fender Jack Cover.	Cracked	206.70	✓
Floor Panel.	Repairs	1125.80	+
Floor Panel Sealant.	} Not Nec	100(SN)	+
Floor Panel Top Covers.		687.20	+

SJS 645X.

Floor Panel Surround Trim Mat ^{HP} ~~new~~ 556.50. X.

Floor Panel Surround Trim Mat Clips ^{HP} ~~new~~ 50(SN) X
8194.40 SN: 610.

Rear Camera. ^{HP} ~~new~~ 6145.80 480(SN) X.

Reverse Sensor ^{HP} ~~new~~ 280(SN) 250(SN) X.

Panel Beating

2990

~~1800~~ ~~1200~~ 1250

Spray Painting.

~~1600~~ ~~1200~~ 1250

Wiring.

total: 9745.80

t/s: 7.81c

~~50~~ 30

07 Days.

~~400~~ 50

To remove reverse sensor

~~140~~ 50

To remove rear camera.

~~150~~ 80

To remove upholstery.

~~150~~ 120

To remove tailgate g/s)

~~150~~ 80

To transfer tailgate fittings.

~~150~~ 80

To spray truck coat

100. X

To remove rear fender g/s)