

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG22006643/KQY3E2

Date: 17/08/2022

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001972858		
Claimant Vehicle No :	SMG1466S	Insured Vehicle No :	YN3662A		
Date of Loss:	09/07/2022	Nature of Claim:	TP	Claim No:	278979

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG1466S	Engine No:	LEB5613104
Make & Model:	HONDA FREED HYBRID, 1.5 G (A)	Chassis No:	GB71077450
Reg. Date:	05/12/2018 (Man. Year: 2018)	Odometer:	358070 km
Colour:	Metallic Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Windforce 8 mm	Rear Left Side:	Windforce 8 mm
Front Right Side:	Windforce 8 mm	Rear Right Side:	Windforce 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,553.44	2,237.32	2,316.12	50.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,050.00	1,290.00	760.00	37.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,603.44	3,527.32	3,076.12	46.58
Approved Total (Overridden) (S\$)		2,800.00		
(S\$)	6,603.44	2,800.00	3,803.44	57.60
+ GST 7.00/7.00% (S\$)	462.24	196.00	266.24	57.60
Nett Amount (S\$)	7,065.68	2,996.00	4,069.68	57.60

INSPECTION

Date of Assignment:	14/07/2022	Optima Werkz Pte Ltd (HQ)
Date Inspected:	14/07/2022 Inspected At:	10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK Autopoint
Estimated Period of Repair:	4.0 days	Singapore 568047

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Aug 2022)
Parts:	M1-MPV	HONDA FREED HYBRID 1.5 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMG1466S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	1,270.60 FL	*1,207.70 FL
2	1		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	82.50 FL	*82.50 FL
3	1		*REAR TAILGATE LOGO EMBLEM	Necessary	68.50 FL	*68.50 FL
4	1		*REAR TAILGATE FREED EMBLEM	Necessary	66.50 FL	*66.50 FL
5	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	78.20 FL	*78.20 FL
6	1		*REAR TAILGATE LAMP LH	Serviceable	396.20 FL	*- FL
7	1		*REAR TAILGATE LAMP RH	Serviceable	396.20 FL	*- FL
8	1		*REAR TAILGATE OUTER CHROME GARNISH	Serviceable	264.80 FL	*- FL
9	1		*REAR TAILGATE MECHANISM LOCK	Repair	136.20 FL	*- FL
10	1		*REAR TAILGATE INNER HANDLE COVER	Dented	54.70 FL	*54.70 FL
11	1		*REAR TAILGATE INNER TRIM BOARD	Serviceable	220.30 FL	*- FL
12	1		*REAR TAILGATE WEATHERSTRIP	Dented / Cut	126.70 FL	*126.70 FL
13	1		*REAR TAILLAMP LH (SCRATCHED)	Not Consistent With The Impact	427.60 FL	*- FL
14	1		*REAR TAILLAMP RH	Serviceable	427.60 FL	*- FL
15	1		*REAR BUMPER	Buckled	798.30 FL	*798.30 FL
16	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	34.80 FL	*- FL
17	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	34.80 FL	*- FL
18	1		*REAR END PANEL TOP GARNISH	Cracked	107.30 FL	*107.30 FL
19	1		*REAR END PANEL (NPA)	Repair	0.00 FL	*- FL
20	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
21	1		*REAR NUMBER PLATE WITH HOLDER	Cracked	50.00 FS	*45.00 FS
22	1		*REAR TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
23	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
24	1		*REAR BUMPER REVERSE SENSOR	No such part	300.00 FS	*- FS
25	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,551.80	2,755.40
- List Item Discount on L Items 20.00/20.00% (\$\$)	998.36	518.08
Total Parts (\$\$)	4,553.44	2,237.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST ACCIDENT AREAS	New	800.00	500.00
2	LABOUR CHARGES FOR PAINTING & FURNISHING MATERIALS AT ACCIDENT AREAS	New	800.00	600.00
3	LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS & ETC	New	150.00	120.00
4	LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS	New	120.00	50.00
5	LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC	New	100.00	0.00
6	TO CHECK WIRING & CENTRAL LOCKING SYSTEM & ETC	New	80.00	20.00
Gross Labour Cost (\$\$)			2,050.00	1,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >