

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22006649/GVY3E2

Date: 17/08/2022

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMB1SNW00015602100

**Claimant Vehicle
No :** SMY5558P

**Insured Vehicle
No :** PC9867B

Date of Loss: 12/07/2022

Nature of Claim: TP

Claim
No: SNM22D204841/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMY5558P**

Make & Model: MITSUBISHI OUTLANDER, 2.0 (A)

Engine No: 4J11DC3049

Reg. Date: 15/03/2021 (Man. Year: 2021)

Chassis No: GF7W0701192

Colour: Red

Odometer: 30175 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/55 R18

Rear Tyre Size: 225/55 R18

Front Left Side: Toyo 6 mm

Rear Left Side: Toyo 6 mm

Front Right Side: Toyo 6 mm

Rear Right Side: Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,073.00	3,483.00	3,590.00	50.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,740.00	5,390.00	3,350.00	38.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	15,813.00	8,873.00	6,940.00	43.89
+ GST 7.00/7.00% (S\$)	1,106.91	621.11	485.80	43.89
Nett Amount (S\$)	16,919.91	9,494.11	7,425.80	43.89

INSPECTION

Date of Assignment: 13/07/2022

Date Inspected: 15/07/2022 Inspected At:

CYCLE & CARRIAGE AUTOMOTIVE PTE LTD
(ubi)

330 UBI ROAD 3

Singapore 408650

Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

NOTE: VEHICLE CONVERT TO OD CLAIM

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$2,759.00 NETT)

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 17 Aug 2022)	
Parts: M1-SUV	MITSUBISHI OUTLANDER 2.0 (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SMY5558P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*MIVEC EMBLEM	Necessary	50.00 FS	*50.00 FS
2	1		*C&C BADGE	Necessary	50.00 FS	*50.00 FS
3	1		*SET REVERSE SENSOR	* Check	220.00 FS	*- FS
4	1		*REAR LICENSE PLATE WITH FRAME	Scratched	50.00 FS	*50.00 FS
5	1		*SUNDRIES	* Check	30.00 FS	*- FS
6	1		*GLASS, TAILGATE WINDOW	Necessary	664.00 FS	*664.00 FS
7	1		*UPR DAM, TAILGATE	Necessary	13.00 FS	*13.00 FS
8	1		*LWR DAM, TAILGATE	Necessary	24.00 FS	*24.00 FS
9	2		*SIDE DAM, TAILGATE	Necessary	48.00 FS	*48.00 FS
10	4		*FASTENER, WINDSHIELD	Necessary	24.00 FS	*24.00 FS
11	2		*STOPPER, WINDSHIELD GLASS	Necessary	6.00 FS	*6.00 FS
12	1		*LH RR OTR LAMP ASSY, COMB	* Check	615.00 FS	*- FS
13	1		*RH RR OTR LAMP ASSY, COMB	* Check	615.00 FS	*- FS
14	1		*LH INR LAMP ASSY, TAIL	* Check	444.00 FS	*- FS
15	1		*RH INR LAMP ASSY, TAIL	* Check	444.00 FS	*- FS
16	1		*GARNISH, TAILGATE	Repair	482.00 FS	*- FS
17	1		*MARK, OUTLANDER	Necessary	84.00 FS	*84.00 FS
18	1		*PANEL ASSY, TAILGATE	Buckled	999.00 FS	*999.00 FS
19	1		*FACE, RR BUMPER	Deformed	1,119.00 FS	*1,119.00 FS
20	1		*LH SIDE BRKT, R/BMPR FACE	Deformed	20.00 FS	*20.00 FS
21	1		*RH SIDE BRKT, R/BMPR FACE	Not Necessary	20.00 FS	*- FS
22	10		*CLIP, FR BUMPER	Necessary	40.00 FS	*40.00 FS
23	1		*EXTENSION, RR BUMPER	Deformed	292.00 FS	*292.00 FS
24	1		*LH REFLECTOR, TAIL LAMP	* Check	101.00 FS	*- FS
25	1		*RH REFLECTOR, TAIL LAMP	* Check	101.00 FS	*- FS
26	1		*ANT, KEYLESS OPERATION, RR	* Check	97.00 FS	*- FS
27	1		*BUZZER, KEYLESS OPERATIO, RR	* Check	92.00 FS	*- FS
28	1		*PANEL, RR END	Repair	329.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	7,073.00	3,483.00
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CARRY OUT DIAGNOSTIC CHECK AND REPROGRAM AFTER REPAIR	New	280.00	280.00
2	CHECK WIRING AND ELECTRICAL SYSTEMS	New	100.00	100.00
3	TO REMOVE & RE-INSTALL ALL CARPETS/TRIMMING TO FACILITATE REPAIR ON REAR ACCIDENT AFFECTED AREAS	New	640.00	320.00
4	TO TRANSFER TAILGATE COMPONENTS & MECHANISM PARTS	New	640.00	320.00
5	TO REMOVE & REPLACE TAILGATE GLASS & MOULDINGS	New	320.00	320.00
6	TO INSTALL RIKECOOL SOLAR FILM ON NEW TAILGATE GLASS	New	220.00	220.00
7	TO REPLACE LOGO, EMBLEM, TAILGATE & GARNISH, TAIL LAMPS, REAR BUMPER, EXTENSION BUMPER, CLIPS, BRACKETS, REFLECTOR LAMPS, ANTENNA, BUZZER, ETC. -TO CUT & WELD REAR END PANEL. STRAIGHTEN, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS	New	3,840.00	1,920.00
8	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS	New	2,200.00	1,650.00
9	TO REMOVE & REPLACE REVERSE SENSOR	New	100.00	80.00
10	TO APPLY ANTI CORROSION ON AFFECTED AREAS	New	100.00	80.00
11	TO APPLY GLASS SEALANT ON NEW TAILGATE GLASS	New	100.00	100.00
12	TO APPLY BODY SEALANT ON REPAIR & NEW PANELS	New	200.00	0.00
			Gross Labour Cost (\$\$)	8,740.00
				5,390.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >