



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

Ubi Customer Service Centre

CYCLE & CARRIAGE

330 Ubi Road 3, Singapore 408650 Tel: (65) 67461000 Fax: (65) 64875857



ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

| Invoice Name & Address | Owner Name & Vehicle Info |
|--|--|
| MALIM ARAFFIZ BIN JALANI | Cust No/Name KCV18929/MALIM ARAFFIZ BIN JALANI |
| BLK 70A TELOK BLANGAH HEIGHTS #20-513 SINGAPORE 101070 | Reg No/Reg Date SMY5558P / 15/03/202 |
| Contact No Mobile: 96574141 | Date In/Mileage 12/07/2022/ 29972 |
| | Chassis No GF7W0701192 |
| | Engine No 4J11DC3049 |
| | Make/Model MIT/20MY OUTLANDER 2.0 CVT MODERN (|
| | Colour/Trim P62 RED DIAMOND / BK BLACK |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No |
|------------|-------|-------------------|-----|---------------------------|--------|
| CTP00040 | Cash | 12/07/2022/ 15:54 | REN | 979 / Renemer Ramirez Bag | 10173 |

| Description of Goods / Services | Qty | Unit Price | Disc% | Amount |
|--|-----|------------|-------|--------------|
| Z TEXT ACCIDENT ON 12/07/2022 ALONG JUNC OF OLD AIRPORT RD & MOUNTBATTEN RD OWNER CLAIMING THIRD PARTY REQUIRED REPLACEMENT VEHICLE TP#: PC9867B TP INS: CHINA TAIPING | | | | |
| A 10028901 TO CARRY OUT DIAGNOSTIC CHECK AND REPROGRAM AFTER REPAIR | | | | 280.00 |
| A 54900099 CHECK WIRING AND ELECTRICAL SYSTEMS | | | | 100.00 |
| E PNT88000 TO REMOVE & RE-INSTALL ALL CARPETS/TRIMMING TO FACILITATE REPAIR ON REAR ACCIDENT AFFECTED AREAS | | | | 320 640.00 |
| E PNT88000 TO TRANSFER TAILGATE COMPONENTS & MECHANISM PARTS | | | | 320 640.00 |
| E PNT88000 TO REMOVE & REPLACE TAILGATE GLASS & MOULDINGS | | | | 320.00 |
| E PNT88000 TO INSTALL RIKECOOL SOLAR FILM ON NEW TAILGATE GLASS | | | | 220.00 |
| E PNT88000 TO REPLACE LOGO, EMBLEM, TAILGATE & GARNISH, TAIL LAMPS, REAR BUMPER, EXTENSION BUMPER, CLIPS, BRACKETS, REFLECTOR LAMPS, ANTENNA, BUZZER, ETC -TO CUT & WELD REAR END PANEL STRAIGHTEN, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS | | | | 1920 3840.00 |
| E PNT98000 SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS | | | | 1650 2200.00 |
| E PNT88000 TO REMOVE & REPLACE REVERSE SENSOR | | | | 80 100.00 |
| M SUNDRY TO APPLY ANTI CORROSION ON AFFECTED AREAS | | | | 80 100.00 |
| M SUNDRY TO APPLY GLASS SEALANT ON NEW TAILGATE GLASS | | | | 100.00 |
| M SUNDRY TO APPLY BODY SEALANT ON REPAIR & NEW PANELS | | | | 200.00 |

LKK Auto Consultants hence notify the Repairer of the following:
 (Resurvey before/after spray painting)
 • To display damaged parts during resurvey
 • Parts price list
 • Third party
 • No illegal
 • Supplier
 is subject
 and
 Finance Company

Acknowledged
 Signature:
 Date:

| | |
|--|--|
| Confirm & accepted by | |
| Authorized signatory and company stamp | |

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

Ubi Customer Service Centre

CYCLE & CARRIAGE

330 Ubi Road 3, Singapore 408650 Tel: (65) 67461000 Fax: (65) 64875857



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

| Invoice Name & Address | Owner Name & Vehicle Info |
|--|--|
| MALIM ARAFFIZ BIN JALANI | Cust No/Name KCV18929/MALIM ARAFFIZ BIN JALANI |
| BLK 70A TELOK BLANGAH HEIGHTS #20-513 SINGAPORE 101070 | Reg No/Reg Date SMY5558P / 15/03/202 |
| Contact No Mobile: 96574141 | Date In/Mileage 12/07/2022/ 29972 |
| | Chassis No GF7W0701192 |
| | Engine No 4J11DC3049 |
| | Make/Model MIT/20MY OUTLANDER 2.0 CVT MODERN (|
| | Colour/Trim P62 RED DIAMOND / BK BLACK |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No |
|------------|-------|-------------------|-----|---------------------------|--------|
| CTP00040 | Cash | 12/07/2022/ 15:54 | REN | 979 / Renemer Ramirez Bag | 10173 |

| Description of Goods / Services | Qty | Unit Price | Disc% | Amount |
|---|-------|------------|-------|---------|
| M SUNDRY | | | | 50.00 |
| TO SUPPLY MIVEC EMBLEM | | | | |
| M SUNDRY | | | | 50.00 |
| TO SUPPLY C & C BADGE | | | | |
| M SUNDRY | | | | 220.00 |
| TO SUPPLY ONE SET OF REVERSE SENSOR | | | | |
| M SUNDRY | | | | 50.00 |
| TO SUPPLY REAR LICENSE PLATE WITH FRAME | | | | |
| M SUNDRY | | | | 30.00 |
| SUNDRIES | | | | |
| M GLASS, TAILGATE WINDOW | 1.00 | 664.00 | 00.00 | 664.00 |
| M UPR DAM, TAILGATE | 1.00 | 13.00 | 00.00 | 13.00 |
| M LWR DAM, TAILGATE | 1.00 | 24.00 | 00.00 | 24.00 |
| M SIDE DAM, TAILGATE | 2.00 | 24.00 | 00.00 | 48.00 |
| M FASTENER, WINDSHIELD | 4.00 | 6.00 | 00.00 | 24.00 |
| M STOPPER, WINDSHIELD GLASS | 2.00 | 3.00 | 00.00 | 6.00 |
| M LH RR OTR LAMP ASSY, COMB | 1.00 | 615.00 | 00.00 | 615.00 |
| M RH RR OTR LAMP ASSY, COMB | 1.00 | 615.00 | 00.00 | 615.00 |
| M LH INR LAMP ASSY, TAIL | 1.00 | 444.00 | 00.00 | 444.00 |
| M RH INR LAMP ASSY, TAIL | 1.00 | 444.00 | 00.00 | 444.00 |
| M GARNISH, TAILGATE | 1.00 | 482.00 | 00.00 | 482.00 |
| M MARK, OUTLANDER | 1.00 | 84.00 | 00.00 | 84.00 |
| M PANEL ASSY, TAILGATE | 1.00 | 999.00 | 00.00 | 999.00 |
| M FACE, RR BUMPER | 1.00 | 1119.00 | 00.00 | 1119.00 |
| M LH SIDE BRKT, R/BMPR FACE | 1.00 | 20.00 | 00.00 | 20.00 |
| M RH SIDE BRKT, R/BMPR FACE | 1.00 | 20.00 | 00.00 | 20.00 |
| M CLIP, FR BUMPER | 10.00 | 4.00 | 00.00 | 40.00 |
| M EXTENSION, RR BUMPER | 1.00 | 292.00 | 00.00 | 292.00 |
| M LH REFLECTOR, TAIL LAMP | 1.00 | 101.00 | 00.00 | 101.00 |
| M RH REFLECTOR, TAIL LAMP | 1.00 | 101.00 | 00.00 | 101.00 |
| M ANT, KEYLESS OPERATION, RR | 1.00 | 97.00 | 00.00 | 97.00 |
| M BUZZER, KEYLESS OPERATIO, RR | 1.00 | 92.00 | 00.00 | 92.00 |
| M PANEL, RR END | 1.00 | 329.00 | 00.00 | 329.00 |

Estimate

Confirm & accepted by

SURVEYOR NAME: Gua Qiao

SURVEYOR SIGNATURE: [Signature]

DATE: 15/7/2022

REMARKS: 6 Days before print photos

Authorized signatory and company stamp

| | |
|---------------|-----------|
| Nett | 15,813.00 |
| 7% GST on | 1106.91 |
| Total Payable | 16,919.91 |

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.