

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS22006653/UCY3E2

Date: 08/08/2022

REFERENCE

Handling Insurer: ECICS Limited Policy No: MPC22A00010701
Claimant Vehicle No : SLF9934Y **Insured Vehicle No :** SLA819H
Date of Loss: 09/07/2022 Nature of Claim: TP Claim No: DMPC2200290H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLF9934Y**
Make & Model: TOYOTA WISH, 1.8 CVT (A) Engine No: 2ZR1830755
Reg. Date: 19/06/2016 (Man. Year: 2016) Chassis No: JTDGG20WX0J005033
Colour: Grey Odometer: 131691 km
Engine Capacity: 1798 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,037.20	1,390.37	8,646.83	86.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,630.00	1,610.00	2,020.00	55.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,667.20	3,000.37	10,666.83	78.05
Approved Total (Overridden) (S\$)		2,400.00		
Nett Amount (S\$)	13,667.20	2,400.00	11,267.20	82.44

INSPECTION

Date of Assignment: 13/07/2022
Date Inspected: 14/07/2022 Inspected At: Asia Motorsports-kaki Bukit (HQ)
15 KAKI BUKIT ROAD 4 #01-05/53 BARTLEY BIZ CENTRE
Singapore 417808
Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Aug 2022)
Parts:	M1-MPV	TOYOTA WISH 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLF9934Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Dented / Deformed	1,016.40 FL	*645.30 FL
2	1		*REAR BUMPER LEFT REFLECTOR	Not Necessary	137.10 FL	*- FL
3	1		*REAR BUMPER RIGHT REFLECTOR	Not Necessary	137.10 FL	*- FL
4	2		*REAR BUMPER SIDE RETAINER (LONG)	Necessary	136.30 FL	*136.30 FL
5	2		*REAR BUMPER SIDE RETAINER (SHORT)	Necessary	133.20 FL	*133.20 FL
6	1		*REAR BUMPER LEFT BRACKET	Not Necessary	68.60 FL	*- FL
7	1		*REAR BUMPER RIGHT BRACKET	Not Necessary	68.60 FL	*- FL
8	1		*REAR TAILGATE ASSY	Repair	1,460.80 FL	*- FL
9	1		*REAR TAILGATE CENTRE LOGO	Necessary	68.80 FL	*68.80 FL
10	1		*REAR TAILGATE INNER TRIM BOARD	Not Necessary	485.50 FL	*- FL
11	1		*REAR TAILGATE OUTER CHROME GARNISH	Not Necessary	218.60 FL	*- FL
12	1		*REAR TAILGATE LOCK MECHANISM	Not Necessary	178.60 FL	*- FL
13	1		*REAR TAILGATE LOCK CATCH	Not Necessary	65.60 FL	*- FL
14	1		*REAR TAILGATE LOCK SENSOR	Cracked	348.10 FL	*348.10 FL
15	1		*REAR TAILGATE INNER PULL POCKET	Not Necessary	89.70 FL	*- FL
16	1		*REAR TAILGATE WEATHERSTRIP	Twisted	188.80 FL	*188.80 FL
17	2		*REAR TAILGATE HINGES	Not Necessary	143.60 FL	*- FL
18	2		*REAR TAILGATE DAMPERS	Not Necessary	173.30 FL	*- FL
19	2		*REAR NO PLATE LAMP	Not Necessary	110.20 FL	*- FL
20	1		*REAR WINDSCREEN GLASS MOULDING	Not Necessary	280.20 FL	*- FL
21	1		*REAR LEFT TAILLAMP	Not Necessary	440.50 FL	*- FL
22	1		*REAR RIGHT TAILLAMP	Not Necessary	440.50 FL	*- FL
23	1		*REAR TAILGATE LEFT TAILLAMP	Not Necessary	336.20 FL	*- FL
24	1		*REAR TAILGATE RIGHT TAILLAMP	Not Necessary	336.20 FL	*- FL
25	1		*REAR END PANEL	Repair	670.30 FL	*- FL
26	1		*REAR END PANEL TOP GARNISH	Not Necessary	296.50 FL	*- FL
27	1		*REAR END PANEL INNER GARNISH	Not Necessary	190.50 FL	*- FL
28	1		*REAR EXHAUST MUFFLER ASSY	Not Necessary	1,287.90 FL	*- FL
29	2		*REAR EXHAUST MUFFLER RUBBER MOUNTING	Not Necessary	66.10 FL	*- FL
30	1		*REAR LEFT FENDER INNER TRIM	Not Necessary	494.60 FL	*- FL
31	1		*REAR RIGHT FENDER INNER TRIM	Not Necessary	494.60 FL	*- FL
32	1		*REAR SPARE TYRE BRACKET HOLDER	Not Necessary	180.90 FL	*- FL
33	1		*REAR WIPER MOTOR	Not Necessary	398.70 FL	*- FL
34	1		*REAR WIPER BLADE ASSY	Not Necessary	170.80 FL	*- FL
35	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	256.20 FL	*- FL
36	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*50.00 FS
37	1		*REAR NO PLATE WITH GARNISH	Not Necessary	100.00 FS	*- FS
38	4		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	40.00 FS	*- FS
39	1		*REAR END PANEL SEALANT	Not Necessary	140.00 FS	*- FS
40	1		*REAR WINDSCREEN GLASS SEALANT	Not Necessary	100.00 FS	*- FS
41	8		*REAR TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
42	4		*REAR TAILGATE OUTER CHROME GARNISH CLIPS	Not Necessary	40.00 FS	*- FS
43	2		*REAR BUMPER REVERSE SENSOR	Shorted	300.00 FS	*200.00 FS
44	1		*SET REAR LEFT FENDER INNER TRIM CLIPS	Not Necessary	40.00 FS	*- FS
45	1		*SET REAR RIGHT FENDER INNER TRIM CLIPS	Not Necessary	40.00 FS	*- FS
46	1		*REAR VIEW CAMERA	Not Necessary	450.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					12,929.60	1,770.50
- List Item Discount on L Items 25.00/25.00% (S\$)					2,892.40	380.13
Total Parts (S\$)					10,037.20	1,390.37

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN REAR AFFECTED AREA AND REPLACE REAR DAMAGED PARTS	New	1,200.00	850.00
2	TO PUTTY AND SPRAY PAINTING REAR PORTION	New	1,200.00	600.00
3	TO CHECK REAR LIGHTING AND WIRING	New	50.00	30.00
4	TO REMOVE AND INSTALL REAR TAILGATE LOCK MECHANISM	New	80.00	0.00
5	TO REMOVE AND INSTALL REAR EXHAUST MUFFLER ASSY	New	120.00	0.00
6	TO REPAIR STRAIGHTEN AND ALIGN BOTH REAR FENDER ASSY	New	300.00	0.00
7	TO REMOVE AND INSTALL REAR INNER GARNISH AND TRIM TO FACILITATE THE REPAIR	New	140.00	80.00
8	TO APPLY ANTI RUST PROOFING TO REAR AFFECTED AREA	New	140.00	0.00
9	TO REMOVE AND INSTALL REAR BUMPER REVERSE SENSOR	New	80.00	50.00
10	TO REMOVE AND INSTALL REAR WINDSCREEN GLASS TO FACILITATE THE REPAIR	New	140.00	0.00
11	TO REMOVE AND INSTALL REAR VIEW CAMERA	New	80.00	0.00
12	TOWING SERVICE	New	100.00	0.00
Gross Labour Cost (\$)			3,630.00	1,610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >