



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2207308

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 25/11/2022
Reference CC3/CTI22006657/Tpa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SH 7079K
Insured Veh. SCW 8886B
Claim No. SNM22D204401/C02
Policy No. DMPCSNW00105652201
Accident Date 21/06/2022
Inspection Date 22/06/2022

| Description | Total |
|--------------------------------|---------------|
| Third Party Express Settlement | 400.00 |
| Subtotal | 400.00 |
| GST (7%) | 28.00 |
| Grand Total | 428.00 |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|---|--|-----------------|--|--|
| CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909 | | | Ref: CC3/CTI22006657/Tpa3q2 Date: 25/11/2022 Code: CTI | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | SCW 8886B | Veh. Inspected | SH 7079K | |
| Policy No. | DMPCSNW00105652201 | Coverage (\$) | 0.00 | |
| Claim No. | SNM22D204401/C02 | Excess (\$) | 0.00 | |
| Assign From | | Assign Date | 22/06/2022 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | HYUNDAI I40 | c.c | 1685 | |
| Engine No. | HIDDEN | Year of Reg. | 2016 | |
| Chassis No. | KMHLB41UMGU087053 | Colour | BLUE | |
| Odometer | 638261 KM | Steering | IN ORDER | |
| Brakes | IN ORDER | Modification | NIL | |
| General | GOOD | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | 205/60 R16 | WEST LAKE | 6 mm | |
| L/H Front Tyre | 205/60 R16 | WEST LAKE | 6 mm | |
| R/H Rear Tyre | 205/60 R16 | WEST LAKE | 6 mm | |
| L/H Rear Tyre | 205/60 R16 | WEST LAKE | 6 mm | |
| 4. Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. | | | | |
| 5. General Information | | | | |
| Accident Date | 21/06/2022 | Inspection Date | 22/06/2022 | |
| Survey held at | COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969 | | | |
| 5a. Remarks | | | | |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. Estimate Days of Repair | | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | 2 Working Days | | |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 7079K

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|---|--|----------------------|---------------------------|-------------------|
| | <u>REPLACEMENT OF PARTS</u> | | | |
| 1 | COVER ASSY -RR BUMPER | DEFORMED | 553.00 | 553.00 |
| 1 | COVER -RR BUMPER LWR | TO REPAIR SEE LABOUR | 228.00 | - |
| 1 | ABSORBER -RR BUMPER ENERGY | NOT NECESSARY | 119.50 | - |
| 1 | BEAM -RR BUMPER | NOT NECESSARY | 428.40 | - |
| 10 | BUMPER COVER CLIP REAR | NECESSARY | 22.00 | 22.00 |
| | LESS 20% DISCOUNT | | -270.18 | -115.00 |
| | | | 1,080.72 | 460.00 |
| | <u>SPECIAL NETT ITEMS</u> | | | |
| 1 | PROTECTOR MAT (SN) | NECESSARY | 50.00 | 50.00 |
| 1 | LOGO REAR BUMPER (SN) | NECESSARY | 50.00 | 50.00 |
| 1 | LOGO FENER (SN) | NECESSARY | 200.00 | 200.00 |
| | | | 300.00 | 300.00 |
| | <u>LABOUR</u> | | | |
| | PANEL BEATING.INCLUSIVE OF THE REPAIR OF COVER - RR BUMPER LWR . | | 300.00 | 280.00 |
| | SPRAYPAINT CHARGE. | | 300.00 | 250.00 |
| | REMOVE/REFIX REVERSE SENSOR . | | 50.00 | 30.00 |
| | | | 650.00 | 560.00 |
| GRAND TOTAL | | | 2,030.72 | 1,320.00 |
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | | 1,050.00 |

Report Ref No. CC3/CTI22006657/Tpa3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SH 7079K

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SH 7079K

RE-INSPECTION

