

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	INDIA INTERNATION	ONAL INSURANCE PL	Re	ef:	CS3/III21006896/Bvy3e2-1	
	64 CECIL STREET #05-02 IOB BUILD	ING SINGAPORE 049711	Da	ate:	01/08/2022	
			Co	ode:	III2	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SMX 3423M	Veh. Inspected		SGN 3468H	
	Policy No.	D20MFL0007747	Coverage (\$)		0.00	
	Claim No.	MFL2021D0002578	Excess (\$)		0.00	
	Assign From	CARINE KEK	Assign Date		14/07/2022	
2.	Vehicle Particulars & Condition					
	Make & Model	TOYOTA COROLLA ALTIS	c.c		1598	
	Engine No.	HIDDEN	Year of Reg.		2006	
	Chassis No.	MR053ZEC107136342	Colour		SILVER	
	Odometer	-	Steering		IN ORDER	
	Brakes	JAMMED	Modification		SPORTS RIM	
	General	POOR				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	185/70 R14	YOKOHAMA		5 mm	
	L/H Front Tyre	185/70 R14	YOKOHAMA		5 mm	
	R/H Rear Tyre	185/70 R14	YOKOHAMA		5 mm	
	L/H Rear Tyre	185/70 R14	YOKOHAMA		5 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S, N/S BODY AND FRONT PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	15/06/2021	Inspection Date		22/06/2021	
	Survey held at	GUAN AUTO SERVICE	•			
		BLK12 #01-59 SIN MING INDUSTRIAL ESTATE SECTOR B SINGAPORE 575656				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORI	ESTIMATED NORMAL PERIOD FOR REPAIR: 13 Working Days				