

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)  
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
 Singapore 408933  
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI22006666/UVY3Q2  
**Date:** 19/10/2022

### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SNW00008382201
Claimant Vehicle No :	FBM6030G	Insured Vehicle No :	PA7702S
Date of Loss:	08/07/2022	Nature of Claim:	TP
		Claim No:	SNM22D204802/C02/TANCHC

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBM6030G	Engine No:	M312M23461
Make & Model:	PIAGGIO VESPA GT200A, 198cc	Chassis No:	ZAPM3120000022350
Reg. Date:	08/03/2005 (Man. Year: 2004)	Odometer:	1588 km
Colour:	Grey		
Engine Capacity:	198 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	120/70-12	Rear Tyre Size:	130/70-12
Front Left Side:	Maxxis 6 mm	Rear Left Side:	Maxxis 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,624.90	2,513.30	5,111.60	67.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,110.00	1,250.00	860.00	40.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>9,734.90</b>	<b>3,763.30</b>	<b>5,971.60</b>	<b>61.34</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,000.00</b>		
<b>Nett Amount (S\$)</b>	<b>9,734.90</b>	<b>3,000.00</b>	<b>6,734.90</b>	<b>69.18</b>

### INSPECTION

Date of Assignment:	14/07/2022	
Date Inspected:	14/07/2022	Inspected At: Erofia Motor Trading Pte Ltd (KAKI BUKIT) 1 KAKI BUKIT AVE 6 #02-62 Singapore 417883
Estimated Period of Repair:	5.0 days	

**Adjuster:** MARCUS CHUA

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 19 Oct 2022)	
<b>Parts:</b>	N/A	PIAGGIO VESPA GT200A 198cc (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FBM6030G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Dented / Bent	225.00 FL	*182.00 FL
2	1		*FRONT FORK ASSY	Not Necessary	980.00 FL	*- FL
3	1		*FRONT SHOCK ABSORBER	Not Necessary	310.00 FL	*- FL
4	1		*METER ASSY (Cracked)	Not Consistent With The Impact	920.00 FL	*- FL
5	1		*TOP COVER (CRACKED)	Not Consistent With The Impact	328.00 FL	*- FL
6	1		*TOP INNER COVER	Not Necessary	328.00 FL	*- FL
7	1		*SET FRONT COWLING MOULDINGS	Cut	250.00 FL	*200.00 FL
8	1		*FRONT INNER COMPARTMENT	Cut	680.00 FL	*680.00 FL
9	1		*SET SIDE MIRROR	Cut	310.00 FL	*155.00 FL
10	1		*HANDLE BAR	Not Necessary	320.00 FL	*- FL
11	1		*SET HAND GRIP	Not Necessary	90.00 FL	*- FL
12	1		*SET HANDLE BAR BALANCER	Not Necessary	160.00 FL	*- FL
13	1		*BRAKE LEVER (N/S)	Cut	300.00 FL	*110.00 FL
14	1		*FOOTSTEP PANEL	Repair	685.00 FL	*- FL
15	1		*RIDER FOOTSTEP REAR COVER	Cut	145.00 FL	*145.00 FL
16	1		*ENGINE COVER	Cut	650.00 FL	*450.00 FL
17	1		*ENGINE COVER CHROME	Cut	190.00 FL	*190.00 FL
18	1		*SIDE STAND	Repair	145.00 FL	*- FL
19	1		*MAIN STAND	Cracked	225.00 FL	*225.00 FL
20	1		*NUMBER PLATE	Frt Necessary	38.00 FS	*10.00 FS
21	1		*SET STEERING CONE	Not Necessary	120.00 FS	*- FS
22	1		*REAR BOX	Cut	650.00 FS	*400.00 FS
23	1		*REAR BOX BRACKET	Not Necessary	180.00 FS	*- FS
24	1		*VESPA EMBLEM	Not fitted	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>8,349.00</b>	<b>2,747.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	724.10	233.70
<b>Total Parts (\$\$)</b>	<b>7,624.90</b>	<b>2,513.30</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
2	TO PROVIDE LABOUR	New	480.00	250.00
3	TO REPAIR BODY FRAME	New	550.00	400.00
4	TO RESPRAY PAINTING	New	1,000.00	600.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,110.00</b>	<b>1,250.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >