



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMN 6893Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	595.00	481.50
1	REAR BUMPER REINFORCEMENT	CRACKED	320.00	294.80
1	REAR BUMPER LOWER GARNISH	DENTED	688.00	451.00
2	REAR BUMPER SENSOR @\$227.00	SERVICEABLE	454.00	-
8	REAR BUMPER CLIP @\$5.50	NECESSARY	44.00	44.00
4	REAR BUMPER INNER SUPPORT BRACKET @\$25.00	NOT NECESSARY	100.00	-
2	REAR NUMBER PLATE LAMP @\$38.00	NOT NECESSARY	76.00	-
	LESS 20% DISCOUNT		-455.40	-254.26
			1,821.60	1,017.04
	<u>SPECIAL NETT ITEMS</u>			
1	REAR NUMBER PLATE (SN)	BENT	50.00	40.00
			50.00	40.00
	<u>LABOUR</u>			
	PANEL BEATING.		650.00	250.00
	CHECK WIRING.		60.00	20.00
	RUST PROOFING.	NOT NECESSARY	60.00	-
	TO REMOVE & REPLACE REAR BUMPER SENSOR.		80.00	40.00
	TO SPRAY PAINTING.		580.00	300.00
			1,430.00	610.00
	GRAND TOTAL		3,301.60	1,667.04
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,300.00

Report Ref No. CS/AGI22006667/Ucy3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.