

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22006668/UVY3M4**Date:** 01/08/2022**REFERENCE**Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMHCSNW00002972200

**Claimant Vehicle  
No :** SLF929Y**Insured Vehicle  
No :** SMY5087G

Date of Loss: 11/07/2022

Nature of Claim: TP

Claim  
No: SNM22D204822C02/IRENE**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SLF929Y**

Make &amp; Model: SUBARU FORESTER, 2.0 (A)

Engine No: FB20Y187862

Reg. Date: 13/08/2016 (Man. Year: 2016)

Chassis No: JF1SJ5KC5GG066223

Colour: Grey

Odometer: 110211 km

Engine Capacity: 1995 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 235/55 R18

Rear Tyre Size: 235/55 R18

Front Left Side: Bridgestone 7 mm

Rear Left Side: Bridgestone 7 mm

Front Right Side: Bridgestone 7 mm

Rear Right Side: Bridgestone 7 mm

*The above values represent the remaining tyre tread depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	10,482.20	4,507.68	5,974.52	57.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,760.00	1,780.00	980.00	35.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>13,242.20</b>	<b>6,287.68</b>	<b>6,954.52</b>	<b>52.52</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,000.00</b>		
<b>(S\$)</b>	13,242.20	5,000.00	8,242.20	62.24
<b>+ GST 7.00/7.00% (S\$)</b>	926.95	350.00	576.95	62.24
<b>Nett Amount (S\$)</b>	<b>14,169.15</b>	<b>5,350.00</b>	<b>8,819.15</b>	<b>62.24</b>

**INSPECTION**

Date of Assignment: 14/07/2022

Date Inspected: 14/07/2022

Inspected At:

Tan Lim Motor Pte Ltd (Defu)  
1 Defu Lane 6  
Singapore 539365

Estimated Period of Repair: 5.0 days

**Adjuster:** MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 01 Aug 2022)
<b>Parts:</b>	M1-SUV	SUBARU FORESTER 2.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLF929Y)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER SPOT LAMP @\$280.00	N/s Cracked/ O/s Not Necessary	560.00 FL	*280.00 FL
2	1	*FRONT BUMPER SPOT LAMP CHROME @\$60.00	N/s Cracked/ O/s Not Necessary	120.00 FL	*60.00 FL
3	4	*FRONT BUMPER SPOT LAMP CLIP @\$5.00	Not Necessary	20.00 FL	*- FL
4	1	*FRONT BUMPER SIDE RETAINER @\$26.00	N/s Cracked/ O/s Not Necessary	52.00 FL	*26.00 FL
5	1	*FRONT BUMPER NOZZLE N/S	Cracked	140.00 FL	*140.00 FL
6	1	*FRONT BUMPER LOWER COVER	Torn	216.00 FL	*216.00 FL
7	1	*FRONT BUMPER TOW HOOK COVER N/S	Missing	16.00 FL	*16.00 FL
8	1	*HEADLAMP ASSY @\$2007.00	N/s Holder Cracked (1Piece)	4,014.00 FL	*2,007.00 FL
9	1	*HEADLAMP LOWER BRACKET @\$85.00	N/s Cracked/ O/s Not Necessary	170.00 FL	*85.00 FL
10	1	*WASHER TANK	Deformed	258.00 FL	*258.00 FL
11	1	*RADIATOR GRILLE ASSY	Cracked	987.00 FL	*325.40 FL
12	1	*AIR-CON CONDENSOR	Not Necessary	998.00 FL	*- FL
13	1	*BONNET LOCK TOP	Not Necessary	64.00 FL	*- FL
14	1	*FRONT SUPPORT PANEL ASSY	Bent	584.00 FL	*584.00 FL
15	1	*FRONT BUMPER	Distorted	780.00 FL	*594.20 FL
16	1	*FRONT BUMPER REINFORCEMENT	Dented	288.00 FL	*288.00 FL
17	1	*BONNET	Repair	876.00 FL	*- FL
18	1	*FRONT FENDER N/S	Buckled	580.00 FL	*580.00 FL
19	1	*FRONT FENDER INNER COWLING N/S	Torn	125.00 FL	*125.00 FL
20	1	*FRONT BUMPER LOWER COVER	Repeated	210.00 FL	*- FL
21	1	*SET FRONT BUMPER PARKING SENSOR	Not fitted	480.00 FS	*- FS
22	1	*FRONT LICENCE PLATE	Scratched	50.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>11,588.00</b>	<b>5,624.60</b>
<b>- List Item Discount on L Items 10.00/20.00% (\$)</b>	1,105.80	1,116.92
<b>Total Parts (\$)</b>	<b>10,482.20</b>	<b>4,507.68</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REINSTALL OF FRONT BUMPER PARKING SENSOR	New	80.00	0.00
2	TO RUST-PROOFING OF THE AFFECTED AREAS	New	200.00	60.00
3	TO DISMANTLE AIR-CON ASSY, REMOVE AND RENEWAL OF PARTS, VACUUM AND CHARGE-IN GAS	New	140.00	100.00
4	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	60.00	20.00
5	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	80.00	0.00
6	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	1,000.00	600.00
7	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,200.00	1,000.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,760.00</b>	<b>1,780.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >