

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22006674/AVY3Q2**Date:** 19/09/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNA00015662101

Claimant Vehicle No : SMS1599D **Insured Vehicle No :** SMY4310T

Date of Loss: 12/07/2022 Nature of Claim: TP Claim No: SNM22D204843/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMS1599D**

Make & Model: KIA CARENS, 1.7 D DCT DIESEL 5DR FWD (A) Engine No: D4FDHH105841

Reg. Date: 05/06/2017 (Man. Year: 2017) Chassis No: KNAHU815VH7182986

Colour: Blue Odometer: 106709 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17

Front Left Side: Tourador 6 mm Rear Left Side: Tourador 6 mm

Front Right Side: Tourador 6 mm Rear Right Side: Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,084.80	8,242.10	8,842.70	51.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,790.00	2,180.00	3,610.00	62.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	22,874.80	10,422.10	12,452.70	54.44
Approved Total (Overridden) (\$\$)		8,300.00		
Nett Amount (\$\$)	22,874.80	8,300.00	14,574.80	63.72

INSPECTION

Date of Assignment: 14/07/2022

Date Inspected: 14/07/2022 Inspected At: JL Perfect Autowork Pte Ltd (HQ)
8 Kaki Bukit Avenue 4, #08-09 Premier@Kaki
Bukit
Singapore 415875

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Sep 2022)
Parts:	M1-MPV	KIA CARENS 1.7 D DCT DIESEL 5DR FWD (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMS1599D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER (UPPER)	Distorted	598.00 FL	*598.00 FL
2	1		*REAR BUMPER (LOWER)	Distorted	387.00 FL	*387.00 FL
3	1		*REAR BUMPER DIFFUSER	Distorted	288.00 FL	*288.00 FL
4	2		*REAR BUMPER LAMP	Cracked	232.00 FL	*232.00 FL
5	2		*REAR BUMPER SIDE INNER GARNISH	Torn	306.00 FL	*306.00 FL
6	1		*REAR BUMPER TOWING COVER	Missing	20.00 FL	*20.00 FL
7	4		*REAR BUMPER SENSOR	Damaged (3 PCS ONLY)	748.00 FL	*561.00 FL
8	4		*REAR BUMPER SENSOR HOLDER	Necessary	144.00 FL	*144.00 FL
9	1		*REAR BUMPER SENSOR WIREHARNES	Not Necessary	348.00 FL	*- FL
10	5		*REAR BUMPER BRACKET	Damaged	105.00 FL	*105.00 FL
11	2		*REAR BUMPER SIDE RETAINER	Necessary	78.00 FL	*78.00 FL
12	2		*REAR BUMPER MUDFLAP	Not Necessary	330.00 FL	*- FL
13	1		*REAR BUMPER REINFORCEMENT	Distorted	428.00 FL	*428.00 FL
14	2		*REAR BUMPER REINFORCEMENT BRACKET	Dented	304.00 FL	*304.00 FL
15	1		*TAILGATE	Dented	1,088.00 FL	*1,088.00 FL
16	2		*TAILGATE LAMP	Not Necessary	486.00 FL	*- FL
17	1		*TAILGATE LOGO	Necessary	76.00 FL	*76.00 FL
18	1		*TAILGATE EMBLEM CARENS	Necessary	64.00 FL	*64.00 FL
19	1		*TAILGATE EMBLEM LIMITED EDITION	Necessary	86.00 FL	*86.00 FL
20	1		*TAILGATE EMBLEM CROI	Necessary	59.00 FL	*59.00 FL
21	1		*TAILGATE EMBLEM TURBO	Necessary	66.00 FL	*66.00 FL
22	1		*TAILGATE DETECTOR	Cracked	346.00 FL	*195.00 FL
23	1		*TAILGATE DETECTOR WIRE HARNESS	Not Necessary	259.00 FL	*- FL
24	2		*TAILGATE STOPPER	Not Necessary	28.00 FL	*- FL
25	1		*TAILGATE LOCK CATCH	Not Necessary	19.00 FL	*- FL
26	1		*TAILGATE WEATHERSTRIP	Cut	168.00 FL	*168.00 FL
27	2		*TAILLAMP	Cut	794.00 FL	*794.00 FL
28	2		*REAR FENDER INNER COWLING	Not Necessary	448.00 FL	*- FL
29	1		*REAR FENDER INNER TRIM	O/S Cracked	948.00 FL	*365.00 FL
30	1		*REAR END PANEL	Dented	594.00 FL	*594.00 FL
31	1		*REAR END PANEL TOP GARNISH	Deformed	127.00 FL	*127.00 FL
32	1		*REAR STORAGE BOX	Cracked	386.00 FL	*386.00 FL
33	1		*REAR CHASSIS MEMBER RH	Repair	846.00 FL	*- FL
34	1		*REAR EXHAUST BOX	Not Necessary	740.00 FL	*- FL
35	1		*REAR EXHAUST INSULATOR	Not Necessary	142.00 FL	*- FL
36	1		*SET REAR EXHAUST GASKET	Not Necessary	60.00 FL	*- FL
37	6		*REAR EXHAUST MOUNTING	Not Necessary	174.00 FL	*- FL
38	1		*REAR SPARE TYRE	Not Necessary	564.00 FL	*- FL
39	1		*REAR SPARE TYRE CABLE BOX	Not Necessary	288.00 FL	*- FL
40	1		*REAR NUMBER PLATE	Bent	50.00 FS	*50.00 FS
41	1		*SET REAR BUMPER (UPPER) CLIP	Necessary	80.00 FS	*20.00 FS
42	1		*SET REAR BUMPER (LOWER) CLIP	Necessary	80.00 FS	*20.00 FS
43	1		*TAILGATE SEALANT	Not Necessary	150.00 FS	*- FS
44	1		*TAILGATE EMBLEM CYCLE & CARRIER	Necessary	150.00 FS	*45.00 FS
45	1		*TAILGATE DAMPER (ELECTRICAL) (SPECIAL TYPE)	Damaged	1,400.00 FS	*600.00 FS
46	2		*TAILGATE INNER TRIM REFLECTOR	Not Necessary	40.00 FS	*- FS

Report was unsubmitted during this print-out.

9/19/22, 3:21 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*TAILGATE INNER TRIM CLIP	Necessary	50.00 FS	*30.00 FS
48	1		*TAILGATE INNER LOCK C/W MOTOR (SPECIAL TYPE)	Damaged	1,200.00 FS	*400.00 FS
49	1		*TAILGATE OPENING FOOT SENSOR (SPECIAL TYPE)	Not Necessary	850.00 FS	*- FS
50	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
51	1		*TAILGATE WINDSCREEN INNER SHIELD	Necessary	60.00 FS	*40.00 FS
52	1		*TAILGATE SIDE LINING	Necessary	80.00 FS	*50.00 FS
53	1		*TAILGATE STICKER CARENS	Necessary	60.00 FS	*20.00 FS
54	1		*TAILGATE TURBO PAD	Necessary	50.00 FS	*40.00 FS
55	1		*SET TAILLAMP CLIP	Necessary	50.00 FS	*20.00 FS
56	1		*SET REAR FENDER INNER COWLING CLIP	Not Necessary	80.00 FS	*- FS
57	1		*SET REAR FENDER INNER TRIM CLIP	Necessary	80.00 FS	*30.00 FS
58	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
59	1		*SET REAR END PANEL TOP GARNISH CLIP	Necessary	40.00 FS	*10.00 FS
60	1		*REVERSE CAMERA	Not Necessary	450.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					18,402.00	8,994.00
- List Item Discount on L Items 10.00/10.00% (\$\$)					1,317.20	751.90
Total Parts (\$\$)					17,084.80	8,242.10
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	New	2,000.00	800.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,600.00	800.00
3	TUFF COAT	New	350.00	80.00
4	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	350.00	80.00
5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
6	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	80.00	50.00
7	TRANSFER TAILGATE MECHANISM	New	80.00	80.00
8	CONDUCT WATER LEAKAGE TEST	New	250.00	0.00
9	RESET TAILGATE AUTO SYSTEM	New	350.00	120.00
10	REMOVE AND REFIX REAR EXHAUST PIPE	New	180.00	0.00
11	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	120.00
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	350.00	0.00
Gross Labour Cost (\$\$)			5,790.00	2,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >