

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG22006675/KPA3Q2**Date:** 11/01/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7220043952
<b>Claimant Vehicle No :</b>	SNF7993R	<b>Insured Vehicle No :</b>	SLJ5538M
Date of Loss:	06/07/2022	Nature of Claim:	TP
		Claim No:	8707321852SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	SNF7993R	Engine No:	L15B6020981
Make & Model:	HONDA SHUTTLE, 1.5 G CVT SENSING (A)	Chassis No:	GK82100825
Reg. Date:	23/06/2022 (Man. Year: 2019)	Odometer:	3455 km
Colour:	Metallic Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Bridgestone 9 mm	Rear Left Side:	Bridgestone 9 mm
Front Right Side:	Bridgestone 9 mm	Rear Right Side:	Bridgestone 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,768.32	0.00	1,768.32	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,230.00	550.00	680.00	55.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>2,998.32</b>	<b>550.00</b>	<b>2,448.32</b>	<b>81.66</b>
<b>+ GST 7.00/7.00% (S\$)</b>	209.88	38.50	171.38	81.66
<b>Nett Amount (S\$)</b>	<b>3,208.20</b>	<b>588.50</b>	<b>2,619.70</b>	<b>81.66</b>
<b>+ Loss of Use (2.0 x S\$60.00/day) (S\$)</b>		120.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>710.50</b>		

**INSPECTION**

Date of Assignment:	18/07/2022	Optima Werkz Pte Ltd (HQ)
Date Inspected:	18/07/2022 Inspected At:	10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK
		Autopoint
		Singapore 568047
Estimated Period of Repair:	2.0 days	

**Adjuster:** KENNETH KONG**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,550.70 FL	*- FL
2	1		*REAR BUMPER SIDE BRACKET RH	Serviceable	35.60 FL	*- FL
3	1		*REAR BUMPER REFLECTOR RH	Serviceable	50.50 FL	*- FL
4	1		*REAR BUMPER INNER SPONGE	Serviceable	101.70 FL	*- FL
5	1		*REAR BUMPER TOWING COVER RH	Serviceable	34.40 FL	*- FL
6	1		*REAR TAILGATE (NPA)	Repair	0.00 FL	*- FL
7	1		*REAR BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
8	1		*REAR BUMPER REVERSE SENSOR	Serviceable	300.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	2,122.90	0.00
- List Item Discount on L Items 20.00/20.00% (\$)	354.58	0.00
Total Parts (\$)	1,768.32	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR CHARGES TO REMOVE,REPLACE ,REFIX REPAIR & READJUST REAR ACCIDENT AREAS & ETC	New	500.00	150.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE ,REAR BUMPER & ETC	New	500.00	400.00
3	TO DAIGNOSIS FAULT CODE & RESET MEMORY	New	150.00	0.00
4	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC	New	80.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,230.00</b>	<b>550.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >