

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22006676/UYA3Q2**Date:** 18/06/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100185921
Claimant Vehicle No :	GBJ2741E	Insured Vehicle No :	GBB7424E
Date of Loss:	07/07/2022	Nature of Claim:	TP
		Claim No:	3878617252SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBJ2741E		
Make & Model:	NISSAN NV350, 2.5 PANEL VAN 5AT 5DR (A)	Engine No:	YD25042554B
Reg. Date:	11/03/2019 (Man. Year: 2018)	Chassis No:	JN1MC2E26Z0030858
Colour:	White	Odometer:	85164 km
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,423.98	1,056.42	367.56	25.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	830.00	420.00	410.00	49.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	2,253.98	1,476.42	777.56	34.50
+ GST 7.00/7.00% (\$\$)	157.78	103.35	54.43	34.50
Nett Amount (\$\$)	2,411.76	1,579.77	831.99	34.50
+ Car Rental (3.0 x S\$90.00/day) (\$\$)		270.00		
Nett Liability (\$\$)		1,849.77		

INSPECTION

Date of Assignment:	28/07/2022	
Date Inspected:	28/07/2022	Inspected At: Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412 Singapore 539195
Estimated Period of Repair:	2.0 days	

Adjuster: MARCUS CHUA**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented	848.30 FL	*617.70 FL
2	1		*FRONT BUMPER RH SIDE RETAINER	Not Necessary	177.80 FL	*- FL
3	1		*RH FOGLAMP COVER	Grazed	127.00 FL	*127.00 FL
4	1		*RH HEADLAMP	Cut	429.10 FL	*429.10 FL
F=Franchise part. L=ListItemDisc.						
					Sub Total (\$)	1,582.20 1,173.80
					- List Item Discount on L Items 10.00/10.00% (\$)	158.22 117.38
					Total Parts (\$)	1,423.98 1,056.42

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REFIT ELECTRICAL WIRING	New	30.00	20.00
2	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS	New	400.00	200.00
3	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS	New	400.00	200.00
Gross Labour Cost (\$)			830.00	420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >