

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMN 4948L

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR FENDER (RH) (NPA) (CONSISTENT)	TO REPAIR SEE LABOUR	-	-
1	REAR BUMPER (CONSISTENT)	MTG CRACKED / BUCKLED	919.40	828.00
1	REAR BUMPER SIDE RETAINER RH (CONSISTENT)	DISTORTED	35.60	35.60
1	REAR BUMPER REFLECTOR RH (CONSISTENT)	CRACKED	42.80	42.80
1	REAR END PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	523.70	-
1	REAR END PANEL TOP GARNISH (CONSISTENT)	SERVICEABLE	155.40	-
1	TAILGATE (CONSISTENT)	BENT	1,200.20	1,200.20
1	TAILGATE WEATHERSTRIP (CONSISTENT)	SERVICEABLE	168.20	-
1	TAILGATE INNER TRIM BOARD (CONSISTENT)	SERVICEABLE	388.40	-
1	EMBLEM 'FREED'(CONSISTENT)	NECESSARY	55.40	55.40
1	EMBLEM 'HYBRID'(CONSISTENT)	NECESSARY	75.40	75.40
1	LOGO 'H' (CONSISTENT)	NECESSARY	32.50	32.50
1	REAR WINDSCREEN MOULDING (CONSISTENT)	NECESSARY	95.40	95.40
1	TAILGATE REFLECTOR RH (CONSISTENT)	SERVICEABLE	360.20	-
1	TAIL LAMP RH (CONSISTENT)	MTG CRACKED	629.40	629.40
1	REAR BUMPER TOWING COVER (CONSISTENT)	MISSING	39.50	39.50
1	REAR FENDER (RH) (ADDITIONAL)(CONSISTENT)	BENT	1,110.90	1,110.90
1	REAR FENDER RIGHT AIR VENT (ADDITIONAL) (CONSISTENT)	SERVICEABLE	26.40	-
1	REAR SPLASH GUARD RIGHT (ADDITIONAL) (CONSISTENT)	DISTORTED	50.00	50.00
	LESS 20% DISCOUNT		-	-839.02
			5,908.80	3,356.08
	SPECIAL NETT ITEMS			
1	REAR WINDSCREEN SEALANT (SN)(CONSISTENT)	NECESSARY	80.00	40.00
1	SET REVERSE SENSOR (SN)(CONSISTENT)	SERVICEABLE	400.00	-
			480.00	40.00
1	I	I		

Report Ref No. CC4/ASM22006677/Kpa3q2



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>LABOUR</u>			
	RUST-PROOFING ON THE REAR ACCIDENT AFFECTED PORTIONS.		100.00	30.00
	TO CHECK & TEST LIGHTING FUNCTIONS & REVERSE SENSOR WIRING.		80.00	50.00
	TO REMOVE AND REFIT REAR WINDSCREEN TO ASSIST REPAIR .		120.00	120.00
	LABOUR TO REPLACE ABOVE PARTS ,PANEL BEAT ,REPAIR & RE ALIGN DAMAGE PARTS.		1,200.00	700.00
	TO PUTTY & SPRAY PAINT REAR END PANEL ,REAR BUMPER ,TAILGATE ,REAR FENDER RIGHT & OTHER AFFECTED AREAS .		1,500.00	800.00
			3,000.00	1,700.00
	GRAND TOTAL		9,388.80	5,096.08

RECOMMENDED COST OF REPAIRS			5,096.08
-----------------------------	--	--	----------

Report Ref No. CC4/ASM22006677/Kpa3q2

KONG SENG CHEONG

**Licensed Appraiser**