

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

| PRE-REPAIR INSPECTION REPORT | | | | | | |
|------------------------------------|---|--|------------------|-------|-------------------------|--|
| | GREAT AMERICAN INSURANCE COMPANY | | | Ref: | CS3/GAI22006683/Eqy3m4 | |
| | 3 TEMASEK AVEN #16-01 CENTENNI SINGAPORE 03919 | AL TOWER | | Date: | 28/07/2022 | |
| | | | (| Code: | GAI | |
| 1. | Policy Particulars :- (THIRD PARTY CLAIM) | | | | | |
| | Insured Veh. | GBH 4332A | Veh. Inspected | | FBT 7351L | |
| | Policy No. | | Coverage (\$) | | 0.00 | |
| | Claim No. | CLMOMVC000004193 | Excess (\$) | | 0.00 | |
| | Assign From | SHERY WONG | Assign Date | | 13/07/2022 | |
| 2. Vehicle Particulars & Condition | | | | | | |
| | Make & Model | YAMAHA NMAX | c.c | | 155 | |
| | Engine No. | HIDDEN | Year of Reg. | | | |
| | Chassis No. | MH3SG5680NK136012 | Colour | | BLUE | |
| | Odometer | 2748 KM | Steering | | IN ORDER | |
| | Brakes | IN ORDER | Modification | | SPORTS RIM | |
| | General | GOOD | | | | |
| 3. Conditions of Tyres | | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | 110/70-13 | DUNLOP | | 4 mm | |
| | L/H Front Tyre | | | | mm | |
| | R/H Rear Tyre | 130/70-13 | DUNLOP | | 4 mm | |
| | L/H Rear Tyre | | | | mm | |
| 4. Description of Damages | | | | | | |
| | THE VEHICLE SUS BODY. | SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S | | | | |
| 5. General Information | | | | | | |
| | Accident Date | 05/07/2022 | Inspect Date / T | ime | 14/07/2022 (07:40 PM) | |
| | Survey held at 34 Toh Guan Road East #01-29 Singapore 608579 | | | | | |
| | Repairer M 1 MOTORING | | | | | |
| 5a. | | | | | | |
| | A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000 | | | | | |
| 5b. Estimate Days of Repair | | | | | | |
| | ESTIMATED NORM | ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days | | | | |

Report Ref No. CS3/GAI22006683/Eqy3m4

Inspected By

CHEN TSUE YEE

K.K.LAU CPT(RET)

Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser