

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22006702/TCY3E2**Date:** 20/01/2023REFERENCEHandling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMB1SNW00009692100

**Claimant Vehicle
No :** SMD1762C**Insured Vehicle
No :** PA3300U

Date of Loss: 12/07/2022

Nature of Claim: TP

Claim
No: SNM22D204867/C02/TANKWDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMD1762C**

Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A)

Engine No: 3ZZ4814923

Reg. Date: 12/12/2008 (Man. Year: 2008)

Chassis No: MR053ZEE106124635

Colour: Silver

Odometer: 126515 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,656.84	4,011.80	6,645.04	62.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,140.00	1,870.00	3,270.00	63.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,796.84	5,881.80	9,915.04	62.77
Approved Total (Overridden) (S\$)		4,700.00		
Nett Amount (S\$)	15,796.84	4,700.00	11,096.84	70.25

INSPECTION

Date of Assignment: 14/07/2022

Date Inspected: 18/07/2022 Inspected At:

JEW Motors (HQ)
60 Jalan Lam Huat Carros Centre #03-72
Singapore 737869

Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Jan 2023)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMD1762C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent	839.90 FL	*839.40 FL
2	1		*BOOTLID 1.6 EMBLEM	Necessary	45.80 FL	*45.80 FL
3	1		*BOOTLID CENTRE EMBLEM	Necessary	45.89 FL	*45.89 FL
4	1		*BOOTLID COROLLA EMBLEM	Necessary	66.40 FL	*66.40 FL
5	1		*BOOTLID ALTIS EMBLEM	Necessary	55.20 FL	*55.20 FL
6	1		*BOOTLID LX EMBLEM	Necessary	39.80 FL	*39.80 FL
7	1		*BOOTLID LOCK	Not Necessary	134.50 FL	*- FL
8	1		*BOOTLID LOCK CATCH	Not Necessary	45.00 FL	*- FL
9	1		*BOOTLID RH LAMP	Cut	255.55 FL	*228.90 FL
10	1		*SET BOOTLID INNER TRIM CLIPS	Not Necessary	45.00 FL	*- FL
11	1		*BOOTLID WEATHERSTRIP	Cut	198.50 FL	*198.50 FL
12	1		*REAR BUMPER	Deformed	548.90 FL	*548.90 FL
13	1		*SET REAR BUMPER CLIPS	Necessary	70.00 FL	*30.00 FL
14	1		*REAR BUMPER RH REFLECTOR	Cracked	55.30 FL	*55.30 FL
15	1		*REAR BUMPER RH SIDE RETAINER (LONG)	Deformed	67.80 FL	*67.80 FL
16	1		*REAR BUMPER RH SIDE RETAINER (SMALL)	Deformed	46.97 FL	*46.97 FL
17	1		*REAR BUMPER LH SIDE RETAINER (LONG)	Not Necessary	67.80 FL	*- FL
18	1		*REAR BUMPER LH SIDE RETAINER (SMALL)	Not Necessary	46.97 FL	*- FL
19	1		*REAR BUMPER INNER SPONGE	Cracked	178.90 FL	*178.90 FL
20	1		*REAR BUMPER RH BRACKET	Not Necessary	97.90 FL	*- FL
21	1		*END PANEL	Bent	590.70 FL	*590.70 FL
22	1		*END PANEL GARNISH	Deformed	202.80 FL	*202.80 FL
23	1		*SET END PANEL GARNISH CLIPS	Necessary	60.00 FL	*20.00 FL
24	1		*RH TAILLAMP ASSY	Cracked	455.67 FL	*410.95 FL
25	1		*SET RH TAILLAMP LOCK CLIPS	Necessary	28.00 FL	*28.00 FL
26	1		*RH TAILLAMP GASKET	Not Necessary	23.00 FL	*- FL
27	1		*RH TAILLAMP LOWER BRACKET	Deformed	55.94 FL	*55.94 FL
28	1		*RH TAILLAMP PANEL	Buckled	178.93 FL	*178.93 FL
29	1		*REAR WINDSCREEN GLASS RUBBER MOULDING	Necessary	78.40 FL	*78.40 FL
30	1		*REAR RH FENDER	Buckled	1,086.90 FL	*1,082.25 FL
31	1		*REAR RH FENDER INNER TRIM	Not Necessary	332.45 FL	*- FL
32	1		*SET REAR RH FENDER INNER TRIM CLIPS	Not Necessary	50.00 FL	*- FL
33	1		*REAR RH FENDER SPLASH SHIELD	Not Necessary	71.20 FL	*- FL
34	1		*SET REAR RH FENDER SPLASH SHIELD CLIPS	Not Necessary	35.00 FL	*- FL
35	1		*SPARE TYRE PANEL TOP BOARD	Not Necessary	278.40 FL	*- FL
36	1		*EXHAUST SILENCER	Not Necessary	723.10 FL	*- FL
37	1		*EXHAUST SILENCER GASKET	Not Necessary	55.00 FL	*- FL
38	1		*REAR RH WHEEL BEARING	Not Necessary	425.70 FL	*- FL
39	1		*REAR RH SHOCK ABSORBER	Not Necessary	211.20 FL	*- FL
40	1		*REAR AXLE BEAM	Not Necessary	1,284.30 FL	*- FL
41	1		*REAR RH DOOR	Not Necessary	1,321.00 FL	*- FL
42	1		*REAR RH DOOR PROTECTOR	Not Necessary	83.22 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*REAR RH DOOR PROTECTOR CHROME INSERT	Not Necessary	32.80 FL	*- FL
44	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	80.00 FS	*60.00 FS
45	1		*REAR WINDSCREEN GLASS INNER SEAL	Necessary	50.00 FS	*50.00 FS
46	1		*RH TAILLAMP PANEL SEAL	Necessary	40.00 FS	*20.00 FS
47	1		*END PANEL SEAL	Necessary	70.00 FS	*30.00 FS
48	1		*REAR RH FENDER SEAL	Necessary	75.00 FS	*30.00 FS
49	1		*REAR REVERSE SENSOR	Not Necessary	450.00 FS	*- FS
50	1		*REAR RH DOOR EDGE RUBBER PROTECTOR	Not Necessary	180.00 FS	*- FS
51	1		*REAR RH SPORT RIM	Not Necessary	1,200.00 FS	*- FS
52	1		*REAR RH TYRE	Not Necessary	550.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)				13,310.79	5,285.73
- List Item Discount on L Items 25.00/25.00% (S\$)				2,653.95	1,273.93
Total Parts (S\$)				10,656.84	4,011.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES	New	1,800.00	800.00
2	SPRAY PAINTING	New	1,500.00	800.00
3	CHECK WIRING AND LIGHTING SYSTEM	New	120.00	30.00
4	APPLY RUST COATING ON AFFECTED AREAS	New	150.00	30.00
5	TO REMOVE AND REFIT REAR WINDSCREEN GLASS TO CARRY REPAIR	New	250.00	120.00
6	TO REMOVE AND REPLACE REAR INNER TRIMS, ROOF LINING, SEAT AND BOARD TO CARRY REPAIR	New	400.00	60.00
7	TO REMOVE AND REPLACE REAR REVERSE SENSORS TO CARRY REPAIR	New	100.00	30.00
8	TO DO WHEEL ALIGNMENT SYSTEM	New	100.00	0.00
9	TO REMOVE AND REPLACE REAR UNDERCARRIAGE PARTS TO CARRY REPAIR	New	550.00	0.00
10	TO REMOVE AND REFIT REAR RH DOOR INNER PARTS TO NEW DOOR	New	120.00	0.00
11	TO BALANCE REAR RH SPORT RIM WITH TYRE	New	50.00	0.00
Gross Labour Cost (\$\$)			5,140.00	1,870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >