

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22006705/UPA3Q2**Date:** 05/09/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900098970
Claimant Vehicle No :	SLK2045H	Insured Vehicle No :	SML3147Z
Date of Loss:	12/07/2022	Nature of Claim:	TP
		Claim No:	6197071434SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLK2045H	Engine No:	L15Z14114310
Make & Model:	HONDA CITY, 1.5 SV CVT (A)	Chassis No:	MRHGM6660HP000483
Reg. Date:	09/01/2017 (Man. Year: 2016)	Odometer:	189715 km
Colour:	Red		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R16	Rear Tyre Size:	185/55 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,218.20	497.92	720.28	59.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,650.00	770.00	880.00	53.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,868.20	1,267.92	1,600.28	55.79
Approved Total (Overridden) (S\$)		1,000.00		
(S\$)	2,868.20	1,000.00	1,868.20	65.13
+ GST 7.00/7.00% (S\$)	200.77	70.00	130.77	65.13
Nett Amount (S\$)	3,068.97	1,070.00	1,998.97	65.13
+ Car Rental (2.0 x S\$100.00/day) (S\$)		200.00		
Nett Liability (S\$)		1,270.00		
Global Sum Settlement (S\$)		1,270.00		

INSPECTION

Date of Assignment:	14/07/2022	
Date Inspected:	14/07/2022	Inspected At: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	2.0 days	

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILLAMP N/S	Not Necessary	248.30 F	*- FL
2	1		*REAR BUMPER	Deep Cut	542.20 F	*542.20 FL
3	1		*REAR BUMPER SIDE RETAINER N/S	Not Necessary	26.50 F	*- FL
4	1		*REAR BUMPER REFLECTOR N/S	Cracked	45.20 F	*45.20 FL
5	1		*SET REAR BUMPER CLIPS	Necessary	35.00 F	*35.00 FL
6	1		*REAR END PANEL	Repair	321.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	1,218.20	622.40
- List Item Discount on L Items 0.00/20.00% (\$)	0.00	124.48
Total Parts (\$)	1,218.20	497.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REFIX REAR REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	100.00	0.00
4	TO SPRAY RUST PROOFING	New	120.00	0.00
5	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	500.00	300.00
6	TO PUTTY & SPRAY PAINTING	New	800.00	400.00
Gross Labour Cost (\$\$)			1,650.00	770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >