

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22006706/APA3Q2**Date:** 07/03/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210120672
Claimant Vehicle No :	SMV4520U	Insured Vehicle No :	SDS6258L
Date of Loss:	13/07/2022	Nature of Claim:	TP
		Claim No:	5506283527SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMV4520U		
Make & Model:	AUDI A4, 2.0 TFSI S-TRONIC (A)	Engine No:	DEM024661
Reg. Date:	30/09/2020 (Man. Year: 2020)	Chassis No:	WAUZZZF49LA077036
Colour:	White	Odometer:	27722 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,742.00	3,384.80	13,357.20	79.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,972.00	1,722.00	1,250.00	42.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	19,714.00	5,106.80	14,607.20	74.10
+ GST 8.00/8.00% (\$\$)	1,577.12	408.54	1,168.58	74.10
Nett Amount (\$\$)	21,291.12	5,515.34	15,775.78	74.10
+ Loss of Use (3.0 x S\$100.00/day) (\$\$)		300.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		5,817.34		

INSPECTION

Date of Assignment:	20/07/2022		
Date Inspected:	20/07/2022	Inspected At:	Premium Automobiles Pte Ltd (HQ) 55 UBI ROAD 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,377.00 FS	*1,901.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	393.00 FS	*- FS
3	1		*FRONT BUMPER SECURING STRIP	Not Necessary	40.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE -CENTER	Not Necessary	219.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT -LOWER CENTRE	Not Necessary	293.00 FS	*- FS
6	1		*FRONT AIR GUIDE -RH	Not Necessary	51.00 FS	*- FS
7	1		*FRONT BUMPER CLOSING ELEMENT -UPPER CENTRE	Not Necessary	293.00 FS	*- FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE -RH	Not Necessary	151.00 FS	*- FS
9	1		*FRONT BUMPER TRIM -RH	Not Necessary	54.00 FS	*- FS
10	1		*FRONT RADIATOR GRILLE	Cracked	1,754.00 FS	*1,403.20 FS
11	2		*FRONT SENSOR -INNER /OUTER	Not Necessary	530.00 FS	*- FS
12	4		*FRONT SEAL RING	Not Necessary	10.00 FS	*- FS
13	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	212.00 FS	*- FS
14	1		*FRONT BUMPER BEAM	Not Necessary	899.00 FS	*- FS
15	1		*FRONT BUMPER RADIATOR SUPPORT COVER	Not Necessary	143.00 FS	*- FS
16	1		*FRONT CAUTION SIGN STICKER	Not Necessary	16.00 FS	*- FS
17	1		*FRONT AIR CONDITIONER STICKER	Not Necessary	9.00 FS	*- FS
18	1		*FRONT BUMPER LOCK BEAM	Not Necessary	154.00 FS	*- FS
19	2		*FRONT BUMPER SUPPORT -LH/RH	Not Necessary	64.00 FS	*- FS
20	4		*FRONT POP RIVET	Not Necessary	4.00 FS	*- FS
21	1		*FRONT FENDER BRACKET	Not Necessary	21.00 FS	*- FS
22	1		*FRONT AIR GUIDE -RH	Not Necessary	51.00 FS	*- FS
23	3		*FRONT AIR GUIDE -LH/RH/UPPER	Not Necessary	57.00 FS	*- FS
24	1		*FRONT LED HEADLIGHT -RH	Not Necessary	8,172.00 FS	*- FS
25	1		*FRONT LEFT CYLINDER -RH	Not Necessary	231.00 FS	*- FS
26	1		*FRONT LEFT CYLINDER BRACKET	Not Necessary	7.00 FS	*- FS
27	1		*FRONT CORRUGATED PIPE	Not Necessary	107.00 FS	*- FS
28	1		*SUNDRIES	Not Necessary	350.00 FS	*- FS
29	1		*FRONT NO PLATE	Necessary	80.00 FS	*80.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 16,742.00 3,384.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR ,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER ,AND RHS HEADLIGHT .RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
4	TO RESPRAY FRONT BUMPER	New	900.00	550.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			2,972.00	1,722.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >