

AUTO PERFORMANCE APPRAISAL

APA

TAX INVOICE

Tan Kang Juat
C/O Guan Auto Service
Blk 7 Sin Ming Industrial Estate Sector C
#01-80/#01-82
Singapore 575642

INVOICE NO : APA22002389

DATE : 31/05/2022

VEHICLE NO : SGV1233P
JOB REFERENCE NO : 22/002501
ACCIDENT DATE : 18/05/2022
SURVEY DATE : 19/05/2022

<u>DESCRIPTION</u>	<u>AMOUNT</u>
Survey Fees Inclusive Of Transportation	\$525.00
Photographs (\$1) Per Copies : 73	\$73.00
TOTAL AMOUNT	\$598.00

Notes :

All cheque payment should be "Crossed" and made payable to "Auto Performance Appraisal"

Auto Performance Appraisal



AUTO PERFORMANCE APPRAISAL

APA

VEHICLE SURVEY REPORTS																																				
Tan Kang Juat C/O Guan Auto Service Blk 7 Sin Ming Industrial Estate Sector C #01-80/#01-82 Singapore 575642																																				
1	Reference Job Reference No : 22/002501 Claim No : - Claim Type : Third Party Accident Date : 18/05/2022 Survey Date : 19/05/2022 Survey Report Date : 31/05/2022																																			
2	Particulars Of Vehicle Vehicle Registration No : SGV1233P Make & Model : Honda Accord Euro R Vehicle Registration Date : 18/05/2007 Chassis No : CL71300861 Engine No : Blocked Colour : Red																																			
3	Condition Of Vehicle And Tyres <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left;"><u>Mileage (KM)</u></th> <th style="text-align: left;"><u>Brakes</u></th> <th style="text-align: left;"><u>Steering</u></th> <th style="text-align: left;"><u>Modification</u></th> </tr> </thead> <tbody> <tr> <td>254101</td> <td>Serviceable</td> <td>Affected</td> <td>None</td> </tr> <tr> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <th style="text-align: left;"><u>Tyres</u></th> <th style="text-align: left;"><u>Make</u></th> <th style="text-align: left;"><u>Size</u></th> <th style="text-align: left;"><u>Balance (MM)</u></th> </tr> <tr> <td>Front RHS</td> <td>Bridgestone</td> <td>225/45R17</td> <td>5</td> </tr> <tr> <td>Front LHS</td> <td>Bridgestone</td> <td>225/45R17</td> <td>5</td> </tr> <tr> <td>Rear RHS</td> <td>Bridgestone</td> <td>225/45R17</td> <td>6</td> </tr> <tr> <td>Rear LHS</td> <td>Bridgestone</td> <td>225/45R17</td> <td>6</td> </tr> </tbody> </table>				<u>Mileage (KM)</u>	<u>Brakes</u>	<u>Steering</u>	<u>Modification</u>	254101	Serviceable	Affected	None					<u>Tyres</u>	<u>Make</u>	<u>Size</u>	<u>Balance (MM)</u>	Front RHS	Bridgestone	225/45R17	5	Front LHS	Bridgestone	225/45R17	5	Rear RHS	Bridgestone	225/45R17	6	Rear LHS	Bridgestone	225/45R17	6
<u>Mileage (KM)</u>	<u>Brakes</u>	<u>Steering</u>	<u>Modification</u>																																	
254101	Serviceable	Affected	None																																	
<u>Tyres</u>	<u>Make</u>	<u>Size</u>	<u>Balance (MM)</u>																																	
Front RHS	Bridgestone	225/45R17	5																																	
Front LHS	Bridgestone	225/45R17	5																																	
Rear RHS	Bridgestone	225/45R17	6																																	
Rear LHS	Bridgestone	225/45R17	6																																	
4	Description Of Damages The vehicle sustained damages at front right hand portion. (For information of damages please refer to Parts/Labour/Photographs attached)																																			
5	Instruction This survey was conducted entirely on a "WITHOUT PREJUDICE" basis, and we have not authorised any repair.																																			

AUTO PERFORMANCE APPRAISAL

Annex A

Vehicle Assessment Reports

Ref No : 22/002501

Damage And Repair Cost Adjustment

<u>S/No</u>	<u>Qty</u>	<u>Parts Description</u>	<u>Comments/condition</u>	<u>Workshop Estimate (\$)</u>	<u>Our Assessment (\$)</u>
List Items					
1	1	Front bumper <i>976</i>	Deformed	1,171.20	1,171.20
2	1	Front bumper RH Fog lamp	Cut/grazed	152.70	<i>ln</i> 152.70 <i>X</i>
3	1	Front bumper RH Fog lamp bracket	Bent	52.30	<i>ln</i> 52.30 <i>X</i>
4	1	Front bumper RH side retainer	Deformed/broken	62.00	62.00
5	1	Front bumper RH side beam	Bent	87.90	87.90
6	1	Front bumper inner reinforcement	Buckled/bent	232.30	<i>ln</i> 232.30 <i>X</i>
7	1 set	Front bumper clips	Broken/necessary	40.00	40.00
8	1	Front grille	To repair	272.60	-
9	1	RH headlamp (HID)	Smashed/broken	1,151.40	1,151.40
10	1	RH headlamp bulb	Malfunction	84.60	84.60
11	1	RH headlamp ballast	Malfunction	152.70	152.70
12	1	Font bonnet	Broken	834.60	834.60
13	1	Front support panel	Badly dented/bent	678.50	<i>ln</i> 678.50 <i>X</i>
14	1	Front support panel top cover	Deformed/broken	113.20	<i>ln</i> 113.20 <i>X</i>
15	1 set	Front support panel top cover clips	Necessary	30.00	<i>ln</i> 30.00 <i>X</i>
16	1	Front RH fender <i>575.60</i>	Buckled	911.20	911.20
17	1	Front RH fender top moulding	Deformed/bent	78.30	<i>ln</i> 78.30 <i>X</i>
18	1	Front RH fender under shield	Deformed/broken	127.60	<i>ln</i> 127.60 <i>X</i>
19	1 set	Front fender under shield clips	Broken/necessary	40.00	40.00
20	1	Front bonnet lock	Serviceable/reuse	89.70	-
21	1	Front RH shock absorber	Serviceable/reuse	438.90	-
22	1	Front RH knuckle arm	Bent	633.70	<i>ln</i> 633.70 <i>X</i>
23	1	Front RH wheel hub	Bent	235.60	<i>ln</i> 235.60 <i>X</i>
24	1	Front RH wheel bearing	Noisy/necessary	130.30	<i>ln</i> 130.30 <i>X</i>

7,801.30 7,000.10

Less discount 20%

1,560.26 1,400.02

Total : 6,241.04 5,600.08

Special Nett Items

25	1	Front bumper lower skirting	To repair	800.00	-
26	1	Front RH sport rim	Cut/warped <i>ln</i>	550.00	<i>ln</i> 550.00 <i>ln</i>
				Total :	1,350.00 550.00

Total Spare Parts : 7,591.04 6,150.08

AUTO PERFORMANCE APPRAISAL

Vehicle Assessment Reports

Annex B

Ref No : 22/002501

Damage And Repair Cost Adjustment

<u>Items</u>	<u>Job Description</u>	<u>Workshop Estimate (\$)</u>	<u>Adjusted Costs (\$)</u>
1	To tow vehicle to workshop.	80.00	80.00 <i>50l</i>
2	To remove, cut out damage portion, jack out, straighten, panel beating, welding, align and renew replaced parts.	1,000.00	700.00 <i>450l</i>
3	To putty and respray painting on affected areas.	1,200.00	800.00 <i>600</i>
4	To check wirings and lightings.	50.00	30.00 <i>20l</i>
5	To remove, refix aircon condenser, pipes, drier vacuum and recharge gas.	150.00	<i>nn</i> 120.00 <i>X</i>
6	To remove, refix front RH under carriages.	150.00	<i>nn</i> 120.00 <i>X</i>
7	To conduct computerise wheel alignment test.	80.00	60.00
8	To supplied and applied anti rust treatments.	100.00	60.00 <i>30l</i>
Total Labour :		2,810.00	1,970.00
Total Spare Parts :		7,591.04	6,150.08
Total Labour :		2,810.00	1,970.00
Total Repair Costs :		10,401.04	8,120.08

Assessor's Recommendation

Repairer Estimate : 10,401.04
 Our Adjustment : 8,120.08

Remarks

The repairer has agreed to undertake the repair on a lump sum basis of \$6,500.00, with a repair period of 6 working days.

Surveyed By:



Lek Boon Hwee
Automobile Appraiser

4 days

GUAN AUTO SERVICE

Blk 7 Sin Ming Industrial Estate Sector C
#01-82 Singapore 575642

FINAL BILL

Tan Kang Juat
c/o Blk 7 Sin Ming Industrial Estate Sector C
#01-82 Singapore 575642

Our Ref.	SGV1233P
Your Ref:	-
Date	2-Jun-2022

No.	Description	Qty	Unit Price	Total
	To supply labour and materials to repair below mentioned vehicle to its pre-accident condition. Vehicle: <u>SGV1233P</u> Make/Model: <u>Honda Accord</u> Accident Date: <u>18-May-22</u>			\$6,500.00
			Amount Due	\$6,500.00



A handwritten signature in black ink, appearing to read "KJuat", written over a horizontal line.

Authorized Signatory