

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 219G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER FRT (DISC 25%)	CUT	482.00	361.50
10	BUMPER CLIPS @\$1.61 (DISC 25%)	NECESSARY	16.10	12.08
1	BUMPER SUPPORT F/RH	NOT NECESSARY	76.40	-
1	BUMPER SUPPORT F/LH	NOT NECESSARY	76.40	-
1	BUMPER ENERGY ABSORBER FRT	NOT NECESSARY	78.80	-
1	BUMPER REINFORCEMENT FRT	NOT NECESSARY	498.40	-
1	ARM SUB-ASSY, FR BUMPER LH	NOT NECESSARY	250.40	-
1	ARM SUB-ASSY, FR BUMPER RH	NOT NECESSARY	250.40	-
1	DEFLECTOR, RADIATOR RH	NOT NECESSARY	83.50	-
1	DEFLECTOR, RADIATOR LH	NOT NECESSARY	77.00	-
1	BUMPER GRILLE SUB-ASSY, LOWER	NOT NECESSARY	311.10	-
1	FOG LAMP RH	NOT NECESSARY	295.20	-
1	LENS & BODY, FR TURN RH	NOT NECESSARY	511.80	-
1	GRILLE, RADIATOR	NOT NECESSARY	310.60	-
1	GRILLE, RADIATOR LOWER NO.2	NOT NECESSARY	94.60	-
1	BUMPER LIP FRT	NOT NECESSARY	139.60	-
1	BUMPER FRT ABSORBER LOWER	NOT NECESSARY	448.30	-
1	HEAD LAMP RH	NOT NECESSARY	945.20	-
			4,945.80	373.58
	<u>LABOUR</u>			
	PANEL BEATING AND BODY WORK.		676.00	200.00
	SPRAY PAINT.		558.00	200.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	TO APPLY RUST-PROOFING ON AFFECTED AREA.	NOT NECESSARY	100.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO CHECK WIRING AND SYSTEM FUNCTION.	NOT NECESSARY	120.00	-
			1,614.00	400.00
	GRAND TOTAL		6,559.80	773.58

Report Ref No. NS/INC22006708/Rvce2





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	600.00
(TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)	

Report Ref No. NS/INC22006708/Rvce2

MOHAMMED RASUL BIN MOHD YUNUS

**Automotive Assessor** 

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

**REGD Auto Consultant-SAE, Licensed Appraiser**