

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS4/CTI22006716/EVY3E2

Date: 31/08/2022

REFERENCE

Insured/Claimant: KE ZHENGHUI Policy No: DMPCSNW00066032200
Date of Loss: 28/06/2022 Nature of Claim: OD Claim No: SNM22D204547/C01/CSC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGN9U**
Make & Model: FERRARI F8 TRIBUTO, 3.9 (A) Engine No: 489852
Reg. Date: 05/02/2021 (Man. Year: 2020) Chassis No: ZFF93LMC000262120
Colour: Blue Odometer: 0 km
Engine Capacity: 3902 cc
Market Value/New Car Price: S\$1,200,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/35Z R20 Rear Tyre Size: 245/35Z R20
Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm
Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	609,222.48	583,260.00	25,962.48	4.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	163,200.00	159,360.00	3,840.00	2.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	772,422.48	742,620.00	29,802.48	3.86
- Excess (S\$)	40,000.00	40,000.00	0.00	0.00
Nett Amount (S\$)	732,422.48	702,620.00	29,802.48	4.07

INSPECTION

Date of Assignment: 14/07/2022
Date Inspected: 15/07/2022 Inspected At: ITAL Auto Pte Ltd (HQ)
30 Leng Kee Road
Singapore 159100
Estimated Period of Repair: 0.0 days

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(EXCLUDE CHECK ITEMS S\$19,438.61 NETT)

TOTAL LOSS ASPECT

Market Value :	\$1,200,000.00
OMV :	\$373,979.00
PARF Rebate (1) :	\$483,872.00
Quota Premium Paid :	\$50,100.00
COE Rebate (2) :	\$42,860.00
Total Rebate (1) + (2) = :	\$526,732.00

The total amount incurred will be Market Value \$1,200,000.00 minus Total Rebate \$526,732.00 = \$673,268.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 31 Aug 2022)
Parts:	M1-COUPÉ	FERRARI F8 TRIBUTO 3.9 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGN9U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*UNDERBODY WATER RETURN PIPE	Missing	387.04 F	*387.04 F
2	1	*WATER DELIVERY HOSE TO RADIATOR	Missing	283.55 F	*283.55 F
3	1	*WATER RETURN HOSE FROM RADIATOR	Missing	247.29 F	*247.29 F
4	12	*COLLAR	Necessary	42.24 F	*42.24 F
5	1	*RADIATOR CONNECTOR HOSE UNION	Missing	260.40 F	*260.40 F
6	1	*PIPE RETAINER CLIP	Missing	2.29 F	*2.29 F
7	1	*VENT PIPE FROM RADIATOR TO DISCONNECTER L	Missing	62.42 F	*62.42 F
8	1	*COLLAR	Necessary	2.92 F	*2.92 F
9	1	*HOSE COLLAR	Missing	1.40 F	*1.40 F
10	1	*BRAKE FLUID RESERVOIR	* Check	242.59 F	*- F
11	4	*HOSE COLLAR	Necessary	5.60 F	*5.60 F
12	2	*FRONT SHOCK ABSORBER	Bent	9,546.00 F	*9,546.00 F
13	1	*LOWER SPACER (2PCS)	Necessary (1Pc Only)	52.40 F	*26.20 F
14	1	*FRONT SHOCK ABSORBER SPRING (2PCS)	Necessary (1Pc Only)	415.60 F	*207.80 F
15	1	*UPPER SPRING SPACER (2PCS)	Necessary (1Pc Only)	85.38 F	*42.69 F
16	1	*COMPL. SHOCK ABSORBER RETAINER CAP (2PCS)	Necessary (1Pc Only)	817.00 F	*408.50 F
17	4	*SCREW	Necessary	39.76 F	*39.76 F
18	1	*SHOCK ABSORBER BUSH (2PCS)	Necessary (1Pc Only)	188.58 F	*94.29 F
19	1	*BALL JOINT (2PCS)	Necessary (1Pc Only)	596.60 F	*298.30 F
20	1	*SCREW (2PCS)	Necessary (1Pc Only)	151.66 F	*75.83 F
21	1	*COMPL. LH FRONT HUB CARRIER	Bent	4,861.18 F	*4,861.18 F
22	1	*COMPL. RH FRONT HUB CARRIER	* Check	4,861.18 F	*- F
23	1	*COMPL. UPPER LH FRONT RIM	Bent	2,508.82 F	*2,508.82 F
24	1	*COMPL. UPPER RH FRONT RIM	* Check	2,508.82 F	*- F
25	16	*THREADED ROD	Necessary	165.92 F	*165.92 F
26	1	*COMPL. LOWER LH FRONT RIM	Bent	3,009.14 F	*3,009.14 F
27	1	*COMPL. LOWER RH FRONT RIM	* Check	3,009.14 F	*- F
28	2	*FRONT BRAKE DISC	Cracked	16,620.56 F	*16,620.56 F
29	1	*SCREW COLLAR (4PCS)	Necessary (2Pcs only)	85.12 F	*42.56 F
30	2	*BRAKE AIR PIPE	Missing	380.78 F	*380.78 F
31	1	*RH FRONT BRAKE AIR DUCT	Missing	626.67 F	*626.67 F
32	1	*LH FRONT BRAKE AIR DUCT	Missing	626.67 F	*626.67 F
33	1	*STABILISER BAR	Bent	594.47 F	*594.47 F
34	1	*BALL-JOINT TIE-ROD	Bent	212.87 F	*212.87 F
35	1	*BALL-JOINT TIE-ROD	Bent	218.78 F	*218.78 F
36	1	*20 FRONT WHEEL	Cut	2,495.15 F	*2,495.15 F
37	1	*20 REAR WHEEL (2PCS)	Cut (1Pc only)	5,085.48 F	*2,542.74 F
38	4	*TYRE PRESSURE MONITORING SYSTEM WHEEL SE	Necessary	1,749.28 F	*1,749.28 F
39	1	*FRONT TYRE (80%)	Torn	1,157.93 F	*926.34 F

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
40	1	*REAR TYRE (80%) (2PCS)	Crushed (1Pc Only)	2,601.34 F	*1,040.54 F
41	1	*CLOCK SPRING CONTACT	Necessary	1,056.83 F	*1,056.83 F
42	1	*DRIVER SIDE AIRBAG MODULE	Broken	4,584.56 F	*4,584.56 F
43	1	*STEERING BOX	Bent	10,689.46 F	*10,689.46 F
44	2	*GASKET	Necessary	5.02 F	*5.02 F
45	2	*GASKET	Necessary	5.10 F	*5.10 F
46	1	*UNDERBODY POWER STEERING RETURN PIPE	Torn	171.43 F	*171.43 F
47	1	*CLIP	Necessary	1.62 F	*1.62 F
48	3	*COLLAR	Necessary	15.84 F	*15.84 F
49	1	*FRONT BUMPER MOUNTING CROSS-MEMBER	Broken	4,379.11 F	*4,379.11 F
50	1	*RH FRONT SPAR	Bent	1,801.62 F	*1,801.62 F
51	1	*RIVET (62PCS)	Necessary	215.76 F	*215.76 F
52	1	*ANGULR BRACE FOR RH STRUT	Bent	336.39 F	*336.39 F
53	1	*ANGULR BRACE FOR LH STRUT	Bent	336.39 F	*336.39 F
54	1	*FRONT RH SHOCK TOWER	Bent	18,943.40 F	*18,943.40 F
55	1	*COMPL. LOWER FRONT SUSPENSION CROSS MEM	Bent	1,509.14 F	*1,509.14 F
56	1	*RH BRACKET	Bent	273.48 F	*273.48 F
57	1	*RH FRONT ACCELEROMETER BRACKET	Bent	72.24 F	*72.24 F
58	1	*LH FRONT ACCELEROMETER BRACKET	Bent	72.24 F	*72.24 F
59	2	*BRACKET	Bent	464.88 F	*464.88 F
60	1	*FRONT LH TORQUE BOX	Bent	4,910.07 F	*4,910.07 F
61	1	*COMPL. RH FRONT WHEEL BAY COVER PANEL	Bent	1,049.66 F	*1,049.66 F
62	1	*COMPL. LH FRONT WHEEL BAY COVER PANEL	Bent	1,174.31 F	*1,174.31 F
63	1	*COMPL. RH UPPER FRONT DIAGONAL BRACE	Bent	743.85 F	*743.85 F
64	1	*COMPL. LH UPPER FRONT DIAGONAL BRACE	Bent	743.85 F	*743.85 F
65	1	*RH DIAGONAL WINDSCREEN VALENCE PANEL END	Bent	1,268.96 F	*1,268.96 F
66	1	*LH DIAGONAL WINDSCREEN VALENCE PANEL END	Bent	1,268.96 F	*1,268.96 F
67	1	*WINDSCREEN VALENCE PANEL CROSS MEMBER	Bent	2,136.45 F	*2,136.45 F
68	1	*RH WINDSCREEN VALENCE PANEL FASTENER BRA	Bent	444.15 F	*444.15 F
69	1	*LH WINDSCREEN VELENCE PANEL FASTENER BRA	Bent	444.15 F	*444.15 F
70	1	*COMPL. UPPER LH HINGE REINFORCEMENT	Bent	919.12 F	*919.12 F
71	1	*COMPL. LOWER LH HINGE REINFORCEMENT	Bent	766.42 F	*766.42 F
72	1	*LH B-PILLAR TRUSS	Bent	840.12 F	*840.12 F
73	1	*LH SUBFRAME CONNECTOR CRASH BOX	Bent	6,011.68 F	*6,011.68 F
74	1	*LOWER RH DIAGONAL BRACE CONNECTED TO TU	Bent	479.76 F	*479.76 F
75	1	*LOWER LH DIAGONAL BRACE CONNECTED TO TU	Bent	479.76 F	*479.76 F
76	1	*RH TUNNEL UPPER FRONT DIAGONAL BRACE	Bent	708.85 F	*708.85 F
77	1	*LH CENTRE SIDEWALL	Bent	36,359.45 F	*36,359.45 F
78	1	*LH A-PILLAR TRUSS	Bent	480.55 F	*480.55 F
79	1	*LH SKILLET MOUNTING BRACKET	Bent	287.66 F	*287.66 F
80	1	*RH LOWER FRONT SUSPENSION CROSS-MEMBER	Bent	84.07 F	*84.07 F
81	1	*LH LOWER FRONT SUSPENSION CROSS-MEMBER	Bent	84.07 F	*84.07 F
82	1	*FRONT BRACKET FASTENING LH REAR FLANK TO	Bent	323.67 F	*323.67 F
83	1	*LH FLANK	Dented	35,605.90 F	*35,605.90 F
84	1	*FRONT RH FENDER	Dented	10,763.98 F	*10,763.98 F
85	1	*FRONT LH FENDER	Dented	10,763.98 F	*10,763.98 F
86	1	*COMPL. LH SIDE CONNECTION EXTENSION	Dented	480.58 F	*480.58 F
87	1	*COMPL. REAR SPOILER	Broken	13,080.69 F	*13,080.69 F
88	1	*WINDSCREEN SURROUND	Dented	5,526.61 F	*5,526.61 F
89	1	*RIVET (2PCS)	Necessary	11.59 F	*11.59 F
90	1	*RH UPPER PILLAR	Dented	3,123.72 F	*3,123.72 F
91	1	*LH UPPER PILLAR	Dented	3,123.72 F	*3,123.72 F
92	1	*COMPL. UPPER WINDSCREEN CROSS MEMBER	Dented	1,081.31 F	*1,081.31 F
93	4	*SCREW	Necessary	19.88 F	*19.88 F
94	1	*COMPL. FRONT BUMPER CARRIER TUBE	Bent	976.24 F	*976.24 F
95	1	*COMPL. RH FRONT SUBFRAME	Bent	1,670.02 F	*1,670.02 F
96	1	*COMPL. LH FRONT SUBFRAME	Tarnished	1,670.02 F	*1,670.02 F
97	1	*RH FENDER BRACKET EXTENSION	Bent	841.00 F	*841.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
98	1	*LH FENDER BRACKET EXTENSION	Bent	841.00 F	*841.00 F
99	1	*RH FENDER BRACKET EXTENSION	Bent	34.82 F	*34.82 F
100	1	*LH FENDER BRACKET EXTENSION	Bent	34.82 F	*34.82 F
101	8	*SCREW	Necessary	11.20 F	*11.20 F
102	1	*SCREW (32PCS)	Necessary	64.32 F	*64.32 F
103	1	*WASHER (34PCS)	Necessary	74.12 F	*74.12 F
104	1	*COMPL. RH HEADLIGHT FASTENER BRACKET	Bent	157.67 F	*157.67 F
105	1	*COMPL. LH HEADLIGHT FASTENER BRACKET	Bent	157.67 F	*157.67 F
106	2	*SHIM	Necessary	17.32 F	*17.32 F
107	2	*SHIM	Necessary	17.32 F	*17.32 F
108	1	*COMPL. INNER FASTENER BRACKET FOR RH HEAD	Bent	139.68 F	*139.68 F
109	1	*COMPL. INNER FASTENER BRACKET FOR LH HEAD	Bent	139.68 F	*139.68 F
110	4	*NUT	Necessary	5.84 F	*5.84 F
111	1	*COMPL. RH FENDER MOUNTING	Bent	1,276.03 F	*1,276.03 F
112	1	*COMPL. LH FENDER MOUNTING	Bent	1,251.94 F	*1,251.94 F
113	2	*TRELLIS MOUNTING BRACKET	Bent	560.04 F	*560.04 F
114	12	*RIVET	Necessary	47.16 F	*47.16 F
115	1	*COMPL. EXTERNAL RH FENDER FASTENER BRACKET	Bent	1,523.53 F	*1,523.53 F
116	1	*COMPL. EXTERNAL LH FENDER FASTENER BRACKET	Bent	1,523.53 F	*1,523.53 F
117	10	*WASHER	Necessary	33.60 F	*33.60 F
118	2	*BRACKET FOR ADJUSTER	Bent	560.04 F	*560.04 F
119	4	*LOWER FASTENER BRACKET FOR FRONT FENDER	Bent	960.24 F	*960.24 F
120	1	*LH UNDERWINDSCREEN TRIM BOX ELEMENT	Bent	480.22 F	*480.22 F
121	1	*REAR LH ENDPIECE	Bent	600.24 F	*600.24 F
122	1	*A PILLAR FLANGE, FRONT LH SECTION	Bent	480.22 F	*480.22 F
123	1	*LH FRONT PANEL	Bent	674.27 F	*674.27 F
124	1	*LH LOCK STRIKER REINFORCEMENT	Bent	720.28 F	*720.28 F
125	1	*COMPL. LH DOOR STRUCTURE	Dented	16,718.42 F	*16,718.42 F
126	2	*LH DOOR HINGE	Bent	470.98 F	*470.98 F
127	1	*COMPL. FRONT LID SKIN AND SUBSTRUCTURE	Bent	20,746.67 F	*20,746.67 F
128	1	*COMPL. RH HINGE	Bent	252.74 F	*252.74 F
129	1	*COMPL. LH HINGE	Bent	240.06 F	*240.06 F
130	1	*FRONT PANEL	Dented	13,926.00 F	*13,926.00 F
131	1	*FRONT AND REAR GASKET KIT	Necessary	4,501.87 F	*4,501.87 F
132	1	*FRONT AND REAR HEADLINER KIT	Necessary	5,738.38 F	*5,738.38 F
133	1	*COMPL. LOCK SYSTEM	Bent	4,407.44 F	*4,407.44 F
134	1	*LH STRIKER	Bent	757.12 F	*757.12 F
135	1	*LH STRIKER FASTENER BRACKET	Bent	23.54 F	*23.54 F
136	1	*LH WINDSCREEN STRIKER PLATE	Bent	110.44 F	*110.44 F
137	1	*SHIM KIT FOR ADJUSTING ROOF RELATIVE TO WI (2PCS)	Bent	172.95 F	*172.95 F
138	1	*COMPL. FRONT RH UNDERBODY SHIELD	Missing	480.58 F	*480.58 F
139	1	*COMPL. FRONT LH UNDERBODY SHIELD	Missing	480.58 F	*480.58 F
140	1	*RH CENTRAL FRONT DAM	Missing	252.11 F	*252.11 F
141	1	*LH CENTRAL FRONT DAM	Missing	252.11 F	*252.11 F
142	1	*RH FRONT INNER DAM	Missing	83.85 F	*83.85 F
143	1	*LH FRONT INNER DAM	Missing	83.85 F	*83.85 F
144	1	*SCREW (22PCS)	Necessary	197.78 F	*197.78 F
145	6	*SCREW	Necessary	16.08 F	*16.08 F
146	9	*WASHER	Necessary	16.47 F	*16.47 F
147	8	*SCREW	Necessary	23.04 F	*23.04 F
148	2	*SCREW	Necessary	17.98 F	*17.98 F
149	1	*CENTRAL UNDERBODY SHIELD, FRONT SECTION	Missing	367.37 F	*367.37 F
150	14	*SCREW	Necessary	125.86 F	*125.86 F
151	1	*SOMPL. REAR UNDERBODY SHIELD	Missing	1,236.45 F	*1,236.45 F
152	8	*RIVET	Necessary	13.60 F	*13.60 F
153	1	*RH BRAKE AIR INTAKE	Missing	228.29 F	*228.29 F
154	1	*LH BRAKE AIR INTAKE	Missing	228.29 F	*228.29 F

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
155	1	*RH FRONT WHEELHOUSE	Torn	1,050.39 F	*1,050.39 F
156	1	*LH FRONT WHEELHOUSE	Missing	1,050.39 F	*1,050.39 F
157	1	*SCREW (33PCS)	Necessary	52.32 F	*52.32 F
158	1	*COMPL. UPPER PART OF RH FRONT SEMI-DUCT	Missing	612.74 F	*612.74 F
159	1	*COMPL. UPPER PART OF LH FRONT SEMI-DUCT	Missing	612.74 F	*612.74 F
160	1	*FRONT DUCT FOR RH LOWER LATERAL AIR VENT	Missing	29.27 F	*29.27 F
161	1	*FRONT DUCT FOR LH LOWER LATERAL AIR VENT	Missing	68.91 F	*68.91 F
162	10	*SCREW	Necessary	70.40 F	*70.40 F
163	1	*SCREW (5PCS)	Necessary	8.08 F	*8.08 F
164	1	*RH UPPER BRAKE COOLING DUCT	Missing	101.23 F	*101.23 F
165	1	*LH UPPER BRAKE COOLING DUCT	Missing	101.23 F	*101.23 F
166	1	*COMPL. RH BRAKE AIR INTAKE	Missing	6,951.02 F	*6,951.02 F
167	1	*COMPL. LH BRAKE AIR INTAKE	Missing	6,951.02 F	*6,951.02 F
168	1	*SCREW (6PCS)	Necessary	13.36 F	*13.36 F
169	4	*CLIP	Necessary	51.84 F	*51.84 F
170	1	*RH HEADLIGHT FASTENER BRACKET	Missing	61.99 F	*61.99 F
171	1	*LH HEADLIGHT FASTENER BRACKET	Missing	61.99 F	*61.99 F
172	1	*BRACKET WITH COLLAR (4PCS)	Necessary	11.71 F	*11.72 F
173	4	*SCREW	Necessary	11.52 F	*11.52 F
174	1	*SCREW (8PCS)	Necessary	13.66 F	*13.66 F
175	1	*COMPL. RH HEADLAMP GUIDE	Necessary	26.50 F	*26.50 F
176	1	*COMPL. LH HEADLAMP GUIDE	Necessary	26.50 F	*26.50 F
177	2	*SCREW	Necessary	4.66 F	*4.66 F
178	1	*COMPL. WINDSCREEN	Broken	6,840.14 F	*6,840.14 F
179	2	*BLOCK	Necessary	17.36 F	*17.36 F
180	2	*ADHESIVE FOAM	Necessary	25.84 F	*25.84 F
181	1	*FOIL FLAP (2PCS)	Necessary	216.07 F	*216.07 F
182	1	*COMPL. LH AIRBAG	Broken	1,801.92 F	*1,801.92 F
183	1	*COMPL. UPPER LH DOOR PANEL - CONFIGURATIO	Broken	9,391.54 F	*9,391.54 F
184	1	*LH DOOR INNER CORNER TRIANGLE TRIM	Broken	77.72 F	*77.72 F
185	1	*LH UPPER DOOR CARD - CONFIGURATION PART	Broken	951.72 F	*951.72 F
186	1	*COMPL. LH DOOR PANEL - CONFIGURATION PART	Broken	5,862.73 F	*5,862.73 F
187	1	*LH DOOR CARD - CONFIGURATION PART	Broken	8,511.91 F	*8,511.91 F
188	1	*COMPL. LH DOOR PANEL POCKET - CONFIGURATI (NPA)	Broken	0.00 F	*- F
189	1	*LH EXTERNAL DOOR HANDLE	Cut	600.24 F	*600.24 F
190	2	*SCREW	Necessary	3.10 F	*3.10 F
191	1	*LH DOOR HANDLE SEAL	Necessary	47.60 F	*47.60 F
192	1	*LH OUTER DOOR HANDLE MODULE	Necessary	412.40 F	*412.40 F
193	2	*EXTERNAL DOOR HANDLE SPACER	Necessary	32.26 F	*32.26 F
194	2	*EXTERNAL DOOR HANDLE SPACER	Necessary	17.32 F	*17.32 F
195	1	*LH DOOR LOCK	Jammed	272.05 F	*272.05 F
196	1	*LH WATERPROOF MEMBRANE	Necessary	104.68 F	*104.68 F
197	2	*DOOR LOCK STRIKER PLATE	Bent	64.34 F	*64.34 F
198	1	*DOOR CHECK STRAP	Bent	98.89 F	*98.89 F
199	1	*FRONT LH DOOR WINDOW LIFT MECHANISM	Broken	1,015.17 F	*1,015.17 F
200	1	*LH DOOR WINDOW	Broken	1,382.93 F	*1,382.93 F
201	1	*LH DOOR TRIANGLE TRIM	Missing	225.31 F	*225.31 F
202	1	*LOWER DOOR PERIMETER SEAL (2PCS)	Necessary	574.47 F	*574.47 F
203	1	*LH DOOR OUTER PERIMETER SEAL	Necessary	666.19 F	*666.19 F
204	1	*LH DOOR INNER PERIMETER SEAL	Necessary	777.24 F	*777.24 F
205	1	*WINDSCREEN PERIMTER SEAL	Necessary	1,887.45 F	*1,887.45 F
206	1	*LH DOOR COSMETIC SEAL	Necessary	67.48 F	*67.48 F
207	2	*GASKET	Necessary	7.50 F	*7.50 F
208	1	*SPRAY NOZZLE (2PCS)	Missing	17.93 F	*17.93 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
209	1		*FRONT LID AIR DUCT SEAL	Broken	276.14 F	*276.14 F
210	1		*SCREW (8PCS)	Necessary	60.98 F	*60.98 F
211	1		*WASHER (8PCS)	Necessary	18.05 F	*18.05 F
212	8		*BLOCK	Necessary	11.44 F	*11.44 F
213	1		*RH FRONT LUGGAGE COMPARTMENT LID STRIKER	Necessary	19.18 F	*19.18 F
214	1		*LH FRONT LUGGAGE COMPARTMENT LID STRIKER	Necessary	19.18 F	*19.18 F
215	1		*RH COSMETIC TRIM	Broken	49.18 F	*49.18 F
216	1		*LH COSMETIC TRIM	Broken	49.18 F	*49.18 F
217	1		*FRONT S-DUCT INLET	Broken	7,494.57 F	*7,494.57 F
218	1		*STRIKER	Broken	71.05 F	*71.05 F
219	1		*LID STRIKER PLATE FILM	Broken	21.16 F	*21.16 F
220	1		*FRONT LID LOCK RELEASE BOWDEN CABLE	Missing	119.56 F	*119.56 F
221	1		*COOMPL. LID LOCK	Missing	1,132.76 F	*1,132.76 F
222	5		*CLIP	Necessary	13.50 F	*13.50 F
223	1		*COMPL. FRONT BUMPER	Missing	21,536.67 F	*21,536.67 F
224	1		*COMPL. RH LATERAL LOWER AERO FLICK	Missing	4,575.36 F	*4,575.36 F
225	1		*COMPL. LH LATERAL LOWER AERO FLICK	Missing	4,575.36 F	*4,575.36 F
226	1		*FRONT BADGE	Missing	471.11 F	*471.11 F
227	1		*NUT	Missing	3.59 F	*3.59 F
228	1		*LH LOWER LATERAL REINFORCEMENT PLATE	Missing	283.27 F	*283.27 F
229	1		*RH LOWER LATERAL REINFORCEMENT PLATE	Missing	283.27 F	*283.27 F
230	1		*BRACKET WITH COLLAR (6PCS)	Missing	17.56 F	*17.56 F
231	6		*SCREW	Necessary	22.86 F	*22.86 F
232	10		*CLIP	Necessary	39.00 F	*39.00 F
233	1		*SCREW (4PCS)	Necessary	38.42 F	*38.42 F
234	1		*CLIP (4PCS)	Necessary	9.15 F	*9.15 F
235	10		*SCREW WITH WASHER	Necessary	18.30 F	*18.30 F
236	6		*SCREW	Necessary	39.00 F	*39.00 F
237	4		*SCREW	Necessary	188.32 F	*188.32 F
238	3		*SCREW	Necessary	26.97 F	*26.97 F
239	2		*BRACKET	Necessary	76.90 F	*76.90 F
240	2		*SCREW	Necessary	16.08 F	*16.08 F
241	8		*WASHER	Necessary	19.52 F	*19.52 F
242	10		*WASHER	Necessary	33.60 F	*33.60 F
243	1		*RIVET (60PCS)	Necessary	102.00 F	*102.00 F
244	1		*COMPL. RH FRONT BUMPER MESH	Missing	658.47 F	*658.47 F
245	1		*COMPL. LH FRONT BUMPER MESH	Missing	819.75 F	*819.75 F
246	1		*LH LATERAL MESH	Missing	170.76 F	*170.76 F
247	1		*LH LATERAL MESH	Missing	170.76 F	*170.76 F
248	1		*FRONT BUMPER CABLE	Missing	366.67 F	*366.67 F
249	1		*LOWER RH AIR INTAKE	Missing	1,960.94 F	*1,960.94 F
250	1		*LOWER LH AIR INTAKE	Missing	1,960.94 F	*1,960.94 F
251	1		*LH BRACKET	Missing	50.59 F	*50.59 F
252	1		*RH BRACKET	Missing	50.59 F	*50.59 F
253	2		*SCREW	Necessary	13.00 F	*13.00 F
254	1		*COMPL. REAR BUMPER	Broken	25,129.43 F	*25,129.43 F
255	1		*COMPL. LH LIGHT UNIT CARRIER	Broken	173.41 F	*173.41 F
256	1		*COMPL. DIFFUSER	* Check	8,816.88 F	*- F
257	1		*COMPL. LUGGAGE COMPARTMENT TUB	Missing	7,053.41 F	*7,053.41 F
258	4		*SCREW	Necessary	17.44 F	*17.44 F
259	4		*WASHER	Necessary	6.92 F	*6.92 F
260	1		*COMPL. FRONT DASHBOARD SUBSTRUCTURE	Bent	886.65 F	*886.65 F
261	1		*COMPL. LOWER DASHBOARD	Broken	6,484.52 F	*6,484.52 F
262	1		*COMPL. LOWER SUBSTRUCTURE EXTENSION BRA	Bent	161.03 F	*161.03 F
263	1		*COMPL. LH LOWER TRIM - CONFIGURATION PART (NPA)	Torn	0.00 F	*- F
264	1		*AIRBAG COVER - CONFIGURATION PART	Broken	13,454.29 F	*13,454.29 F

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
265	1	*AC VENT (3PCS)	Broken (1Pc only)	1,488.86 F	*496.29 F
266	1	*COMPL. LH PASSENGER SIDE SATELLITE	Broken	3,641.48 F	*3,641.48 F
267	1	*LH DEMISTER SURROUND	Broken	79.58 F	*79.58 F
268	1	*COMPL. DEFROSTER SURROUND	Cut	872.41 F	*872.41 F
269	1	*DEFROSTER SURROUND SEAL	Necessary	12.84 F	*12.84 F
270	1	*COMPL. UPPER GRILLE	Broken	877.16 F	*877.16 F
271	1	*PASSENGER AIRBAG	Broken	2,581.87 F	*2,581.87 F
272	1	*BRACKET	Necessary	108.86 F	*108.86 F
273	1	*LH SUN VISOR - CONFIGURATION PART	Broken	2,410.76 F	*2,410.76 F
274	1	*LH WINDSCREEN PILLAR TRIM - CONFIGURATION	Broken	978.18 F	*978.18 F
275	1	*UPPER WINDSCREEN TRIM - CONFIGURATION PA	Broken	1,653.49 F	*1,653.49 F
276	1	*COMPL. MIRROR COVER	Broken	385.24 F	*385.24 F
277	1	*LH LOWER WINDSCREEN PILLAR TRIM - CONFIGUR	Broken	506.56 F	*506.56 F
278	1	*LH WINDSCREEN PILLAR BRACKET	Necessary	34.88 F	*34.88 F
279	1	*SCREW (4PCS)	Necessary	6.10 F	*6.10 F
280	1	*COMPL. LH RACING SEAT - CONFIGURATION PART (NPA)	Torn	0.00 F	*- F
281	1	*LH THREE POINT SEAT BELT	Jammed	1,349.60 F	*1,349.60 F
282	1	*RH THREE POINT SEAT BELT	Jammed	1,349.60 F	*1,349.60 F
283	1	*COMPL. INTERNAL REAR VIEW MIRROR	Missing	668.96 F	*668.96 F
284	1	*LH EXTERNAL REAR VIEW MIRROR	Missing	1,889.68 F	*1,889.68 F
285	1	*LH EXTERNAL REAR VIEW MIRROR GLASS	Missing	391.81 F	*391.81 F
286	1	*COMPL. WINDSCREEN WIPER ASSEMBLY	Broken	2,044.85 F	*2,044.85 F
287	1	*DRIVER SIDE WINDSCREEN WIPER ARM	Broken	537.91 F	*537.91 F
288	1	*PASSENGER SIDE WINDSCREEN WIPER ARM	Broken	302.79 F	*302.79 F
289	1	*DRIVER SIDE WINDSCREEN WIPER BLADE	Necessary	278.97 F	*278.97 F
290	1	*PASSENGER SIDE WINDSCREEN WIPER BLADE	Necessary	231.10 F	*231.10 F
291	2	*PROTECTIVE CAP	Missing	25.62 F	*25.62 F
292	1	*WINDSCREEN / HEADLIGHT WASHER FLUID RESER	Broken	913.08 F	*913.08 F
293	7	*CLIP	Necessary	11.48 F	*11.48 F
294	1	*MOBILE DUCT	Necessary	318.15 F	*318.15 F
295	1	*UNDERBODY FREON DELIVERY-RETURN PIPE	Missing	689.06 F	*689.06 F
296	1	*PIPR FROM HVAC TO UNDERBODY	Missing	1,010.81 F	*1,010.81 F
297	2	*BUSH	Necessary	28.42 F	*28.42 F
298	1	*PIPE FROM DISCONNECTOR TO RECEIVER DRIER	Missing	336.14 F	*336.14 F
299	2	*SQUADRA CORSE SHIELD BADGE	Necessary	3,745.58 F	*3,745.58 F
300	6	*NUT	Necessary	27.66 F	*27.66 F
301	6	*WASHER	Necessary	8.04 F	*8.04 F
302	1	*COMPL. LH UNDERDOOR TRIM	Broken	3,605.68 F	*3,605.68 F
303	1	*COMPL. CENTRE COSMETIC COVER	Missing	7,929.48 F	*7,929.48 F
304	2	*VIBRATION DAMPER	Missing	137.78 F	*137.78 F
305	1	*COMPL. RH COSMETIC TRIM	Missing	4,565.45 F	*4,565.45 F
306	4	*SCREW	Necessary	20.12 F	*20.12 F
307	2	*PLUG	Necessary	3.70 F	*3.70 F
308	1	*COMPL. LH COSMETIC TRIM	Missing	4,565.45 F	*4,565.45 F
309	6	*SCREW	Necessary	9.06 F	*9.06 F
310	6	*BLOCK	Necessary	8.40 F	*8.40 F
311	1	*COMPL. RH UNDERWINDSCREEN TRAY	Missing	6,728.03 F	*6,728.03 F
312	1	*UPPER AIR DUCT SEAL	Necessary	12.84 F	*12.84 F
313	1	*COMPL. LH UNDERWINDSCREEN TRAY	Missing	6,728.03 F	*6,728.03 F
314	2	*STABILUS GAS STRUT	Bent	221.25 F	*221.24 F
315	1	*LH UNDER WINDSCREEN TRAY PLUG	Necessary	24.00 F	*24.00 F
316	8	*WASHER	Necessary	10.40 F	*10.40 F
317	4	*FRONT FIREWALL COMPARTMENT SEAL	Necessary	22.56 F	*22.56 F
318	1	*RH LUGGAGE COMPARTMENT SEAL	Missing	270.34 F	*270.34 F
319	1	*LH LUGGAGE COMPARTMENT SEAL	Missing	270.34 F	*270.34 F
320	1	*LOW TONE HORN	Missing	143.00 F	*143.00 F
321	2	*FRONT CRASH SENSOR	Missing	180.70 F	*180.70 F
322	3	*ACCELEROMETER FOR MAGNERIDE SYSTEM	Missing	1,641.78 F	*1,641.78 F

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
323	2	*LATERAL CRASH SENSOR	Missing	181.18 F	*181.18 F
324	2	*LATERAL CRASH SENSOR	Missing	180.70 F	*180.70 F
325	1	*AIRBAG ECU	Necessary	1,083.66 F	*1,083.66 F
326	1	*RH HEADLAMP	Broken	7,106.22 F	*7,106.22 F
327	1	*LH HEADLAMP	Broken	7,106.22 F	*7,106.22 F
328	8	*SCREW	Necessary	23.04 F	*23.04 F
329	8	*WASHER	Necessary	13.68 F	*13.68 F
330	12	*WASHER	Necessary	17.16 F	*17.16 F
331	2	*COMPL LATERAL TURN INDICATOR	Missing	348.96 F	*348.96 F
332	1	*CENTRAL CEILING LIGHT UNIT	Broken	2,233.84 F	*2,233.84 F
333	1	*OUTER LH TAILLIGHT	Broken	1,506.88 F	*1,506.88 F
334	1	*INNER LH TAILLIGHT	Broken	1,522.74 F	*1,522.74 F
335	1	*HIGH TONE HORN	Missing	143.00 F	*143.00 F
336	1	*LH FRONT SPAR	Bent	1,754.51 F	*1,754.51 F

F=Franchise part.

Total Parts (\$\$) 609,222.48 583,260.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE DAMAGED ITEMS	New	134,400.00	130,560.00
2	TO SPRAY PAINT DAMAGED PANELS	New	28,800.00	28,800.00
Gross Labour Cost (S\$)			163,200.00	159,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >