

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunus Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS22006727/UVY3M4**Date:** 08/08/2022**REFERENCE**

Insured/Claimant: LEE GUOHAO ROFIENOE Policy No: MPC22P0098800
Date of Loss: 13/07/2022 Nature of Claim: OD Claim No: DMPC2200294H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGX1388R**
Make & Model: TOYOTA ESTIMA, 2.4 (A) Engine No: 2AZF032481
Reg. Date: 10/07/2007 (Man. Year: 2007) Chassis No: ACR500036413
Colour: Black Odometer: 221015 km
Engine Capacity: 2362 cc
Market Value/New Car Price: S\$45,000.00
Sum Insured (\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,239.70	8,032.20	4,207.50	34.38
Miscellaneous Items	225.00	60.00	165.00	73.33
Labour	2,100.00	1,420.00	680.00	32.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	14,564.70	9,512.20	5,052.50	34.69
Approved Total (Overridden) (\$\$)		7,600.00		
- Excess (\$\$)	0.00	250.00	-250.00	
(\$\$)	14,564.70	7,350.00	7,214.70	49.54
+ GST 7.00/7.00% (\$\$)	1,019.53	514.50	505.03	49.54
Nett Amount (\$\$)	15,584.23	7,864.50	7,719.73	49.54

INSPECTION

Date of Assignment: 14/07/2022 Present Location: SME Motor Pte Ltd (Kaki Bukit)
SME Motor Pte Ltd (Kaki Bukit)
Date Inspected: 15/07/2022 Inspected At: 1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit
Singapore 417883
Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Aug 2022)
Parts:	M1-MPV	TOYOTA ESTIMA 2.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGX1388R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BONNET (WCP)	Buckled	215.00 F	*215.00 F
2	2		*FRT BONNET HINGE (WCP)	Bent	76.00 F	*76.00 F
3	1		*FRT BONNET LOCK (WCP)	Bent	65.00 F	*65.00 F
4	1		*FRT BONNET INSULATOR (WCP)	Torn	125.00 F	*125.00 F
5	8		*INSULATOR CLIP (WCP)	Necessary	16.00 F	*16.00 F
6	1		*FRT BONNET LOCK CABLE (WCP)	Jammed	55.00 F	*55.00 F
7	1		*FRT GRILLE ASSY (WCP)	Broken	190.00 F	*190.00 F
8	1		*FRT GRILLE LOGO (WCP)	Missing	65.00 F	*65.00 F
9	4		*FRT GRILLE CLIP (WCP)	Missing	8.00 F	*8.00 F
10	1		*FRT BUMPER (WCP)	Distorted	850.00 F	*850.00 F
11	2		*FRT BUMPER RETAINER (WCP)	Bent	76.00 F	*76.00 F
12	10		*FRT BUMPER CLIP (WCP)	Necessary	20.00 F	*20.00 F
13	1		*FRT BUMPER INNER SPONGE (WCP)	Torn	65.00 F	*65.00 F
14	1		*FRT BUMPER REINFORCEMENT (WCP)	Bent	185.00 F	*185.00 F
15	1		*FRT BUMPER CENTER BEAM (WCP)	Bent	95.00 F	*95.00 F
16	1		*RFT BUMPER LOWER GRILLE (WCP)	Torn	95.00 F	*95.00 F
17	2		*HEADLAMP (WCP)	Broken	1,500.00 F	*1,500.00 F
18	1		*HEADLAMP SUPPORT PANEL ASSY (WCP)	Bent	550.00 F	*550.00 F
19	1		*BRACE PANEL (WCP)	Bent	45.00 F	*45.00 F
20	1		*SUPPORT TOP GARNISH (WCP)	Distorted	125.00 F	*125.00 F
21	8		*TOP GARNISH CLIP (WCP)	Necessary	16.00 F	*16.00 F
22	1		*AIRCON CONDENSER (WCP)	Bent / Punctured	550.00 F	*550.00 F
23	1		*RADIATOR (WCP)	Bent / Punctured	565.00 F	*565.00 F
24	1		*RADIATOR TOP GARNISH (WCP)	Cracked	75.00 F	*75.00 F
25	1		*RADIATOR FAN COWLING (WCP)	Cracked	185.00 F	*185.00 F
26	1		*RADIATOR FAN MOTOR (WCP)	Jammed	195.00 F	*195.00 F
27	1		*RADIATOR FAN BLADE (WCP)	Cracked	95.00 F	*95.00 F

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*AIRCON FAN MOTOR (WCP)	Jammed	195.00 F	*195.00 F
29	1		*AIRCON FAN BLADE (WCP)	Cracked	95.00 F	*95.00 F
30	2		*AIRCON SIDE DEFLECTOR (WCP)	Not Necessary	90.00 F	*- F
31	2		*AIRCON CONDENSER TOP BRACKET (WCP)	Not Necessary	50.00 F	*- F
32	2		*RADIATOR TOP BRACKET (WCP)	Twisted	50.00 F	*50.00 F
33	1		*WASHER TANK (WCP)	Not Necessary	95.00 F	*- F
34	1		*WASHER TANK NECK (WCP)	Not Necessary	35.00 F	*- F
35	1		*RADIATOR SPARE TANK (WCP)	Cracked	170.00 F	*170.00 F
36	1		*AIRCON COOLING PIPE (WCP)	Not Necessary	385.00 F	*- F
37	1		*AIRCON DISCHARGE PIPE (WCP)	Not Necessary	245.00 F	*- F
38	1		*AIRCON SUCTION PIPE (WCP)	Not Necessary	315.00 F	*- F
39	1		*AIR DUCT (WCP)	Not Necessary	95.00 F	*- F
40	1		*AIR CLEANER BOX (WCP)	Not Necessary	400.00 F	*- F
41	1		*BATTERY BRACKET (WCP)	Not Necessary	35.00 F	*- F
42	1		*FRT EXHAUST MANIFOLD COVER (TOP) (WCP)	Not Necessary	175.00 F	*- F
43	2		*HID UNIT (WCP)	Damaged	690.00 F	*690.00 F
44	2		*HID BULB (WCP)	Not Necessary	440.00 F	*- F
45	1		*ALTERNATOR (WCP)	Not Necessary	850.00 F	*- F
46	1		*FAN BELT (WCP)	Not Necessary	115.00 F	*- F
47	1		*FRT ENGINE MOUNTING (WCP)	Not Necessary	85.00 F	*- F
48	1		*REAR ENGINE MOUNTING (WCP)	Not Necessary	105.00 F	*- F
49	1		*RH ENGINE MOUNTING (WCP)	Not Necessary	155.00 F	*- F
50	1		*LH ENGINE MOUNTING (WCP)	Not Necessary	155.00 F	*- F

F=Franchise part.

Sub Total (\$\$)	11,127.00	7,302.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	1,112.70	730.20
Total Parts (\$\$)	12,239.70	8,032.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	BATTERY (Not Necessary)	160.00	0.00
2	1	FRT NUMBER PLATE (Cracked)	40.00	35.00
3	1	RADIATOR COOLANT (Necessary)	25.00	25.00
Sub Total (\$\$)			225.00	60.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WIRE CHECKING	New	30.00	20.00
2	REMOVE & REFIX AIRCON AND GAS	New	100.00	100.00
3	REMOVE & REFIX ALTERNATOR & FAN BELT	New	120.00	0.00
4	REMOVE & REFIX 1 SET ENGINE MOUNTING	New	150.00	0.00
5	LABOUR CHARGE	New	850.00	700.00
6	SPRAY PAINTING	New	850.00	600.00
Gross Labour Cost (\$\$)			2,100.00	1,420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >