

ASS. REC. BY:

REF:

CS/III22006729/Kqy3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

MFL2022D0003373

Sum Insured:

Excess:

1500

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$150k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

21

days

Res.: Yes or No

Lum Sum:

1.81 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

15/07/22@5.05pm revert to III via Merimen.

21/07/22@4.30pm Meena informed C/A at \$20K via Merimen.

25/07/22@10.40am Informed Patrick C/A not more than \$20K or whichever lower & ex:\$1500.

16/03/23 finalised LS \$18750 with Aileen (Red \$9539.40, 34%)

Veh No:

SNC 457J

Yr Regn:

09, 21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Freed

Wagon

Colour

m-Black

c.c

1496

Sp.Reading

A/C: Insured / Std / NI / NA

EngNo:

T/Radio: Insured / Std / NI / NA

C/No:

GB7 3132638

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / Rim or

Tyre Size:

F: Dun

185/65R15

R: Davanti

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

9

mm

L/Bal.

7

mm

L/Bal.

9

mm

D.O.A.

26/8/22

D.O.I.

15/7/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear & RT N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

16/03 Typist

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

21

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

S + RS, SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format: MER-OD

Lump Sum T.B.T. (\$ 18750

Repairer Estimates
ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

205 Braddell Road
Singapore 579701

Tel: 63837613 Fax: 62815767/65462533 Email: teokeejin@cdge.com.sg

INSURER:

India International Insurance Pte Ltd (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	D18MFL0003414-02	Date of Loss:	26/06/2022
Vehicle Reg. No.:	SNC457J	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	COMFORTDELGRO RENT-A-CAR PTE LTD		

Make/Model:	HONDA FREED HYBRID, 1.5 G (A)	Vehicle Reg. Date:	27/09/2021
Vehicle Colour:	BLACK		
Engine No:	LED7238892	Chassis No:	GB73132638
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	21 ✓		

Not Ashwin
Mercury B&P
Extra TBA

Present Location: COMFORTDELGRO ENGINEERING PTE LTD (BRADDELL)

COST OF CLAIMS	Amount
Parts	20,303.12
Miscellaneous Items	11.00
Labour	6,900.00
Paintwork Labour	0.00
Polishing	0.00
Gross Total (S\$)	27,214.12
+ GST 7.00% (S\$)	1,904.99
Nett Amount (S\$)	29,119.11

This claim is handled by: **PATRICK TIA JEE KIANG**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

DETAILS

Repairer Estimates

Source: MRM-SG Version: 1.0 (Last Synchronised: 14 Jul 2022)
 M1-MPV HONDA FREED HYBRID 1.5 G (A) (Catalogue:Merimen Singapore 1.0)
 Repairer's (Price-denominated Standard List)
 Print Code: ComfortDelGro Engineering Pte Ltd/SNC457J/14/07/2022 17:19
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No. Qty Part No. Particulars

			%Disc	%Depr	Amount	
1	1	*FRT RH FENDER				
2	1	*FRT RH FENDER INNER SHIELD	20	0.00	*441.00 F	X
3	8	*FRT RH FENDER INNER SHIELD CLIP	20	0.00	*150.00 F	X
4	1	*FRT LH FENDER	20	0.00	*31.20 F	X
5	1	*FRT LH FENDER INNER SHIELD	20	0.00	*441.00 F	✓
6	8	*FRT LH FENDER INNER SHIELD CLIP	20	0.00	*150.00 F	✓
7	1	*FRT LH FENDER HYBRID BADGE	20	0.00	*31.20 F	✓
8	1	*FRT LH QUATER GLASS	20	0.00	*66.00 F	✓
9	1	*FRT LH FENDER LOWER PANEL(OUTER)	20	0.00	*510.00 F	?
10	1	*FRT LH FENDER LOWER PANEL(INNER)	20	0.00	*191.00 F	✓
11	1	*FRT LH FENDER LOWER PANELSUPPORT BRACKET	20	0.00	*210.00 F	✓
12	1	*FRT LH RIM 15	20	0.00	*150.00 F	✓
13	1	*FRT LH TYRE9DUNLOP ENASAVE EC300/185/65R15	0	0.00	*401.00 FS	✓
14	1	*FRT LH WHEEL HUB	0	0.00	*250.00 FS	
15	1	*FRT LH WHEEL HUB BEARING	20	0.00	*201.00 F	✓
16	1	*FRT LH KUNCKLE ARM	20	0.00	*196.00 F	✓
17	1	*FRT LH LOWER ARM	20	0.00	*351.00 F	✓
18	1	*FRT LH SHOCK ABSORBER	20	0.00	*291.00 F	✓
19	1	*FRT LH SHOCK ABSORBER TOP MOUNTING	20	0.00	*350.00 F	✓
20	1	*LH STEERING TIE ROD	20	0.00	*48.00 F	?
21	1	*LH STEERING TIE ROD END	20	0.00	*121.00 F	?
22	1	*FRT WINDSCREEN GLASS	20	0.00	*99.00 F	?
23	1	*FRT WINDSCREEN GLASS MOULDING	20	0.00	*1,800.00 F	✓
24	1	*SEALANT	20	0.00	*60.00 F	✓
25	1	*INNER SEAL	0	0.00	*40.00 FS	✓
26	1	*ERP BRACKET	0	0.00	*30.00 FS	✓
27	1	*PHV	0	0.00	*26.00 FS	✓
28	1	*AIRBAG CONTROL UNIT	0	0.00	*50.00 FS	✓
29	1	*FRT AIR BAG CRASH SENSOR LH	20	0.00	*854.00 F	✓
30	1	*FRT AIR BAG CRASH SENSOR RH	20	0.00	*104.00 F	✓
31	1	*FRT BUMPER	20	0.00	*104.00 F	✓
32	1	*FRT BUMPER SIDE RETAINER RH	20	0.00	*898.00 F	✓
33	1	*FRT BUMPER SIDE RETAINER LH	20	0.00	*22.00 F	✓
34	10	*FRT BUMPER CLIP	20	0.00	*22.00 F	✓
35	1	*FRT NUMBER PLATE	20	0.00	*38.00 F	✓
36	1	*RADIATOR GRILLE	0	0.00	*45.00 FS	✓
37	1	*FRT BUMPER UPPER AIRDUCT	20	0.00	*982.00 F	✓
38	1	*FRT BUMPER LOWER CENTER GRILLE	20	0.00	*36.00 F	?
39	1	*FRT BUMPER RH SIDE COVER	20	0.00	*165.00 F	✓
40	1	*FRT BUMPER LH SIDE COVER	20	0.00	*241.00 F	✓
41	1	*FRT BUMPER LOWER GRILLE COVER RH	20	0.00	*241.00 F	✓
42	1	*FRT BUMPER LOWER GRILLE COVER LH	20	0.00	*91.00 F	?
43	1	*FRT BUMPER INFORCEMENT	20	0.00	*89.00 F	✓
			20	0.00	*332.00 F	✓

ComfortDelGro Engineering Pte Ltd/SNC457J/14/07/2022 17:19. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Repairer Estimates

Part No.	Particulars	%Disc	%Depr	Amount	
	*RH HEADLAMP	20	0.00	*1,454.00 F	✓
	*RH HEADLAMP LOWER BRACKET	20	0.00	*36.00 F	✓
	*LH HEADLAMP	20	0.00	*1,454.00 F	✓
	*LH HEADLAMP LOWER BRACKET	20	0.00	*36.00 F	?
	*WIPER TANK	20	0.00	*90.00 F	✓
	*FRT SUPPORT PANEL TOP	20	0.00	*753.00 F	?
	*FRT RH FENDER LOWER PANEL(OUTER)	20	0.00	*191.00 F	✓
	*FRT RH FENDER LOWER PANEL(INNER)	20	0.00	*210.00 F	X
	*FRT RH FENDER LOWER SUPPORT BRACKET	20	0.00	*150.00 F	X
	*FRT RH FENDER INNER SHIELD	20	0.00	*120.00 F	✓
	*STEERING WHEEL AIRBAG	20	0.00	*2,400.00 F	✓
	*STEERING WHEEL AIRBAG CLOCK SPRING	20	0.00	*283.00 F	✓
	*FRT LH PASSENGER AIRBAG	20	0.00	*3,201.00 F	✓
	*FRT DASHBOARD	20	0.00	*750.00 F	✓
	*FRT RH SEAT BELT	20	0.00	*602.00 F	✓
	*FRT LH SEAT BELT	20	0.00	*602.00 F	✓
	*REAR RH FENDER	20	0.00	*912.00 F	✓
	*REAR BUMPER	20	0.00	*950.00 F	X
	*REAR RH BUMPER RETAINER	20	0.00	*25.00 F	X

chise part. S=SpcNett.

Sub Total (\$\$)	25,168.40
- List Item Discount on L Items (\$\$)	4,865.28
Total Parts (\$\$)	20,303.12

ComfortDelGro Engineering Pte Ltd/SNC457J/14/07/2022 17:19. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Miscellaneous Items

ous Items

OD/TP Case (Insurer)

Amount

11.00

Sub Total (\$\$)

11.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	TO CUT WELD FRT PANEL,JACK STRAIGHTEN FRT CHASSIS,CUT FENDER LOWER PANEL,REPLACE DAMAGE PARTS AND REALIGN AFFECTED AREAS	New	1000	1,300.00
2	TO PUTTY,RESPRAY ON FRT BONNET,FRT BUMPER,BOTH FENDER,CHASSIS FRAME,FRT LH DOOR AND AFFECTED AREAS	New	1750	1,500.00
3	REMOVE RADIATOR AND CONDENSOR TO ASSIST REPAIR AND REPLACE	New	100	150.00
4	TO VACCUM AND RECHARGE AIRCON GAS	New		80.00
5	TO REMOVE FRT WINDSCREEN GLASS TO ASSIST REPAIR AND REPLACE	New		120.00 ✓
6	REMOVE FRT DASHBOARD TO ASSIST REPAIR AND REPLACE	New		250.00 ✓
7	TO REPLACE STEERING AIRBAG ,CLOCK SPRING,PASSENGER AIRBAG AND SRS CONTROL UNIT	New	280	400.00
8	TO REMOVE AND REPLACE BOTH FRT SEAL BELT	New	80	200.00
9	TO RESET AND RE-PROGRAM ECU/AIRBAG SYSTEM	New	280	400.00
10	TO CUT WELD ON REAR RH FENDER AND REPLACEMENT.REPLACE REAR BUMPER AND REALIGN AFFECTED AREAS	New	750	1,000.00
11	TO PUTTY,RESPRAY ON RH REAR FENDER ,RR BUMPER AND AFFECTED AREAS	New	500	800.00
12	TO REMOVE INTERIOR UPHOLSTERY TO ASSIST REPAIR AND REFIT	New	100	150.00
13	TO DISMANTLE FRT LH SUSPENSION TO ASSIST REPAIR AND REPLACE. (RIM,TYRE,KUNCKLE ARM,LOWER ARM,ABSORBER ETC.)	New	200	300.00
14	TO CHECK AND ADJUST WHEEL ALIGNMENT	New	60	100.00
15	TO TUFF KOTE ON REAR AFFECTED AREAS	New	NI	150.00 X
Gross Labour Cost (\$\$)				6,900.00

ComfortDelGro Engineering Pte Ltd/SNC457J/14/07/2022 17:19. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >