

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS22006731/KCY3M4**Date:** 26/08/2022REFERENCE

Handling Insurer: ECICS Limited Policy No:

Claimant Vehicle No : SMH3373H **Insured Vehicle No :** SMQ8873B

Date of Loss: 30/06/2022 Nature of Claim: TP Claim No: DMC2200117H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMH3373H**

Make & Model: TOYOTA HARRIER, 2.0 M GRADE (A) Engine No: 8ARZ148783

Reg. Date: 18/01/2019 (Man. Year: 2018) Chassis No: JTEZB3GH60J004171

Colour: Metallic Pearl White Odometer: 38015 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R18 Rear Tyre Size: 235/55 R18

Front Left Side: Bridgestone 3 mm Rear Left Side: Bridgestone 3 mm

Front Right Side: Bridgestone 3 mm Rear Right Side: Bridgestone 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,861.08	730.00	2,131.08	74.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,110.00	1,210.00	900.00	42.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	4,971.08	1,940.00	3,031.08	60.97

INSPECTION

Date of Assignment: 15/07/2022

Date Inspected: 19/07/2022 Inspected At: Tat Heng Motor Works (HQ)
Blk 10 Ang Mo Kio Ind Park 2A, #02-09 AMK
Autopoint
Singapore 568047

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 26 Aug 2022)

Parts: M1-SUV TOYOTA HARRIER 2.0 M GRADE (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMH3373H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	811.30 FL	*- FL
2	1		*FRONT RH FENDER	Repair	1,446.30 FL	*- FL
3	1		*FRONT RH DOOR (NPA)	Respray	0.00 FL	*- FL
4	1		*SET FENDER CLIPS	Not Necessary	35.00 FS	*- FS
5	1		*FRONT RH TYRE	Serviceable	290.00 FS	*- FS
6	1		*FRONT RH TYRE RIM	Dented/Cut	730.00 FS	*730.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,312.60	730.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	451.52	0.00
Total Parts (\$\$)	2,861.08	730.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	ADJUST WHEEL ALIGNMENT	New	60.00	60.00
2	TO REPLACE,REPAIR,STRAIGHTEN & RE-ALIGN ALL DAMAGED PARTS	New	850.00	400.00
3	TO SPRAY PAINT ON ALL AFFECTED AREAS	New	1,200.00	750.00
Gross Labour Cost (\$)			2,110.00	1,210.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >