

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/III22006737/APA3Q2**Date:** 10/03/2023**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549_02

Claimant Vehicle No : SLF8293U**Insured Vehicle No :** GBH622P

Date of Loss: 14/07/2022

Nature of Claim: TP

Claim No: MFL2022D0003830

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLF8293U**

Make & Model: TOYOTA COROLLA AXIO, 1.5 X (A)

Engine No: 2NR8493105

Reg. Date: 03/06/2016 (Man. Year: 2015)

Chassis No: NRE1610008929

Colour: Blue

Odometer: 160430 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60 R15

Rear Tyre Size: 195/60 R15

Front Left Side: Falken 6 mm

Rear Left Side: Falken 6 mm

Front Right Side: Falken 6 mm

Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,270.41	4,804.72	5,465.69	53.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,660.00	1,450.00	2,210.00	60.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,930.41	6,254.72	7,675.69	55.10
Approved Total (Overridden) (S\$)		5,000.00		
Nett Amount (S\$)	13,930.41	5,000.00	8,930.41	64.11
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		38.45		
Nett Liability (S\$)		5,338.45		
Global Sum Settlement (S\$)		5,330.00		

INSPECTION

Date of Assignment: 25/07/2022

Date Inspected: 25/07/2022 Inspected At:

HD Perfect Autowork Pte Ltd (HQ)

8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit

Singapore 415875

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Oct 2022)
Parts:	143	TOYOTA COROLLA AXIO 1.5 X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLF8293U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,552.20 FL	*563.00 FL
2	2		*FRONT BUMPER FOGLAMP COVER	Not Necessary	124.80 FL	*- FL
3	1		*FRONT BUMPER TOWING COVER	Not Necessary	35.90 FL	*- FL
4	1		*FRONT BUMPER LOWER GRILLE	Cracked	165.10 FL	*165.10 FL
5	2		*FRONT BUMPER SIDE RETAINER	Necessary	117.80 FL	*117.80 FL
6	1		*FRONT BUMPER REINFORCEMENT	Dented	379.00 FL	*379.00 FL
7	1		*FRONT BUMPER SPONGE	Cracked	90.20 FL	*90.20 FL
8	2		*FRONT FENDER INNER COWLING	Not Necessary	344.20 FL	*- FL
9	1		*FRONT RADIATOR GRILLE WITH LOGO	Cracked	818.40 FL	*485.00 FL
10	1		*FRONT RADIATOR TOP RUBBER	Not Necessary	38.90 FL	*- FL
11	2		*HEADLAMP	Cracked	1,943.20 FL	*1,943.20 FL
12	1		*ENGINE UNDER COVER GARNISH	Not Necessary	185.81 FL	*- FL
13	1		*BONNET	Repair	871.50 FL	*- FL
14	2		*BONNET HINGE	Not Necessary	117.80 FL	*- FL
15	2		*BONNET STOPPER	Not Necessary	51.40 FL	*- FL
16	1		*BONNET LOCK	Not Necessary	135.10 FL	*- FL
17	1		*FRONT SUPPORT PANEL	Buckled	1,294.30 FL	*889.00 FL
18	1		*FRONT SUPPORT PANEL LOWER FRONT GARNISH	Not Necessary	162.60 FL	*- FL
19	1		*FRONT BRACE PANEL	Bent	180.40 FL	*180.40 FL
20	1		*HORN	Not Necessary	135.70 FL	*- FL
21	1		*AIR CONDENSOR	Warped	1,567.30 FL	*1,338.00 FL
22	1		*RADIATOR	Not Necessary	2,072.80 FL	*- FL
23	4		*RADIATOR MOUNTING	Not Necessary	96.80 FL	*- FL
24	2		*RADIATOR SIDE GARNISH	Not Necessary	96.40 FL	*- FL
25	1		*RADIATOR TOP SUPPORT GARNISH	Deformed	95.60 FL	*95.60 FL
26	1		*RADIATOR UPPER GUARD	Not Necessary	98.00 FL	*- FL
27	1		*RADIATOR LOWER GUARD	Not Necessary	96.00 FL	*- FL
28	1		*FRONT NUMBER PLATE	Dented	80.00 FS	*50.00 FS
29	1		*SET FRONT BUMPER CLIP	Necessary	120.00 FS	*30.00 FS
30	1		*FRONT BUMPER INNER BOTTOM GARNISH CLIP	Not Necessary	60.00 FS	*- FS
31	1		*SET FRONT FENDER INNER COWLING LH	Not Necessary	50.00 FS	*- FS
32	1		*BONNET SEALANT	Not Necessary	80.00 FS	*- FS
33	1		*FRONT SUPPORT PANEL SEALANT	Not Necessary	80.00 FS	*- FS
34	1		*SET RADIATOR SIDE GARNISH CLIP	Not Necessary	50.00 FS	*- FS
35	1		*SET RADIATOR AIR GUARD GARNISH CLIP	Not Necessary	60.00 FS	*- FS
36	1		*RADIATOR COOLANT	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	13,487.21	6,366.30
- List Item Discount on L Items 25.00/25.00% (S\$)	3,216.80	1,561.58
Total Parts (S\$)	10,270.41	4,804.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVING AND REPLACING PARTS	New	1,600.00	700.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,600.00	600.00
3	REFOCUS HEADLAMP BEAM	New	80.00	30.00
4	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	New	120.00	60.00
5	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	80.00	60.00
6	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (S\$)			3,660.00	1,450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >