

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22006741/KCY3E2**Date:** 11/10/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	SNM22D204924
Claimant Vehicle No :	SLC2732A	Insured Vehicle No :	PC3279M
Date of Loss:	13/07/2022	Nature of Claim:	TP
		Claim No:	SNM22D204924/C02/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLC2732A		
Make & Model:	PEUGEOT 5008, 1.6 D BLUEHDI EAT6 S/R (A)	Engine No:	10JBHC3027056
Reg. Date:	09/05/2016 (Man. Year: 2015)	Chassis No:	VF30EBHZTFS309443
Colour:	Metallic Grey	Odometer:	107492 km
Engine Capacity:	1560 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/50 R17	Rear Tyre Size:	215/50 R17
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,650.75	3,155.85	1,494.90	32.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	940.00	435.00	505.00	53.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	5,590.75	3,590.85	1,999.90	35.77
+ GST 7.00/7.00% (\$\$)	391.35	251.36	139.99	35.77
Nett Amount (\$\$)	5,982.10	3,842.21	2,139.89	35.77

INSPECTION

Date of Assignment:	15/07/2022	
Date Inspected:	20/07/2022 Inspected At:	Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint Singapore 568047
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 11 Oct 2022)

Parts: M1-SUV PEUGEOT 5008 1.6 D BLUEHDI EAT6 S/R (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLC2732A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP LH	Cut	1,541.00 FL	*1,541.00 FL
2	1		*FRONT GRILLE	Serviceable	365.00 FL	*- FL
3	1		*FRONT GRILLE CHROME MLDG	Scratched	412.00 FL	*412.00 FL
4	1		*FRONT BUMPER	Buckled	1,382.00 FL	*1,382.00 FL
5	1		*FRONT BUMPER SIDE RETAINER LH	Distorted	89.00 FL	*89.00 FL
6	15		*FRONT BUMPER CLIPS	Necessary	82.50 FL	*82.50 FL
7	1		*FRONT BUMPER LOWER AIR GRILLE	Serviceable	221.00 FL	*- FL
8	1		*FRONT BUMPER REINFORCEMENT	Repair	461.00 FL	*- FL
9	1		*FRONT BUMPER CTR BRT	Repair	282.00 FL	*- FL
10	1		*FOGLAMP LH	Serviceable	154.00 FL	*- FL
11	1		*FOGLAMP COVER LH	Serviceable	178.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	5,167.50	3,506.50
- List Item Discount on L Items 10.00/10.00% (\$\$)	516.75	350.65
Total Parts (\$\$)	4,650.75	3,155.85

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING	New	40.00	15.00
2	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD. TO KNOCK & REPAIR FRONT FENDER RH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME	New	400.00	200.00
3	TO SPRAY FRONT FENDER LH, FRONT BUMPER	New	500.00	220.00
Gross Labour Cost (\$\$)			940.00	435.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >