

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22006745/EQY3Q2**Date:** 05/10/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNA00012282101

Claimant Vehicle No : SMK1755L **Insured Vehicle No :** SLH2142B

Date of Loss: 11/07/2022 Nature of Claim: TP Claim No: SNM22D204893/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMK1755L**

Make & Model: KIA CERATO, 1.6 LX (A) Engine No: G4FGJH722038

Reg. Date: 29/03/2019 (Man. Year: 2018) Chassis No: KNAF1416MK5031074

Colour: Grey Odometer: 32849 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16

Front Left Side: Michelin 4 mm Rear Left Side: Michelin 4 mm

Front Right Side: Michelin 4 mm Rear Right Side: Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,717.00	3,433.00	1,284.00	27.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,860.00	5,560.00	3,300.00	37.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,577.00	8,993.00	4,584.00	33.76
+ GST 7.00/7.00% (S\$)	950.39	629.51	320.88	33.76
Nett Amount (S\$)	14,527.39	9,622.51	4,904.88	33.76

INSPECTION

Date of Assignment: 14/07/2022

Date Inspected: 29/08/2022 Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 8.0 days

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Oct 2022)
Parts:	143	KIA CERATO 1.6 LX (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMK1755L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
2	1		*COVER -RR BUMPER	Broken	651.00 FS	*651.00 FS
3	1		*COVER -RR BUMPER LWR	Broken	241.00 FS	*241.00 FS
4	1		*COVER -RR BUMPER UNDER ,LH	Broken	33.00 FS	*33.00 FS
5	1		*COVER -RR BUMPER FOG LAMP ,LH	Cut	19.00 FS	*19.00 FS
6	1		*LAMP ASSY -SIDE T/SIGNAL ,LH	Cut	201.00 FS	*201.00 FS
7	1		*BRACKET -RR BEAM UPR MTG ,LH	Not Necessary	9.00 FS	*- FS
8	1		*BEAM -RR BUMPER	Broken	318.00 FS	*318.00 FS
9	1		*STAY -RR BUMPER RH	Not Necessary	65.00 FS	*- FS
10	1		*STAY -RR BUMPER LH	Bent	65.00 FS	*65.00 FS
11	1		*BRACKET ASSY -RR BPR SIDE UPR, L	Not Necessary	25.00 FS	*- FS
12	1		*BRACKET ASSY -RR BPR SIDE UPR,R	Not Necessary	31.00 FS	*- FS
13	1		*LOGO ASSY -KIA SUB	Necessary	32.00 FS	*32.00 FS
14	1		*EMBLEM -CERATO	Necessary	28.00 FS	*28.00 FS
15	1		*PANEL ASSY -TRUNK LID	Dented	1,491.00 FS	*1,491.00 FS
16	1		*PANEL ASSY ,BACK	Dented	324.00 FS	*324.00 FS
17	1		*HINGE ASSY -TRUNK LID ,LH	Not Necessary	97.00 FS	*- FS
18	1		*HINGE ASSY -TRUNK LID ,RH	Not Necessary	97.00 FS	*- FS
19	1		*LATCH ASSY -TRUNK LID	Not Necessary	112.00 FS	*- FS
20	1		*W/STRIP-TRUNK LID OPNG	Not Necessary	100.00 FS	*- FS
21	1		*LAMP ASSY -REAR COMB OUTSIDE ,LH	Not Necessary	402.00 FS	*- FS
22	1		*LAMP ASSY -REAR COMB INSIDE ,LH	Not Necessary	346.00 FS	*- FS
23	10		*CLIPS	Necessary	10.00 FS	*10.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **4,717.00** **3,433.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW REAR BUMPER ,BOOTLID ,REAR END PANEL,REPAIR REAR LAMP HOUSING LH	New	3,200.00	1,280.00
2	REMOVE & INSTALL PARKING SENSOR	New	100.00	80.00
3	SPRAY PAINT FOR REAR BUMPER ,BOOTLID ,REAR END PANEL REAR LAMP HOUSING LH	New	2,200.00	1,100.00
4	REMOVE & INSTALL REAR COMPARTMENT TRIMS	New	300.00	300.00
5	C&C LOGO	New	50.00	50.00
6	APPLY SEALANT FOR ACCIDENT PORTION	New	80.00	40.00
7	SUPPLY PARKING SENSOR	New	220.00	0.00
8	CHECK WIRING & ELECTRICAL SYSTEM	New	50.00	50.00
9	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRICAL CONTROL SYSTEM	New	280.00	280.00
10	REPLACE REAR END PANEL ,REPAIR REAR FLOOR PANEL & LH REAR FENDER	New	1,280.00	1,280.00
11	RESPRAY REAR END PANEL ,REPAIR REAR FLOOR PANEL & LH REAR FENDER	New	1,100.00	1,100.00
Gross Labour Cost (\$\$)			8,860.00	5,560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >