

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22006755/KPA3Q2**Date:** 12/05/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7990000051
Claimant Vehicle No :	SHD357E	Insured Vehicle No :	SLE8651A
Date of Loss:	10/07/2022	Nature of Claim:	TP
		Claim No:	1711292428SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD357E		
Make & Model:	RENAULT LATITUDE, 2.0 DCI AUTO D/AB 4DR (A)	Engine No:	M9R8839C003042
Reg. Date:	17/05/2016 (Man. Year: 2015)	Chassis No:	VF1ABL15AUC282678
Colour:	Metallic White/Red	Odometer:	750688 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Sailun 7 mm	Rear Left Side:	Sailun 8 mm
Front Right Side:	Sailun 7 mm	Rear Right Side:	Sailun 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,844.10	2,706.32	4,137.78	60.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,880.00	890.00	6,990.00	88.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,724.10	3,596.32	11,127.78	75.58
Approved Total (Overridden) (S\$)		2,900.00		
Nett Amount (S\$)	14,724.10	2,900.00	11,824.10	80.30
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	13/07/2022		
Date Inspected:	13/07/2022	Inspected At:	Trans-cab Auto Services Pte Ltd No 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	2.0 days		

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT	Bent / Cracked	747.20 FL	*747.20 FL
2	1		*BUMPER UNDERTRAY FRT	Serviceable	292.50 FL	*- FL
3	1		*BUMPER SPOILER FRT	Distorted	344.70 FL	*344.70 FL
4	1		*BUMPER ABSORBER FRT	Serviceable	394.68 FL	*- FL
5	1		*BUMPER BRACKET KIT FRT LH	Serviceable	101.40 FL	*- FL
6	1		*BUMPER RETAINER FRT LH	Serviceable	101.40 FL	*- FL
7	1		*BUMPER BRACKET KIT FRT RH	Serviceable	101.40 FL	*- FL
8	1		*BUMPER RETAINER FRT RH	Cracked	101.40 FL	*101.40 FL
9	1		*BUMPER SUPPORT FRT	Serviceable	10.70 FL	*- FL
10	1		*BUMPER BRACKET FRT RH (HEADLAMP LOWER)	Cracked	116.47 FL	*116.47 FL
11	1		*BUMPER GRILLE LOWER FRT	Serviceable	147.00 FL	*- FL
12	1		*BUMPER FOG LAMP GRILLE LH	Serviceable	207.21 FL	*- FL
13	1		*BUMPER FOG LAMP GRILLE RH	Serviceable	207.21 FL	*- FL
14	1		*TOW COVER FRT	Serviceable	60.90 FL	*- FL
15	1		*FENDER PANEL FRT RH	Bent	437.10 FL	*437.10 FL
16	1		*WHEELARCH FRT RH	Cracked	191.40 FL	*191.40 FL
17	1		*BUMPER UNDERTRAY FRT	Serviceable	292.50 FL	*- FL
18	1		*RADIATOR GRILLE	Serviceable	969.90 FL	*- FL
19	1		*RADIATOR GRILLE BADGE RENAULT	Serviceable	225.36 FL	*- FL
20	1		*RADIATOR GRILLE FRAME	Serviceable	686.00 FL	*- FL
21	1		*FRAME FULL SUPPORT PANEL	Serviceable	592.70 FL	*- FL
22	1		*WIPER RESERVOIR	Dented	179.60 FL	*179.60 FL
23	1		*HEADLAMP RH	Mtg Cracked	743.60 FL	*743.60 FL
24	1		*FRONT BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
25	1		*LICENSE PLATE WITH HOLDER FRT	Serviceable	121.00 FS	*- FS
26	1		*FENDER LINER CLIP	Necessary	65.00 FS	*65.00 FS
27	1		*FRONT UNDERTRAY CLIP	Not Necessary	65.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,569.33	2,992.47
- List Item Discount on L Items 10.00/10.00% (\$\$)	725.23	286.15
Total Parts (\$\$)	6,844.10	2,706.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT REAR BIG AND SMALL W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	300.00	0.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	440.00
3	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	3,000.00	400.00
4	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
5	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00
6	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
7	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
8	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00
9	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
10	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
11	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
12	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
			Gross Labour Cost (S\$)	7,880.00
				890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >