

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 4882J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	DOOR FRT/RH (DISC 25%)	BENT	894.40	670.80
1	BUMPER REAR (DISC 25%)	SCRATCHED	458.60	343.95
10	BUMPER CLIPS @\$2.10 (DISC 25%)	NECESSARY	21.00	15.75
1	DOOR RR/RH (DISC 25%)	BENT	954.50	715.88
1	FENDER RR/RH (DISC 25%)	BENT	766.80	575.10
1	STICKER STRIDES TAXI (DOOR) (SN)	NECESSARY	60.00	60.00
1	STRIDES LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 65558888 (SN)	NECESSARY	21.60	21.60
1	HINGE LOWER RHF, DOOR	NOT NECESSARY	90.10	-
1	HINGE UPPER RHF, DOOR	NOT NECESSARY	80.50	-
1	CHECK ASSY, FR DOOR,	NOT NECESSARY	150.30	-
1	DOOR BELT FRT/RH	NOT NECESSARY	69.20	-
1	DOOR REGULATOR SUB-ASSY, FRT / REAR RH	NOT NECESSARY	224.80	-
1	DOOR REGULATOR MOTOR FRONT RH	NOT NECESSARY	947.80	-
1	SILL MEMBER OUTER RH	NOT NECESSARY	519.80	-
1	DOOR LOCK RR/RH	NOT NECESSARY	709.30	-
1	DOOR REGULATOR MOTOR FRONT RH	NOT NECESSARY	947.80	-
1	DOOR REGULATOR SUB-ASSY, FRT/REAR RH	NOT NECESSARY	224.80	-
1	DOOR HINGE LOWER RR/RH	NOT NECESSARY	72.20	-
1	CHECK ASSY, RR DOOR	NOT NECESSARY	150.30	-
1	DOOR HINGE UPPER RR/RH	NOT NECESSARY	81.70	-
1	SEALANT W/SCREEN	NOT NECESSARY	37.00	-
1	FENDER LINE RR/RH	NOT NECESSARY	141.30	-
1	SILL MEMBER PLATE RR/RH	NOT NECESSARY	57.50	-
1	TYRE	NOT NECESSARY	126.74	-
1	BUMPER SIDE RETAINER RR/RH	SERVICEABLE	94.80	-
1	QUARTER GLASS RR/RH	SERVICEABLE	846.50	-
1	WHEEL DISC	TO REPAIR SEE LABOUR	1,484.20	-
			10,241.34	2,410.88

Report Ref No. NS/INC22006757/Rce2



## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF WHEEL DISC.		1,690.00	800.00
	SPRAY PAINT.		1,872.00	950.00
	TO DO WHEEL ALIGNMENT / TYRE BALANCING.		120.00	60.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	TO CHECK WIRING AND SYSTEM FUNCTION.	NOT NECESSARY	120.00	-
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		200.00	60.00
	TO TRANSFER DOOR MECHANISM.		240.00	120.00
	TO REMOVE & REFIT REAR QUARTER GLASS RH.	NOT NECESSARY	120.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
			4,522.00	1,990.00
	GRAND TOTAL		14,763.34	4,400.88
	RECOMMENDED COST OF LUMP SUM REPAIRS			3,500.00
	(TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			3,000.00

Report Ref No. NS/INC22006757/Rce2

MOHAMMED RASUL BIN MOHD YUNUS

**Automotive Assessor** 

The

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

**REGD Auto Consultant-SAE, Licensed Appraiser**