



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 591E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	NUMBER PLATE FRAME (SN)	CRACKED	12.00	12.00
1	NUMBER PLATE (SN)	BENT	15.00	15.00
1	BRACKET, FR BUMPER	SERVICEABLE	110.40	-
1	FENDER FRT/RH	NOT NECESSARY	723.40	-
1	NAME PLATE (HYBRID)	NOT NECESSARY	51.90	-
1	FENDER PROTECTOR FRT / RH SIDE	NOT NECESSARY	113.90	-
1	FENDER SEAL TO COWL SIDE RH	NOT NECESSARY	15.20	-
1	FENDER LINER FRT / RH	NOT NECESSARY	171.70	-
1	FENDER LINER PAD, FR WHEEL RH	NOT NECESSARY	49.30	-
1	BUMPER FRT	TO REPAIR SEE LABOUR	482.00	-
			1,744.80	27.00
	<b><u>LABOUR</u></b>			
	PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF BUMPER FRT.		676.00	100.00
	SPRAY PAINT.		756.00	200.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	TO APPLY RUST-PROOFING ON AFFECTED AREA.	NOT NECESSARY	100.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
			1,692.00	300.00
	<b>GRAND TOTAL</b>		<b>3,436.80</b>	<b>327.00</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>			<b>200.00</b>

Report Ref No. NS/INC22006758/Rvce2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.