

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22006760/GVCM4**Date:** 08/12/2022**REFERENCE**

Insured/Claimant: JEREMY KOH JOON KIAT (JEREMY XU JUNJIE)

Policy No: 1800015501

Date of Loss: 29/06/2022

Nature of Claim: OD

Claim No: 8435459974SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLW4800T**

Make & Model: AUDI A4, 2.0 SEDAN TFSI S-TRONIC (NAV) (A) Engine No: CVK050345

Reg. Date: 13/02/2018 (Man. Year: 2017)

Chassis No: WAUZZZF43JA072279

Colour: Blue

Odometer: 42355 km

Engine Capacity: 1984 cc

Market Value/New Car Price: S\$115,000.00

Price:

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R18

Rear Tyre Size: 245/40 R18

Front Left Side: Goodyear 6 mm

Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,198.00	2,156.16	4,041.84	65.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,522.00	2,272.00	1,250.00	35.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,720.00	4,428.16	5,291.84	54.44
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	9,220.00	3,928.16	5,291.84	57.40
+ GST 7.00/7.00% (S\$)	645.40	274.97	370.43	57.40
Nett Amount (S\$)	9,865.40	4,203.13	5,662.27	57.40

INSPECTION

Date of Assignment: 18/07/2022

Date Inspected: 15/07/2022 Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	2,377.00 FS	*- FS
2	1		*RADIATOR GRILLE	Cracked	1,478.00 FS	*1,182.40 FS
3	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	219.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	Not Necessary	254.00 FS	*- FS
5	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	139.00 FS	*110.80 FS
6	1		*FRONT BUMPER REINFORCEMENT BEAM	Bent	899.00 FS	*719.20 FS
7	1		*FRONT BUMPER TOP COVER	Not Necessary	143.00 FS	*- FS
8	1		*CAUTION STICKER	Not Necessary	16.00 FS	*- FS
9	1		*AIR COND STICKER	Not Necessary	9.00 FS	*- FS
10	1		*FRONT BUMPER BRACKET LOCK CARRIER	Not Necessary	154.00 FS	*- FS
11	2		*FRONT BUMPER SUPPORT - LH / RH	Not Necessary	64.00 FS	*- FS
12	4		*FRONT BUMPER POP RIVET	Necessary	4.00 FS	*2.88 FS
13	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Necessary	21.00 FS	*16.32 FS
14	2		*RADIATOR AIR GUIDE INNER - LH / RH	Broken	64.00 FS	*25.60 FS
15	2		*RADIATOR AIR GUIDE OUTER - LH / RH	Not Necessary	28.00 FS	*- FS
16	1		*RADIATOR AIR GUIDE UPPER	Not Necessary	19.00 FS	*- FS
17	1		*FRONT NO PLATE	Bent	60.00 FS	*60.00 FS
18	1		*SUNDRIES	Necessary	250.00 FS	*38.96 FS
F=Franchise part. S=SpcNett.						
					Total Parts (S\$)	6,198.00 2,156.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID (S/N)	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
3	TO RESPRAY FRONT BUMPER	New	900.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK (S/N)	New	192.00	192.00
5	TO RESPRAY BONNET	New	900.00	550.00
Gross Labour Cost (S\$)			3,522.00	2,272.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >