

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22006761/GVCM4**Date:** 10/01/2023**REFERENCE**

Insured/Claimant:	CAI ZILIANG	Policy No:	2070125712		
Date of Loss:	11/07/2022	Nature of Claim:	OD	Claim No:	8945915051SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMM828G		
Make & Model:	AUDI A4, 2.0 TFSI S-TRONIC (A)	Engine No:	DEM024299
Reg. Date:	28/08/2020 (Man. Year: 2020)	Chassis No:	WAUZZZF49LN015502
Colour:	White	Odometer:	53571 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$162,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/40ZR18	Rear Tyre Size:	245/40ZR18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,931.00	1,901.60	15,029.40	88.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,422.00	1,722.00	2,700.00	61.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	21,353.00	3,623.60	17,729.40	83.03
- Excess (\$\$)	1,100.00	1,100.00	0.00	0.00
(\$\$)	20,253.00	2,523.60	17,729.40	87.54
+ GST 7.00/7.00% (\$\$)	1,417.71	176.65	1,241.06	87.54
Nett Amount (\$\$)	21,670.71	2,700.25	18,970.46	87.54

INSPECTION

Date of Assignment:	18/07/2022		
Date Inspected:	15/07/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: XING GUO QIANG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*RADIATOR BUMPER	Cut	2,377.00 FS	*1,901.60 FS
2	1	*RADIATOR BUMPER FIXING PARTS	Not Necessary	393.00 FS	*- FS
3	1	*RADIATOR BUMPER SECURING STRIP	Not Necessary	40.00 FS	*- FS
4	1	*RADIATOR BUMPER GRILLE - CENTER	Not Necessary	219.00 FS	*- FS
5	1	*RADIATOR BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	293.00 FS	*- FS
6	1	*RADIATOR BUMPER AIR GUIDE - RH	Not Necessary	51.00 FS	*- FS
7	1	*RADIATOR BUMPER CLOSING ELEMENT - UPPER CENTRE	Not Necessary	293.00 FS	*- FS
8	1	*RADIATOR BUMPER AIR GUIDE GRILLE - RH	Not Necessary	151.00 FS	*- FS
9	1	*RADIATOR BUMPER TRIM - RH	Not Necessary	54.00 FS	*- FS
10	1	*RADIATOR GRILLE	Not Necessary	1,754.00 FS	*- FS
11	1	*HORN LOW TONE - RH	Not Necessary	139.00 FS	*- FS
12	1	*HORN BRACKET - RH	Not Necessary	33.00 FS	*- FS
13	1	*RADIATOR PARKING AID SENSOR	Not Necessary	265.00 FS	*- FS
14	4	*RADIATOR PARKING AID SENSOR SEAL RING	Not Necessary	10.00 FS	*- FS
15	1	*RADIATOR BUMPER FOAM FILLER PIECE	Not Necessary	212.00 FS	*- FS
16	1	*RADIATOR BUMPER REINFORCEMENT BEAM	Not Necessary	899.00 FS	*- FS
17	1	*RADIATOR GUIDE SECTION - RH	Not Necessary	41.00 FS	*- FS
18	1	*RADIATOR BUMPER TOP COVER	Not Necessary	143.00 FS	*- FS
19	1	*CAUTION STICKER	Not Necessary	16.00 FS	*- FS
20	1	*A/C STICKER	Not Necessary	9.00 FS	*- FS
21	1	*LOCK CARRIER BRACKET	Not Necessary	154.00 FS	*- FS
22	2	*LOCK CARRIER BRACKET SUPPORT - LH / RH	Not Necessary	64.00 FS	*- FS
23	1	*LED HEADLIGHT - RH	Not Necessary	8,172.00 FS	*- FS
24	1	*LED HEADLIGHT LIFT CYLINDER - RH	Not Necessary	231.00 FS	*- FS
25	1	*LIFT CYLINDER BRACKET - RH	Not Necessary	7.00 FS	*- FS
26	1	*LIFT CYLINDER HOSE - RH	Not Necessary	107.00 FS	*- FS
27	1	*OUTSIDE TEMP SENSOR BRACKET	Not Necessary	21.00 FS	*- FS
28	1	*RADIATOR AIR DUCT GUIDE - LH	Not Necessary	51.00 FS	*- FS
29	2	*RADIATOR AIR DUCT GUIDE - RH / UPPER	Not Necessary	38.00 FS	*- FS
30	1	*FRONT WHEEL HOUSING LINER - RH	Not Necessary	262.00 FS	*- FS
31	1	*FRONT WHEEL SPOILER - RH	Not Necessary	82.00 FS	*- FS
32	1	*SUNDRIES	Not Necessary	350.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 16,931.00 1,901.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER RADIATOR WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND RADIATOR PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	700.00	-
3	TO DISMANTLE AND RENEW RADIATOR BUMPER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
4	TO RESPRAY RADIATOR BUMPER AND RHS RADIATOR FENDER	New	2,000.00	550.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			4,422.00	1,722.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >