

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/GRB22006763/GPA3Q2**Date:** 18/06/2023**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447\_01  
**Claimant Vehicle No :** SHD8646T **Insured Vehicle No :** SLK4382X  
 Date of Loss: 13/07/2022 Nature of Claim: TP Claim No: MFL2022D0003662

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SHD8646T**  
 Make & Model: HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A) Engine No: G4LEKU388832  
 Reg. Date: 19/12/2019 (Man. Year: 2019) Chassis No: KMHC851CVLU183998  
 Colour: Yellow Odometer: 0 km  
 Engine Capacity: 1580 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

**CONDITION OF TYRES**

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15  
 Front Left Side: West Lake 6 mm Rear Left Side: West Lake 6 mm  
 Front Right Side: West Lake 6 mm Rear Right Side: West Lake 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,212.76	967.24	4,245.52	81.44
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	2,300.00	1,510.00	790.00	34.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>7,523.76</b>	<b>2,488.24</b>	<b>5,035.52</b>	<b>66.93</b>
<b>+ GST 7.00/7.00% (S\$)</b>	526.66	174.18	352.48	66.93
<b>Nett Amount (S\$)</b>	<b>8,050.42</b>	<b>2,662.42</b>	<b>5,388.00</b>	<b>66.93</b>
<b>+ Loss of Use (6.0 x S\$40.00/day) (S\$)</b>		240.00		
<b>+ Car Rental (6.0 x S\$125.19/day) (S\$)</b>		751.14		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>3,661.01</b>		
<b>Global Sum Settlement (S\$)</b>		<b>3,660.00</b>		

**INSPECTION**

Date of Assignment: 15/07/2022 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)  
 Date Inspected: 15/07/2022 Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang)  
 59 Loyang Drive  
 Singapore 508969  
 Estimated Period of Repair: 5.0 days

**Adjuster:** XING GUO QIANG**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Oct 2022)
Parts:	143	HYUNDAI AE IONIQ HEV FL 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD8646T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Torn	459.40 FL	*459.40 FL
2	1		*REAR BUMPER BRACKET LH	Not Necessary	55.80 FL	*- FL
3	1		*REAR FENDER LH	Repair	1,768.30 FL	*- FL
4	1		*REAR FENDER SHIELD LH	Not Necessary	173.60 FL	*- FL
5	1		*REAR DOOR PANEL LH	Repair	2,147.90 FL	*- FL
6	1		*REAR WHEEL COVER LH	Scratched	346.40 FL	*346.40 FL
7	1		*REAR LH LOWER ARM	Not Necessary	239.50 FL	*- FL
8	1		*REAR LH UPPER ARM	Not Necessary	147.30 FL	*- FL
9	1		*REAR LH SHOCK ABSORBER	Not Necessary	230.50 FL	*- FL
10	1		*REAR LH HUB WHEEL BEARING LH	Not Necessary	544.00 FL	*- FL
11	1		*REAR DOOR COMFORT APP	Necessary	80.00 FS	*80.00 FS
12	1		*REAR FENDER PETROL STICKER	Necessary	25.00 FS	*25.00 FS
13	1		*REAR FENDER ADVERTISEMENT	Necessary	100.00 FS	*100.00 FS
14	1		*REAR DDOR ADVERTISEMENT	Necessary	100.00 FS	*100.00 FS
15	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
					Sub Total (\$\$)	6,439.70 1,132.80
					- List Item Discount on L Items 20.00/20.00% (\$\$)	1,226.94 165.56
					Total Parts (\$\$)	5,212.76 967.24

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,050.00	700.00
2	SPRAY PAINTING	New	800.00	750.00
3	REMOVE/REFXI REAR UPHOLSTERY	New	90.00	0.00
4	REMOVE/REFIX DOOR PARTS	New	90.00	0.00
5	REMOVE/REFXI REAR SUSPENSION	New	90.00	0.00
6	RESET WHEEL ALIGNMENT	New	90.00	60.00
7	TUFF CAOTING	New	90.00	0.00
Gross Labour Cost (\$\$)			2,300.00	1,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >